## THIS IS NOT A BOUNDARY SURVEY

This copyrighted document expires 08-17-16. Reproduction and/or dissemination after this date is unauthorized.

MORTGAGE INSPECTION OF: DEED BOOK \_\_\_\_\_ PAGE \_\_\_\_ COUNTY \_Cumberland \_\_\_\_\_ PAGE \_\_\_\_ LOT \_\_\_\_

ADDRESS: 24 Salem Street, Portland, Maine

Buyer: Betsy Morrell


Sellers: Mari M. Jones & Robert P. Wolterstorff

Job Number: 888-55

Inspection Date: 05-17-16

Scale: \_\_1" = 20'

Client File #: \_ 742.175



HEREBY CERTIFY TO:

Edgar S. Catlin, III, Bath Savings Institution and its title insurer.

Monuments found did not conflict with the deed description.

The dwelling setbacks do not violate town zoning requirements.

As delineated on the Federal Emergency Management Agency Community

Panel 230051 0013B:

The structure does not fall within the special flood hazard zone.

The land does not fall within the special flood hazard zone.

A wetlands study has not been performed.

APPARENT EASEMENTS AND RIGHTS OF WAY ARE SHOWN, OTHER ENCUMBRANCES, RECORDED OR NOT, MAY EXIST. THIS SKETCH WILL NOT REVEAL ABUTTING DEED CONFLICTS, IF ANY.

## Livingston-Hughes

Professional Land Surveyors 88 Guinea Road Kennebunkport, Maine 04046

207-967-9761 phone

207-967-4831 fax

www.livingstonhughes.com