



Permitting and Inspections Department
Approved with Conditions
07/30/2018

studio









07/30/2018


(3) EXIST. FLIES. ABOVE go here. VI 2 HR, RATED ASSEMBLY EXIST. BASEMENT REMOVATEDWI (Z) APT. UHITS ADDED

Love lab Studio sign permit BUILDING SECTION

A3 = section/fucade



## X-BR-SSSB-36-SQ



1.25" Square steel tubing construction

steel hanging tracket

Love Lab Studio Sign Permit



Permitting and Inspections Department Approved with Conditions 07/30/2018

sign gues heve

As = facade image

Love Lab Studio Sign Permit