



ment Window Replacement List, April 2015

Approved for Historic Preservation
Certificate of Appropriateness

06/04/15

Date: _____

	Item	Marvin Quote Item (15 Jan 2015)	Rough Opening	Picture of Existing Unit to be Replaced
A	Marvin Clad Magnum Inswing Tilt-Turn	1	37" x 31 ¾"	DSCN1650.jpg
B	Marvin Clad Magnum Inswing Tilt-Turn	1	37" x 31 ¾"	DSCN1651.jpg
C	Marvin Integrity Wood/ Ultrex Awning	2	37" x 31 ¾"	DSCN1652.jpg
D	Marvin Integrity Wood/ Ultrex Awning	2	37" x 31 ¾"	DSCN1653.jpg
E	Marvin Integrity Wood/ Ultrex Awning	3	37" x 20 ½"	DSCN1654.jpg
F	Marvin Integrity Wood/ Ultrex Awning - Fixed	3	37" x 20 ½"	DSCN1649.jpg
G	Marvin Integrity Wood/ Ultrex Awning - Fixed	3	37" x 20 ½"	DSCN1648.jpg
H	Marvin Integrity Wood/ Ultrex Awning	3	37" x 20 ½"	DSCN1647.jpg

ADDITIONAL PICTURES

Unit	Item	Picture	Notes
	View from Spring Street to SW side of house	DSCN1660.jpg	View from West
	View from Spring street near Apartment building, North side	DSCN1661.jpg	View from North
D	View of similar Marvin awning with Unit D nearby	DSCN1662.jpg	This is on porch addition on SW side of house