

330 Danforth Street

BRAMHALL



#8303-1R

March 20, 1969

Mr. Louis S. Peverade
336 Danforth Street
Portland, Maine 04102

Re: 336 Danforth Street


Dear

Your property has been surveyed by the Portland Housing Division and has met Minimum Code Standards. Congratulations are extended to you for the general condition of your property. Many people in the area are making improvements in their property even though they meet the requirements of ordinance relating to housing conditions. Good maintenance is the best way to preserve the useful life of your property and neighborhood.

Many services are available through the site office for further improvements to your property. Should you want advice on landscaping, structural changes, plans, and financing, please call 773-1773.

If we can be of further help, please feel free to call on us. Thank you for your interest in the program and your cooperation in making Bramhall Hill a more beautiful residential area.

Sincerely,



Lyle D. Noyes
Housing Supervisor

GLS:clb

Inspector Bo. Bailey

Date 3/20/69

Proj. No.

BRAMBALL

DWELLING UNIT SCHEDULE

CROWDING	LOCATION	336 DANFORTH ST	COMP.
SANIT.	D.U. LOC.	1 ST FL.	PERM.
INFEST.	OCCUPY	LEWIS F. PAVARADA	
BASE D.U.	OWNER		
	AGENCY		
DET'N	ADDRESS		YTS

[illegible]

	KITCHEN	BATH	POOR TOILET	DINING	Lv 000	000	1 BED	2 BED	3 BED	OTH	TOTAL
OVERCROWDING 65' - 7'	✓	✓	✓	✓	✓	✓	✓	✓	✓		
50 SLEEP'G	✓	✓	✓	✓	✓	✓	✓	✓	✓		
VENTILATION 1/12 P 1/2	✓	✓	✓	✓	✓	✓	✓	✓	✓		
LIGHTING WIRING	✓	✓	✓	✓	✓	✓	✓	✓	✓		
DET-RN WALLS	✓	✓	✓	✓	✓	✓	✓	✓	✓		
CEILINGS	✓	✓	✓	✓	✓	✓	✓	✓	✓		
WINDOWS	✓	✓	✓	✓	✓	✓	✓	✓	✓		
FLOORS	✓	✓	✓	✓	✓	✓	✓	✓	✓		
FLOORS	✓	✓	✓	✓	✓	✓	✓	✓	✓		

KITCHEN SINK & WATER

☒ SINK

☒ SUPPLY & WASTE

☒ FLOOR, SINK

HEATING

☒ STACPS, FLUES, VENTS

☒ HT'GS VENTED, REP'R

BATHING FACILITIES

☒ SHARED MAX. 414

☒ LONG U. I PER 15

Remarks

Portland
Health Dept.
CS-7

Inspector

Best Beauty

Date 3/20/68

Bramhall

DWELLING UNIT SCHEDULE

CODING	LOCATION	336 DANFORTH ST	CORP.
SAME	D.U. LOC.	27 AM - 1 ST FLV.	PERD.
INVEST.	OCCUPY	Gerold Poviter	
BASE D.U.	OWNER		
OWNER	AGENT		
OWNER	ADDRESS		VTS

Occupants

Information

Occupancy

Appendix

Violations

[illegible]

	KITCHEN	BATH	TOILET	L.V./R.M. W.C.	1 BED	2. BED	3. BED	BED	B'U	OTHER	TOTAL
OVERCROWDING 65' - 7'	✓	✓		✓	✓	✓	✓				
50 SLEEP'RS	✗	✗	✗	✓	✓	✓	✓				
VENTILATION 1/2 x 1/2	✓	✓		✓	✓	✓	✓				
LIGHTING WIRING	✓	✓		✓	✓	✓	✓				
DET'N FALLS	✓	✓		✓	✓	✓	✓				
CE. LINES	✓	✓		✓	✓	✓	✓				
WINDOWS	✓	✓		✓	✓	✓	✓				
LOH IS	✓	✓		✓	✓	✓	✓				
FLOORS	✓	✓		✓	✓	✓	✓				

✓ MEN'S SINK & WATER

✓ SINK

✓ SUPPLY & WASTE

✓ PLUGS, GEN'L

HEATING

✓ STICKS, FLUES, VENTS

✓ HT'GS VERTED, REP'G

BATHING FACILITIES

✓ SHARED MAX. 400

✓ 140 U. 1 PER 15

Remarks

Portland
Health Dept.
ES-7

304 Bailey