

NOTES

Permit No. 80/1023
 Location 10-21 Cornell St.
 Owner Morris, Ingala & Morris
 Date of permit 9-15-80
 Approved 12-2-80 ^{12 unit}
 in old school

1-11-80 Just start to site prep
 1-8-80 Most of bldg stripped of
 wall board on 1st and 2nd floors - 2nd
 floor work done
 1-28-81 Sidewalk to driveway worked on
 3-13-81 Structural framing in begun
 done. Stairways is included completed
 on second floor. Metal roof in place on
 1st floor. Electrical work has been
 out for bid yet. Exterior brick work
 is being done by Smehal 9-26-81
 9-26-81 Capt that the expected
 the frame in weather
 It looks like they will be
 working until 11:00.
 10-11-81 Work done on
 total on the 1st. It seems
 to going over slow. The
 11-6-81 Work has been completed
 the windows. Embankment
 is being done on the
 stand some bushes on
 will work in the frame.
 11-25-81 Frame is in
 frame is total. 11/25/81
 Check out OK
 12-27-81 The gas water
 all put up. 12/27/81
 1-6-82 Gas has been
 work done on
 new door blind. 1/6/82
 plumbing has been
 installed. Installation
 being done on 1st floor.
 2-15-82 Plumbing has
 been done. 2/15/82
 Cap being work in
 done.
 12-8-82 1 unit is finished
 from model. 3 more are near
 being finished.

1-11-80 Just start to site prep
 1-8-80 Most of bldg stripped of
 wall board on 1st and 2nd floors - 2nd
 floor work done
 1-28-81 Sidewalk to driveway worked on
 3-13-81 Structural framing in begun
 done. Stairways is included completed
 on second floor. Metal roof in place on
 1st floor. Electrical work has been
 out for bid yet. Exterior brick work
 is being done by Smehal 9-26-81
 9-26-81 Capt that the expected
 the frame in weather
 It looks like they will be
 working until 11:00.
 10-11-81 Work done on
 total on the 1st. It seems
 to going over slow. The
 11-6-81 Work has been completed
 the windows. Embankment
 is being done on the
 stand some bushes on
 will work in the frame.
 11-25-81 Frame is in
 frame is total. 11/25/81
 Check out OK
 12-27-81 The gas water
 all put up. 12/27/81
 1-6-82 Gas has been
 work done on
 new door blind. 1/6/82
 plumbing has been
 installed. Installation
 being done on 1st floor.
 2-15-82 Plumbing has
 been done. 2/15/82
 Cap being work in
 done.
 12-8-82 1 unit is finished
 from model. 3 more are near
 being finished.