
CITY OF PORTLAND
DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street
Portland, Maine 04101

Inspection Violations

Owner/Manager KORTHY GABOR &		Inspector Suzanne Hunt	Inspection Date 1/6/2009
Location 247 VALLEY ST	CBL 064 E003001	Status Re-Inspect 5 Days	Inspection Type Complaint-TACI

Code	Int/Ext	Floor	Unit No.	Area	Compliance Date
1) 22-3 (a)	Exterior				
Violation:	Rodent Harborage				
Notes:	remove mattress from side of building				
2) 6-109.d	Exterior				
Violation:	Disposal of rubbish, ashes, garbage and waste				
Notes:	Covered Trash cans are required for all trash stored outside.				
Comments:	mattress on side of building must be removed. Trash bags must be kept in covered trash containers.				