Portland, Maine



Yes. Life's good here.

Planning & Urban Development Department

Director of Planning and Urban Development Jeff Levine

> Inspection Services, Director Tammy M. Munson

June 11, 2015

SEA OTTER 16G LIMITED 39 COVESIDE LN YARMOUTH, ME 04096

CBL: 064 E019001

Located at: 16 GILMAN ST

Certified Mail 7010 1870 0002 8136 8053

To whom it may concern:

An evaluation of the above-referenced property on 06/10/2015 shows that the structure fails to comply with Chapter 6.Article V. of the Code of Ordinances of the City of Portland, The Housing Code. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within 30 days of the date of this notice. A re-inspection of the premises will occur on 07/13/2015 at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code.

This constitutes an appealable decision pursuant to Section 6-127 of the Code.

Please feel free to contact me if you wish to discuss the matter or have any questions.

Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection.

Sincerely,

Chuck Fagone

Code Enforcement Officer

(207) 874-8789

CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager SEA OTTER 16G LIMITED		Inspector	Inspection Date
		Chuck Fagone	6/10/2015
Location	CBL	Status	Inspection Type
16 GILMAN ST	064 E019001	Failed	Complaint-Inspection

Code 1) 6-116. (c) Int/Ext

Floor

Unit No. Area

Compliance Date

Interior

Stairways

Violation:

EGRESS OBSTRUCTIONS

Every hallway, stairway, corridor, exit, fire escape door or other means of egress shall be kept clear

of obstructions at all times.

Notes:

The rear stairwell was blocked with bags of returnables, television set and other items. All means of

egress should remain clear at all times. Please communicate this to the tenants.

2) 6-116. (e)

Interior

Basement/rear stairway

Violation:

FIRE PROTECTION

Every dwelling, dwelling unit, rooming house and rooming unit shall comply with the applicable provisions of the most current edition of the National Fire Protection Association Life Safety Code, and with all other applicable state statutes and regulations.

Notes:

The rear stairwell needs to be completely finished to include trim work around windows. Smoke detector in the rear stairwell was missing, but was replaced by maintenance, a sprinkler head needs to be installed over the gas fired systems.

CERTIFIED MATL.

Portland, Maine



Yes. Life's

Planning & Urban Developmer Inspection Division

389 Congress Street, Room 31 Portland, Maine 04101-3509



7010 1870 0002 8136 8053



1000



04096

U.S. POSTAGE PAID PORTLAND,ME 04101 JUN 12, 15 AMOUNT \$6.74

00100439-08

PUSIVIE

Sea Otter 16G Limited
39 Coveside Lane
Yarmouth, Maina 04.006 NATION

E 6/20

NIXIE

015 DE 1009

0007/23/15

RETURN TO SENDER UNCLAIMED UNABLE TO FORWARD

C444444566F0

04101356699 *3084-01481-12-41

