CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

November 8, 2017

Responsible Party 1:				
INN AT ST JOHN THE				
939 CONGRESS ST				
PORTLAND, ME 04102				
Location	CBL	Inspection Date		
Location 939 CONGRESS ST	CBL 065 C001001	Inspection Date 10/12/2017		
		=		

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 11/30/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 101-7.9.3 EMERGENCY LIGHTS REQUIRE MAINTENANCE; 7.9.3 Periodic Testing of Emergency Equipment 7.9.3.1 Required emergency lighting systems shall be tested in accordance with one of the three options offered by 7.9.3.1.1, 7.9.3.1.2, or 7.9.3.1.3. 7.9.3.1.1 Testing of required emergency lighting systems shall be permitted to be conducted as follows: (1) Functional testing shall be conducted monthly with a minimum of 3 weeks and a maximum of 5 weeks between tests, for not less than 30 seconds, except as otherwise permitted by 7.9.3.1.1(2). (2) The test interval shall be permitted to be extended beyond 30 days with the approval of the authority having jurisdiction. (3) Functional testing shall be conducted annually for a minimum 1-1/2 hours if the emergency lighting system is battery powered. (4) The emergency lighting equipment shall be fully operational for the duration of the test required by 7.9.3.1.1(1) and (3). (5) Written records of visual inspections and tests shall be kept by the owner for inspection by the authority having jurisdiction. High side C	
NFPA 101- 7.2.8.6.2 FIRE ESCAPE REQUIRES REPAIR; The authority having jurisdiction shall be permitted to approve any existing fire escape stair that has been shown by load test or other satisfactory evidence to have adequate strength. floor 2 bolt dislodged from building rear exterior	//
NFPA 13 SPRINKLER SYSTEM INSPECTION TAG; NFPA 13 covers the annual maintenance, inspection, and record keeping requirements for sprinkler system inspection tags. needs annual inspection	//

Violation		Proposed Date of Completion
wiring installations shall be provide only to temporary wiring installatio	RDS; Ground-fault protection for personnel for all temporary ed to comply with 590.6(A) and (B). This section shall apply ans used to supply temporary power to equipment used by nodeling, maintenance, repair, or demolition of buildings, ctivities.	//
FINAL DATE OF COMPLETED V	(IOLATION(S)	//
FIRE PREVENTION BUREAU RE	E-INSPECTION OF COMPLETED VIOLATION(S)	//
	o reject or modify any proposed plan of action, and may all capacity to complete the proposed plan. Please contact ON	=
	t listed within the timeframes provided. If I require add the Fire Prevention Bureau <u>prior to the deadline</u> to requ discretion to grant or deny.	
· ·	ny responsibility to schedule a reinspection of my prope Ny failure to schedule a reinspection shall be deemed an ied.	•
	ement, I understand that I am liable for penalties pursu § 1-15 and 10-25, and 30-A M.R.S. § 4452 and may be s	• •
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	