## CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

## **Inspection Violations**

Owner/Manager		Inspector	Inspection Date	
Chasse Randall R		11/10/1999		
Locatation	CBL	Status	Inspection Type	
75 Roberts St	066A B010001	Green 0-4 Violations	Housing-Housing Inspection	

	Code	Int/Ext	Floor	Unit No.	Area	Compliance Date	
1)	6-108.5	Exterior			Roof		
	Violation:						
	Notes:	All four (4) chimneys are in need of being	rebuilt or rep	ointed. Brick	s are fallir	ng from right rear.	
2)	6-108.3 Exterior		Throughout				
	Violation:						
	Notes:	lotes: There are several broken windows around the house.					

**Comments:**