CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date
CORBIN JEFFREY P		Tom Markley	3/11/2005
Locatation	CBL	Status	Inspection Type
81 GRANITE ST	066A B019001	Re-Inspect 10 Days	Complaint-Electrical Only

	Code	Int/Ext	Floor	Unit No.	Area	Compliance Date		
1)	6-116.5	Interior			Various locations			
	Violation:	Fire Protection						
	Notes:	Smoke detectors inoperable or not hard-wired battery back-up						
2)	6-113.5	Interior Various locations		ocations				
	Violation:	Maintenance of lighting fixtures						
	Notes:	Various outlets wired incorrectly						
3)	6-108.1	Interior			Basemen	t		
	Violation:	Foundations cellars, exterior walls, roofs						
	Notes:	Excessive Junk / trash in basement must be removed and basement cleared (30 days)						
Comments: An Electrician must be contacted immediately; Violations for Smoke detectors and Outlets must be						and Outlets must be		

nents: An Electrician must be contacted immediately; Violations for Smoke detectors and Outlets must be corrected within 7 days

Excessive Junk / trash

in basement must be removed and basement cleaned within 30 days