

CITY OF PORTLAND
DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street
Portland, Maine 04101

Inspection Violations

Owner/Manager DEXTER ANNE MAYRE		Inspector Tammy Munson	Inspection Date 7/21/2006
Location 8 DEANE ST	CBL 066A C005001	Status Re-Inspect 30 Days	Inspection Type Complaint-Inspection

Code	Int/Ext	Floor	Unit No.	Area	Compliance Date
1) 6-108.1	Exterior			Various locations	
Violation:	Foundations cellars, exterior walls, roofs				
Notes:	Exterior walls structurally unsafe				
2) 6-108.1	Exterior			Various locations	
Violation:	Foundations cellars, exterior walls, roofs				
Notes:	Exterior roof structurally unsafe				
3) 6-108.3	Exterior			Various locations	
Violation:	Exterior windows, doors and skylights				
Notes:	Exterior windows structurally unsafe				
4) 6-108.3	Exterior			Various locations	
Violation:	Exterior windows, doors and skylights				
Notes:	Exterior doors structurally unsafe				
5) 6-109.5	Exterior			Various locations	
Violation:	Rodent and vermin control.				
Notes:	Rodent and Vermin harborage				
Comments:	Building is severely dilapidated and in structural disrepair. This building must be repaired or demolished within 30 Days. A permit will be required for either option				