

**CITY OF PORTLAND**  
**DEPARTMENT OF PLANNING & URBAN DEVELOPMENT**  
 389 Congress Street  
 Portland, Maine 04101

**Inspection Violations**

<b>Owner/Manager</b> EL NOUR MALIK		<b>Inspector</b> Suzanne Hunt	<b>Inspection Date</b> 10/3/2006
<b>Location</b> 165 ST JOHN ST	<b>CBL</b> 068 B006001	<b>Status</b> Re-Inspect 10 Days	<b>Inspection Type</b> Complaint-Inspection

<b>Code</b>	<b>Int/Ext</b>	<b>Floor</b>	<b>Unit No.</b>	<b>Area</b>	<b>Compliance Date</b>
1) 12-79	Exterior				
<b>Violation:</b> Junk Vehicles					
<b>Notes:</b> one unregistered back saturn car in side yard					
2) 6-111.3	Interior		all	Various locations	
<b>Violation:</b> Water supply.					
<b>Notes:</b> no water supply					
3) 6-109.5	Exterior				
<b>Violation:</b> Rodent and vermin control.					
<b>Notes:</b> 4 mattresses, garbage bags, clothing and various thrown away objects in side and back yard.					
4) 6-109.5	Exterior				
<b>Violation:</b> Rodent and vermin control.					
<b>Notes:</b> building is not secure, front door is not locked, windows are open.					
5) 6-108.1	Exterior				
<b>Violation:</b> Foundations cellars, exterior walls, roofs					
<b>Notes:</b> siding has fallen off the back exterior wall of building					
6) 6-108.1	Exterior			Entry Way	
<b>Violation:</b> Foundations cellars, exterior walls, roofs					
<b>Notes:</b> banister on entrance way porch is broken					

**Comments:**