CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

November 3, 2016

Responsible Party 1:			
Newman Thomas			
208 PINE ST			
PORTLAND, ME 04102			
Location	CBL	Inspection Date	
208 PINE ST	069 B001001	10/14/2016	
Inspector	Inspection Type	Status	
Scott True	FP Routine Inspection	Failed	

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must complete the proposed date of completion column by proposing a reasonable timeframe to remedy each violation. This form must be received by the Fire Prevention Bureau no later than 11/30/2016. The Bureau reserves the right to reject or modify any proposed plan of action, and may require evidence of sufficient financial and technical capacity to complete the proposed plan. Please contact the Bureau with any questions.

YOUR FAILURE TO SUBMIT A PLAN OF ACTION BY THE DATE PROVIDED, OR TO CORRECT ANY VIOLATION WITHIN THE APPLICABLE TIME FRAME, MAY RESULT IN LEGAL ACTION AGAINST YOU, THE IMPOSITION OF CIVIL PENALTIES, AND THE PURSUIT OF OTHER LEGAL REMEDIES.

Violation	Proposed Date of Completion
NFPA 101- 31.3.2.1.1 BOILER PROTECTION REQUIRED; The areas described in Table 31.3.2.1.1 shall be protected as indicated: Boiler and fuel-fired heater rooms serving more than a single dwelling unit (minimum separation/protection is 1 hour or sprinklers) May be one under a red plastic cover. Did not want to remove cover. Owner will verify with heat Co., if missing then installation required.	* was already
NFPA 101- 8.3.4.2 60 MINUTE FIRE DOOR REQUIRED; Refer to NFPA 101- Table 8.3.4.2 that states fire door assemblies for vertical shafts (including stairways, exits, and refuse chutes) are rated and required for 1 hour. The two apartments front and rear	01/31/17 **

* Henting company (Pine Stafe Services) confirmed & prinkled in boiler voon. See e-wail with picture addacted.

** One of the apartners (200 flow) will be eliminated when lease expires than 31 and the rooms will be take back that the primary residues.

Therefore propere five rated doors front rear for the remains 3rd flow apartners only.

VIOLATOR CERTIFICATION

I agree to remedy the violations listed within the timeframes provided. If I require additional time to comply, I understand that I must contact the Fire Prevention Bureau <u>prior to the deadline</u> to request an extension, which is entirely within the Bureau's discretion to grant or deny.

I further understand that it is my responsibility to schedule a reinspection of my property once the violations have been remedied to do so. My failure to schedule a reinspection shall be deemed an admission that the violations have not been remedied.

1 0	ent, I understand that I am liable for penalties pursuant to the City of
Portland Code of Ordinances §§ 1-1	15 and 10-25, and 30-A M.R.S. § 4452 and may be subject to further legal
11/29/2016	Domonsible Porty
Date !	Responsible Party THOMAS C. NEWMAN
Date	Responsible Party
SEEN AND AGREED	
Date	Fire Prevention Bureau

Newman, Thomas

From:

Lee Nicely <lee@pinestateservices.com>

Sent:


Monday, November 28, 2016 12:53 PM

To:

Newman, Thomas

Subject:

RE: Good morning from Pine State Services



Sent from my Verizon, Samsung Galaxy smartphone

----- Original message -----

From: "Newman, Thomas" <tnewman@verrilldana.com>

Date: 11/28/16 12:09 PM (GMT-05:00)

To: Lee Nicely <lee@pinestateservices.com>

Subject: RE: Good morning from Pine State Services

Hi Lee,

I have to submit proof of the sprinkler head to City of Portland today (due by 11/30). Can you please send me an e-mail with the pictures you promised (below) and confirming yes, our new system has a sprinkler in the boiler room. Thanks,

Tom

Thomas C. Newman, Partner