Inspections Division
Date: 02/14/18

1. B/B revised EAST exterior section at kitchen/basement

ITEM 2

SEE Section A_A support walls S-1.0

2. Section at kitchen/basement Lally Col

12_13_17

40 Bowdoin Street

Structural details

3/4"=1'-0"

S-1.3

SECTION DETAILS