Quality Assurance Labs Inc.

NON-DESTRUCTIVE TESTING AND INSPECTION SERVICES

80 PLEASANT AVENUE • SOUTH PORTLAND, MAINE 04108 • TEL: (207) 799-8911 • FAX: (207) 799-7251

INSPECTION REPORT S.W. COLE ENG. PAGE OF CUSTOMER: GRAY, ME ADDRESS: ROGER DOMINGO ATTENTION: COPIES: MERCY @ FORE RIVER PROJECT: MERCY HOSPITAL OWNER: CONTRACTOR: GILBANE REPORTNO :: QAL-08-0935 JOB No.: 06-1069.1 P. O. NUMBER: DATES INSPECTED: 05 - 16 - 08 REMARKS >>> FINAL RE-INSPECTION OF FIELD MODIFICATIONS AT GRID LINE H-2. > PER SITE DRAWINGS SK-502A AND SK-2-26, ALL RE-WORK DUE TO PREVIOUS REJECTS. ARE NOW COMPLETE. ALL COMPLETED WELDING COMPLIES WITH DRAWINGS AND AWS D1 1 REQUIREMENTS FOR VISUAL ACCEPTANCE. END ITEMS /// **FAA REPAIR STATION NUMBER RX5R187N** METHOD(S), PROCESS(ES), PROCEDURE(S) MERCURY FREE ADDITIONAL INFORMATION - SEE ATTACHED: SKETCH(ES) SUPPLEMENTARY SHEET(S) NOT REPORTS VIDEO CERTIFICATION DATE SIGNATURES INSPECTOR MICHAEL DREW CWI # 99050211 05 | 16 | 08 SUPERVISOR