

Quality Assurance Labs Inc.

NON-DESTRUCTIVE TESTING AND INSPECTION SERVICES

80 PLEASANT AVENUE • SOUTH PORTLAND, MAINE 04106 • TEL: (207) 799-8911 • FAX: (207) 799-7251

INSPECTION REPORT

CUSTOMER: S.W. COLE ENG.	PAGE 1 OF 1
ADDRESS: GRAY, ME.	
ATTENTION: ROGER DOMINGO	
COPIES:	
PROJECT: MERCY AT FORE RIVER	
OWNER: MERCY HOSPITAL	
CONTRACTOR: GILBANE	

JOB No.: 06-1069.1	REPORT No.: QAL-07-0749	P. O. NUMBER:	DATES INSPECTED: 04-25-07
--------------------	-------------------------	---------------	---------------------------

REMARKS

VISUAL INSPECTION OF STRUCTURAL STEEL CONNECTIONS : GRID LINES 1 - 5 , A - H .

- > 1st LEVEL COLUMN TO COLUMN SPLICE CONNECTIONS COMPLETE . ALL FIELD WELDS COMPLY WITH AWS D1.1 FOR VISUAL ACCEPTANCE .
- > 3rd LEVEL COLUMN TO COLUMN SPLICE CONNECTIONS REVEAL (6) LOCATIONS MARKED FOR UN-ACCEPTABLE CONDITIONS . IE: EXCESS WELD REINFORCEMENT , UNDERFILL , AND ARC STRIKES .

END ITEMS ///

FAA REPAIR STATION NUMBER RX5R187N
 METHOD(S),PROCESS(ES),PROCEDURE(S) MERCURY FREE

ADDITIONAL INFORMATION - SEE ATTACHED: SKETCH(ES) SUPPLEMENTARY SHEET(S) NDT REPORTS VIDEO

SIGNATURES

CERTIFICATION	DATE		
	LEV.	M	D Y
CWI		04	25 07

INSPECTOR MICHAEL DREW CWI# 99050211

SUPERVISOR