Quality Assurance Labs Inc.

-No. 9101---P. 1

CERTIFICATION

10 | 09 | 07

(FORM Q703 REV 0)

NON-DESTRUCTIVE TESTING AND INSPECTION SERVICES 60 PLEASANT AVENUE . SOUTH PORTLAND, MAINE 04106 . TEL: (207) 799-8911 . FAX: (207) 799-7251 INSPECTION REPORT ì OF PAGE S. W. COLE ENG. CUSTOMER: GRAY, ME. ADDRESS: ROGER DOMINGO ATTENTION: COPIES: MERCY AT FORE RIVER PROJECT: **MERCY** OWNER: GILBANE CONTRACTOR: 10 - 09 - 07 DATES INSPECTED: REPORT No.: QAL-07-1926 P. O. NUMBER: JOB No.: 06-1069.1 REMARKS FINAL VISUAL INSPECTION OF FIELD WELDING RE-WORK PER SKS-64 DWG. FOR 3X3X 1/2 ANGLE TO LOWER BEAM CONNECTIONS AT LINES 3 & F. > REF . PREVIOUS FIELD REPORT DATED 09 - 26 - 07 : A) LINE (F) SHOWS ALL REWORK OF SPLICE AND STIFFNER CONNECTIONS COMPLETE. B) LINE (3) SHOWS ALL REWORK OF SPLICE AND STIFFNER CONNECTIONS COMPLETE. COMPLETED WORK COMPLIES WITH ENGINEERING AND AWS DILL REQUIREMENTS FOR VISUAL ACCEPTANCE. END ITEMS /// FAA REPAIR STATION NUMBER RX5R187N METHOD(S),PROCESS(ES),PROCEDURE(S) MERCURY FREE NOT REPORTS VIDEO SUPPLEMENTARY SHEET(S) SKETCH(E9) ADDITIONAL INFORMATION - SEE ATTACHED:

SIGNATURES

MICHAEL DREW CWI # 99050211 Muche

INSPECTOR SUPERVISOR