

1924 Portland Tax Records: 56 Douglass Street, Portland, Portland, ME

Portland, Maine
 Assessment 19
 Name Thompson
 Owner Boyle Elaine Maude
 Street Douglass No. 56
 Block 780 Lot 25
 Use of Bldg. Residence Name
 Tenants and Rooms
 Rentals
 Age
 Condition of Repair

Class	Exterior	Plumbing
Bungalow	Clapboards	Common
Single House	Siding	Individual
Two family	Shingles	Open
Three family	Stucco	Set tubs
Apartment	Paper	Finish
Store Building	Tapestry Brick	Plain
Office	Com. Brick	Hardwood
Factory	Galv. Iron	Halls
Storage	Stone	Wood
Stables	Terra Cotta	Terrazzo
Garage, private	Concrete	Marble
Garage, public		Roof - Roofing
Theatre	Heating	Shingle
Club House	Stove	Slate
Cottage	Furnace	Gravel
	Hot Water	Prepared
Foundation	Steam	Asbestos
Brick	Light	Flat
Stone	Oil	Hip
Concrete	Gas	Gable
Pile	Electric	Dormers
Basement		Windows
Full	Floor	Plain Glass
Cement Floor	Common	Wire Glass
Waterproof	Hardwood	Shutters
Construction	Re-Concrete	Miscellaneous
Frame	Concrete Slab	Elevator
Brick	Waterproof	Sprinkler
Tile		Fire Escape
Block	Ceiling	Refrigerator
Stone	Plaster	Vacuum Cleaner
Re-Concrete	Metal	Safes and Vaults
Mill	Panelled	Telephone Equip.
Steel Frame	Rough	

Ground Area 1161 Height 23
 Cubic Feet 26,694 Unit 1161
 Utility Dep. 85 Per cent.
 Dep. 85 Sound Value, \$ 3604

Land 3136 Corner Interior Alley
 Front Depth ft.
 COMPUTATION

Area	Multiplier	Coefficient	
7196	100	3136	
Year	Unit	Coefficient	Land Value
19	708	3136	42514



Surveyed by
 (Remarks on other Side)
 124 - 1145/70 - 5500+
 124 - 1149/495 - 6380+

Remarks about Buildings
Thompson 1923

Remarks about Land
 Shutter
 640
 121
 20.5
 21.2

DOUGLASS ST

Remarks about Personal Property

CITY OF PORTLAND, MAINE
 ASSESSORS DEPARTMENT

CHART	BLOCK
3	Building Volumes Checked
4	Building Values Placed
5	Building Values Extended
6	Land City Questionnaire Made
7	Land Values Placed
8	Land Values Extended
9	or parcel with 1923
10	Personal Property Added