

6/27/03 AM Set backs cannot be determined  
without finding the corner pins. Allow  
6/24 pm - second inspection: Pins located. OK  
to place footings. AR

7/15/03 Clerk in - elec/plumb framing on sun porch  
OK to insulate gutter (none)

10/14/03 Final inspection - all outlets ok  
no problems seen. OK to close permit.

Permit # 03-0519

CBL # 80-H-5