

197-199 Dartmouth Street

32-A-12



August 17, 1977 ✓

Alice & Rose Slosberg
195 Dartmouth Street
Portland, Maine 04103

Dear Alice & Rose Slosberg: Re: NCP-Oakdale Neighborhood Conservation Program
197-199 Dartmouth Street, Portland, Maine 82-A-12

The Housing Inspections Division of the Department of Neighborhood Conservation has recently completed an exterior inspection of your property in conjunction with the above referred program.

Congratulations are extended to you for the general conditions of your property which was found to meet the standards established by the City's Housing Code. We did, however, note the following items that could cause future problems.

LEFT MIDDLE FOUNDATION - loose mortar.

FRONT TRIM- peeling paint.

Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.

Sincerely yours,
Joseph E. Gray, Jr., Director
Neighborhood Conservation

By Lyle D. Noyes
Lyle D. Noyes,
Chief of Housing Inspections

Inspector H. Bartlett
G. Bartlett

VW

Ok-15-d

STRUCTURE INSPECTION SCHEDULE

1) 1st Name EATLETT

[illegible]

