## CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

## **Inspection Violations**

Owner/Manager		Inspector	Inspection Date
STIMSON MARY T		Suzanne Hunt	8/12/2010
Locatation	CBL	Status	Inspection Type
79 ISLAND AVE	084 1008001	Re-Inspect 14 Days	Building Permit-Inspection

	Code	Int/Ext	Floor	Unit No.	Area	Compliance Date
1)	110.26 (b)	Exterior			BackYard	
	Violation:	EC 2005/NFPA 70				
	Notes:	The overhead service Electric service is not secured to the building per code. A licens must repair the connection.				

Comments: Drive by revealed service line inproperly connected to house. Line is not secure to home and a rope

is acting as attachment. Took photo. Caled CMP