



## INSPECTION WORKSHEET (BLDG-002479-2018) FOR CITY OF PORTLAND

<b>Case Number:</b>	BLDC2018-00089	<b>Case Module:</b>	Permit Management
<b>Inspection Date:</b>	05/29/2018	<b>Inspection Status:</b>	Passed
<b>Inspector:</b>	Duane Hanson	<b>Inspection Type:</b>	Final Inspection
<b>Job Address:</b>	45 Exchange St Portland, ME 04101	<b>Parcel Number:</b>	032 E005001

<b>Contact Type</b>	<b>Company Name</b>	<b>Name</b>
Applicant/Preparer	Peruvian Link	Scott Mitchell
	Peruvian Link	Karina Pomroy
Contractor		Scott Mitchell
		Gilbert Miller
Property Owner	Peruvian Link	Karina Pomroy

<b>Checklist Item</b>	<b>Passed</b>	<b>Comments</b>
General Comments	False	