## CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

## **Inspection Violations**

Owner/Manager		Inspector	Inspection Date
MONTGOMERY GEORGE F II &		Suzanne Hunt	7/15/2010
Locatation	CBL	Status	Inspection Type
150 ISLAND AVE	087 00020001	Re-Inspect 7 Days	Building Permit-Certificate of Occ

Code Int/Ext Floor Unit No. Area Compliance Date

1) 6-120.

**Violation:** Posted against occupancy.

**Notes:** The exterior stairs leading to the beach are posted against occupancy/ use. A barrier must be provided

at both entracnes to staris to prevent use.

2) 6-108.(d)

**Violation:** Stairways, stairwells, stairs and porches.

**Notes:** The exterior stairs to the beach must be removed or brought in a safe condition. Stair construction will

require a permit.

Comments: The exterior stairs leading to beach front are not safe. They are structurally deteriorated and unsafe

to use, they are posted against occupancy/use. Barriers must be constructed immediately to prevent

use. I will check for barriers in 7 days. The stair construction will require a permit.