

SUBSURFACE WASTEWATER DISPOSAL SYSTEM APPLICATION

Department of Health and Human Services
 Division of Environmental Health
 (207) 287-2070 FAX (207) 267-4172

Town, City, Plantation PORTLAND; PEAKS ISLAND	Street, Road Subdivision 30 HIGHLAND AVENUE	Owner's Name AARON & KELLY SCHUIT
ALBERT FRICK ASSOCIATES ARE NOT SURVEYORS PROPERTY INFORMATION APPROXIMATED PER TOWN TAX MAP AND AERIAL PHOTOGRAPH VERIFY PROPERTY LINES TO ASSURE ACCURATE LOCATION PRIOR TO SYSTEM INSTALLATION	SITE PLAN Scale 1" = 100 FT. or as shown	SITE LOCATION PLAN (Attach Map from Maine Atlas Recommended)

EXISTING DWELLING

APPROX. EXISTING WELL

EXISTING 1000 GALLON CONCRETE SEPTIC TANK

EXISTING DISPOSAL AREA

9" DIA FLAGGED OAK

PROPOSED DISPOSAL AREA

(ERP) 8" DIA FLAGGED MAPLE

HIGHLAND AVE

FERRY LANDING

PLEASANT AVE

CENTRAL AVE

SITE #30

IPF

IPF

IPF

IPF

SOIL DESCRIPTION AND CLASSIFICATION (Location of Observation Holes Shown Above)																									
Observation Hole <u>TP A</u> <input checked="" type="checkbox"/> Test Pit <input type="checkbox"/> Boring " Depth of Organic Horizon Above Mineral Soil <u>STRIPPED</u>	Observation Hole <u>TB B</u> <input type="checkbox"/> Test Pit <input checked="" type="checkbox"/> Boring " Depth of Organic Horizon Above Mineral Soil																								
<table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>Texture</th> <th>Consistency</th> <th>Color</th> <th>Mottling</th> </tr> </thead> <tbody> <tr> <td>SANDY</td> <td>FRIABLE</td> <td>YELLOWISH</td> <td></td> </tr> <tr> <td>LOAM</td> <td></td> <td>BROWN</td> <td></td> </tr> <tr> <td colspan="4" style="text-align:center;">BEDROCK</td> </tr> </tbody> </table>	Texture	Consistency	Color	Mottling	SANDY	FRIABLE	YELLOWISH		LOAM		BROWN		BEDROCK				<table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>Texture</th> <th>Consistency</th> <th>Color</th> <th>Mottling</th> </tr> </thead> <tbody> <tr> <td colspan="4" style="text-align:center;">BEDROCK</td> </tr> </tbody> </table>	Texture	Consistency	Color	Mottling	BEDROCK			
Texture	Consistency	Color	Mottling																						
SANDY	FRIABLE	YELLOWISH																							
LOAM		BROWN																							
BEDROCK																									
Texture	Consistency	Color	Mottling																						
BEDROCK																									
<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td>Soil Classification <u>2</u> Profile <u>A</u> Condition</td> <td>Slope <u>0-3%</u></td> <td>Limiting Factor <u>10"</u></td> <td> <input type="checkbox"/> Ground Water <input type="checkbox"/> Restrictive Layer <input checked="" type="checkbox"/> Bedrock <input type="checkbox"/> Pit Depth </td> </tr> </table>	Soil Classification <u>2</u> Profile <u>A</u> Condition	Slope <u>0-3%</u>	Limiting Factor <u>10"</u>	<input type="checkbox"/> Ground Water <input type="checkbox"/> Restrictive Layer <input checked="" type="checkbox"/> Bedrock <input type="checkbox"/> Pit Depth	<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td>Soil Classification</td> <td>Slope</td> <td>Limiting Factor</td> <td> <input type="checkbox"/> Ground Water <input type="checkbox"/> Restrictive Layer <input type="checkbox"/> Bedrock <input type="checkbox"/> Pit Depth </td> </tr> <tr> <td>Profile</td> <td>Condition</td> <td>%</td> <td></td> </tr> </table>	Soil Classification	Slope	Limiting Factor	<input type="checkbox"/> Ground Water <input type="checkbox"/> Restrictive Layer <input type="checkbox"/> Bedrock <input type="checkbox"/> Pit Depth	Profile	Condition	%													
Soil Classification <u>2</u> Profile <u>A</u> Condition	Slope <u>0-3%</u>	Limiting Factor <u>10"</u>	<input type="checkbox"/> Ground Water <input type="checkbox"/> Restrictive Layer <input checked="" type="checkbox"/> Bedrock <input type="checkbox"/> Pit Depth																						
Soil Classification	Slope	Limiting Factor	<input type="checkbox"/> Ground Water <input type="checkbox"/> Restrictive Layer <input type="checkbox"/> Bedrock <input type="checkbox"/> Pit Depth																						
Profile	Condition	%																							

BA
 Site Evaluator Signature

352
 SE

8/24/17
 Date

Page 2 of 3
 HHE-200 Rev. 02/11