

77-79 DEERFIELD ROAD



Full cut # 920R - Half cut # 8702R - Trim cut # 9203R - Full cut # 8203R



FILL IN COMPLETELY AND SIGN WITH INK

PERMIT

Permit No.

JUN 1

APPLICATION FOR PERMIT FOR HEATING, COOKING OR POWER EQUIP.

Portland, Maine, June 14, 1941

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location 79 Deerfield Road Use of Building Dwelling No. Stories New Building
Name and address of owner of appliance Edward J. Berman, 79 Deerfield Road Existing
Installer's name and address Ballard Oil & Equipment Co. of Maine
353 Cumberland Avenue, Portland Telephone 2-1991

General Description of Work

To install Oil Burning Equipment

Steam Heating System

IF HEATER, POWER BOILER OR COOKING DEVICE

Is appliance or source of heat to be in cellar? yes If not, which story Kind of Fuel Oil
Material of supports of appliance (concrete floor or what kind) Concrete
Minimum distance to wood or combustible material, from top of appliance or casing top of furnace,
from top of smoke pipe from front of appliance from sides or back of appliance
Size of chimney flue Other connections to same flue

IF OIL BURNER

Name and type of burner Gilbarco GB00 Labeled and approved by Underwriters' Laboratories? yes
Will operator be always in attendance? Type of oil feed (gravity or pressure) pressure
Location oil storage basement No. and capacity of tanks one 275-gallon
Will all tanks be more than seven feet from any flame? yes How many tanks fireproofed?

Amount of fee enclosed? \$1.00 (\$1.00 for one heater, etc. 50 cents additional for each additional heater, etc. in same building at same time.)

Signature of Installer BY R. H. Buntin
Manager-Oil Burner Division

INSPECTION COPY

Permit No. 41 / 840

Location 79 Deerfield Rd

Owner Edward V. Beerna

Date of Permit 6/16/41

Post Card sent:

Notif. for insp. **INSPECTION NOT COMPLETED**

Approval Tag issued

Oil Burner Check List (date)

1. Kind of heat

2. Label

3. Anti-siphon

4. Oil storage

5. Tank distance

6. Vent Pipe

7. Fill Pipe

8. Gauge

9. Rigidity

10. Feed safety

11. Pipe sizes and material

12. Control valve

13. Ash pit vent

14. Temp. or pressure safety

15. Instruction card

16.

NOTES

Wm. L. G. L. G.

1744. *Heideclausia*

Exploration Time

Side.



GENERAL RESIDENTIAL ZONE

APPLICATION FOR PERMIT

Class of Building or Type of Structure 3rd

6915

Permit No. PERMIT-155

JUN 21 1927

Portland, Maine, June 18 1927

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

This undersigned hereby applies for a permit to erect ~~alter~~ install the following building ~~structure~~ equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 77 Deerfield Rd. Ward 8 Within Fire Limits? no Dist. No. -
Owner's or ~~lessor's~~ name and address George L. King 11 Grassboro Rd. Telephone F 8367 R
Contractor's name and address J. C. French 130 Highland St. Telephone F 9437 J
Architect's name and address _____
Proposed use of building 2 Car Private Garage No. families _____
Other buildings on same lot Dwelling House

Description of Present Building to be Altered

Material _____ No. stories _____ Heat _____ Style of roof _____ Roofing _____
Last use _____ No. families _____

General Description of New Work

Build 2 Car Private Garage

Details of New Work

Size, front 18 depth 19 No. stories 1 Height average grade to highest point of roof 12
To be erected on solid or filled land? solid earth or rock? Earth
Material of foundation Concrete Slab 4" Thickness, top _____ bottom _____
Material of underpinning _____ Height _____
Kind of roof Pitch of chimneys _____
Kind of heat _____ Type of fuel _____ Distance, heater to chimney _____
If oil burner, name and model _____
Capacity and location of oil tanks _____
Is gas fitting involved? no Size of service _____
Corner posts 4x4 Sills 4x4 Girt or ledger board? _____ Size _____
Material columns under girders _____ Size _____ Max. on centers _____
Studs (outside walls and carrying partitions) $\leq$ 1-10" O.C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.
Joists and rafters: 1st floor Concrete, 2nd _____, 3rd _____, roof 2x4
On centers: 1st floor _____, 2nd _____, 3rd _____, roof 2x4
Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot no to be accommodated 2
Total number commercial cars to be accommodated _____ cars habitually stored in the proposed building? no

Miscellaneous

Removal or disturbing of any shade tree on a public street? no
Estimated cost \$500 No. sheets 1
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes Fee \$ 7.5
INSPECTION John P. Laroche Signature of owner


3530H

Ward 8 Permit No. 271915 W
Location 77 Deerfield
Owner George Kerr
Day permit June 24, 1940
Notif. closing-in _____
Insp. closing-in _____
Final notif. _____
Final Insp. 10/12/40 W.H.B.
Cert. of Occupancy issued _____

NOTES


9/6/40 brother's
done mm

SECTION FOR PERMIT



Division of Labor W. 11

Division of Labor W. 11



June 21, 1927

W. C. French,
130 Highland St.,
Portland, Me.

Dear Sir:

Enclosed is the building permit covering the erection of a single family dwelling house for George L. King at 77 Deerfield Road.

It is noted that you propose to use 2 x 8 floor joists on the second floor, 16" on centers and on a span of 15 ft. Unless you propose to use long leaf yellow pine or first grade Douglas Fir, this construction is not heavy enough. You are referred to Pages 140 and 141 of the Building Code.

Please notify this office by phone or by letter what you propose to do about this question before you proceed with the framing of the building.

Yours truly,

Inspector of Buildings.

27/593-I E-12/29/27

December 13, 1927

Mr. W. J. French
100 Highland Avenue
Portland, Maine

Dear Sir:

Referring to the building for George King at 77 Deerfield Road, we find that the shield over the heater smoke pipe in the cellar is not long enough to protect the entire length of the smoke pipe as required by law. It should be 3 feet or 3 feet 3 inches in length to fully comply with the law.

Please have this correction made promptly as we are unable to issue the final certificate for the building until this item can be checked off.

It is noted that you have made this shield but 12 inches wide for an 8 inch smoke pipe. We are not raising this question of width in this particular case, but you should note in the future that such a shield is required to be at least 3 times the diameter of the smoke pipe in width.

Very truly yours,

Inspector of Buildings

WJ/S



(R) GENERAL RESIDENCE ZONE

Permit No. 0802

APPLICATION FOR PERMIT

Class of Building or Type of Structure

3rd

Portland, Maine

JUN 18 1927 JUN 21 1927

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect and install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 77 Doxford Rd. Ward 8 Within Fire Limits? Yes Dist. No. 9
Owner's or Lessee's name and address George L. King 11 Cassadaga St. Telephone 7-8257-6
Contractor's name and address W. C. French 150 Highland Telephone _____
Architect's name and address _____
Proposed use of building Dwelling House No. families 1
Other buildings on same lot no

Description of Present Building to be Altered

Material _____ No. stories _____ Heat _____ Style of roof _____ Roofing _____
Last use _____ No. families _____

General Description of New Work

Build 1 Family Dwelling House

Details of New Work

Size, front 30 depth 34 No. stories 1 1/2 Height average grade to highest point of roof 28
To be erected on solid or filled land? solid earth or rock? earth
Material of foundation Concrete Thickness, top 10 bottom 12
Material of underpinning Brick Height 36" Thickness 8
Kind of roof Pitch Roof covering Asphalt Shingles
No. of chimneys 2 Material of chimneys Brick of lining Tile
Kind of heat Steam Type of fuel Oil Distance, heater to chimney 6'-0"
If oil burner, name and model Ballard
Capacity and location of oil tanks 1-275 gal tank 10' from heater (8/25/27) Tank
Is gas fitting involved? yes Size of service _____
Corner posts 4x6 Sills 4x8 Girt or ledger board? Girt Size 2-2x6
Material columns under girders Iron post Size 4" dia Max. on centers 8'-0"
Studs (outside walls and carrying partitions) 2x4-16" O. C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.
Joists and rafters: 1st floor 2x8 2nd 2x8 3rd _____ roof 2x6
On centers: 1st floor 16 2nd 16 3rd _____ roof 24"
Maximum span: 1st floor 14'-0" 2nd 15'-0" 3rd _____ roof _____
If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____ to be accommodated _____
Total number commercial cars to be accommodated _____
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no
Plans filed as part of this application? yes (see Garage) No. sheets 1
Estimated cost \$ 12830 12000 Fee \$ 5.75
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining hereto are observed? yes Total 4.00

INSPECTION COPY

Signature of owner _____

3829

Ward 8 Permit No. 27/892
 Location 77 Beechfield St
 Owner George King
 Date of permit June 21/27
 Not closing-in 8/13/27 - 8 AM
 Inspn. closing-in _____
 Final Notif. 10/31/27 9:30 AM
 Cert. of Occupancy issued Wm S.
 NOTES
 Header over Muller
 front entry fire escape
 the double fire escape
 over the entrance to the
 fire escape had the 20"
 studs 1st floor near
 furnace place close
 fire escape edge to roof
 1st floor ceiling with
 fire escape R.H. side
 down
 (fire escape)
 (Bollinger)
 (over)

8/16/27 - gas meter
 close to heater place
 in cellar. gas
 meter to 9 with
 fire installation
 Wm S.
 Above notation not
 changed at date of
 final inspect. 10/3/27
 fire escape close to
 smoke pipe etc.
 Wm S. French
 found the small
 fire escape
 Wm S. 10/4/27
 Not in 11/1/27
 " 11/4/27
 " 11/13/27
 Has studs only 12 x 12
 studs 6024/4 to full
 protection 12/11/27
 Cellar 12/13/27



APPLICATION FOR PERMIT FOR
HEATING, COOKING OR POWER EQUIPMENT

Portland, Maine, July 9, 1986

PERMIT ISSUED

JUL 10 1986

City Of Portland

To: INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location 79 Deerfield Rd. Use of Building dwelling- single Stories 2 New Building
Name and address of owner of appliance John Kelly - same Listing "xx"
Installer's name and address William Carr - 368 Gray Rd. Falmouth Telephone 791-0630

General Description of Work

To install boiler - replacement

IF HEATER, OR POWER BOILER

Location of appliance basement Any burnable material in floor surface or beneath? no
If so, how protected? Kind of fuel? # 2 fuel oil
Minimum distance to burnable material, from top of appliance or casing top of furnace 3' all around
From top of smoke pipe From front of appliance From sides or back of appliance
Size of chimney flue 8" x 8" Other connections to same flue none
If gas fired, how vented? Rated maximum demand per hour
Will sufficient fresh air be supplied to the appliance to insure proper and safe combustion? yes

IF OIL BURNER

Name and type of burner Labelled by underwriters' laboratories?
Will operator be always in attendance? Does oil supply line feed from top or bottom of tank?
Type of floor beneath burner Size of vent pipe
Location of oil storage Number and capacity of tanks
Low water shut off Make No
Will all tanks be more than five feet from any flame? How many tanks enclosed?
Total capacity of any existing storage tanks for furnace burners

IF COOKING APPLIANCE

Location of appliance Any burnable material in floor surface or beneath?
If so, how protected? Height of Legs, if any
Skirting at bottom of appliance? Distance to combustible material from top of appliance?
From front of appliance From sides and back From top of smokepipe
Size of chimney flue Other connections to same flue
Is hood to be provided? If so, how vented? Forced or gravity?
If gas fired, how vented? Rated maximum demand per hour

MISCELLANEOUS EQUIPMENT OR SPECIAL INFORMATION

Amount of fee enclosed? 25.00

APPROVED:

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed?

Oil Burner Lic # 522
Falmouth Fuel

CS 300

INSPECTION

FILE

APPLICANT'S

ASSESSOR'S COPY

Signature of Installer

William H. Carr Jr.

167 MPH MTS 005

8-11-86

NOTES

Installation completed

Permit No. 86-891
Location 99 Lee Street, Cal.
Owner John Kelly
Date of permit 7-9-86
Approved 7-10-86

- 1. 1/2" MIN. PIPING
- 2. 1/2" VENT PIPE
- 3. Kind of Head
- 4. Bumper, rigidity & Support
- 5. Name & Label
- 6. Inertia Control
- 7. High Limit Control
- 8. Main Control Switch
- 9. Low Water Control
- 10. High Limit Control
- 11. Ripping support & protection
- 12. Valves in supply line
- 13. Capacity of tanks
- 14. Tank rigidity & support
- 15. Oil gauge
- 16. Inertia Card
- 17. Oil level
- 18. Adequate ventilation
- 19. Protection to combustible
- 20. Thermal Control switch

OK

