CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date
ANSPACH DONALD		Jon Rioux	7/25/2007
Locatation	CBL	Status	Inspection Type
31 BELMEADE RD	111 C009001	Re-Inspect 10 Days	Complaint-Inspection

Code Int/Ext Floor Unit No. Area Compliance Date

1) 6-109.1

Violation: Sanitiation/Maintenance of assigned areas.

Notes: Remove the discarded construction debris: plastic, rugs, trash, broken glass, and other debris left in the

overall yard.

2) 105.1 Exterior Porch

Violation: Building w/o Permit

Notes: Rear porch built without a permit.

An after-the-fact permit application must be submitted to this office within ten (10) days of this notice.

Comments: