
CITY OF PORTLAND
DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street
Portland, Maine 04101

Inspection Violations

Owner/Manager ANSPACH DONALD		Inspector Jon Rioux	Inspection Date 7/25/2007
Location 31 BELMEADE RD	CBL 111 C009001	Status Re-Inspect 10 Days	Inspection Type Complaint-Inspection

Code	Int/Ext	Floor	Unit No.	Area	Compliance Date
1) 6-109.1					
Violation:	Sanitation/Maintenance of assigned areas.				
Notes:	Remove the discarded construction debris: plastic, rugs, trash, broken glass, and other debris left in the overall yard.				
2) 105.1	Exterior			Porch	
Violation:	Building w/o Permit				
Notes:	Rear porch built without a permit.				
	An after-the-fact permit application must be submitted to this office within ten (10) days of this notice.				
Comments:	08-06-07 Violations are still present, and Mr. Anspach did not report to our office to obtain and after-the-fact building permit.				