



FRONT DOOR




BATHROOM DOOR

MAY 22 2013
RECEIVED
Dept. of Building Inspections
City of Portland Maine



80

FRONT DOOR




RECEIVED


MAY 22 2013

Dept. of Building Inspections
City of Portland Maine


BATHROOM DOOR



REGISTER



BACK WALL




RECEIVED

MAY 22 2013

Dept. of Building Inspections
City of Portland Maine

FRONT WALL/GLASS WINDOWS



RECEIVED

MAY 22 2013

Dept. of Building Inspections
City of Portland Maine

LAUNDRY WALL

OUTSIDE WALL

