

94 Dartmouth Street

116-A-11



July 14, 1977 ✓

Beattie Lawrence Bradley
94 Dartmouth Street
Portland, Maine 04102

Dear Mr. Bradley:

Re: MCP-Oakdale Neighborhood Conservation Program
94 Dartmouth Street, Portland, Maine 116-A-11

The Housing Inspections Division of the Department of Neighborhood Conservation has recently completed an exterior inspection of your property in conjunction with the above referred program.

Congratulations are extended to you for the general condition of your property which was found to meet the standards established by the City's Housing Code. We did, however, note the following items that could cause future problems.

1. EXTERIOR TRIM & WALLS - peeling paint.
2. EXTERIOR - RIGHT - WALL - missing gutter.

3a
3a

Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.

Sincerely yours,
Joseph E. Gray, Jr., Director
Neighborhood Conservation

By Lyle D. Noves
Lyle D. Noves,
Chief of Housing Inspections

Inspector G. Bartlett
G. Bartlett

OK-1st-EX

Housing Inspection Division

1) Insp. Name BARTLETT



