

CITY OF PORTLAND
DEPARTMENT OF PLANNING & URBAN DEVELOPMENT
 389 Congress Street
 Portland, Maine 04101

Inspection Violations

Owner/Manager MACDONALD ROBERT C		Inspector John Bisesti	Inspection Date 04/25/2006
Locatation 70 FESSENDEN ST	CBL 117 A017001	Status	Inspection Type Complaint-Inspection

Code	Int/Ext	Floor	Unit No.	Area	Compliance Date
1) 6-109.4	Exterior				05/10/2006
Violation: Disposal of rubbish, garbage and waste.					
Notes: Trash bags on porch					
Comments: Trash on porch garbage out early. Needs letter Called John Hatcher and obtained owners mailing address for letter entered under property management					