CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date
MOULTON JOYCE L		Marland Wing	1/27/2005
Locatation	CBL	Status	Inspection Type
75 FESSENDEN ST	117 B020001	Re-Inspect 30 Days	Complaint-Housing Inspection

	Code	Int/Ext	Floor	Unit No.	Area (Compliance Date
1)	6-108.3 Violation: Notes:	Exterior Exterior windows, doors and skylights Front Hall Window broken Glass	2		Hall	05/27/2005
2)	6-108.3 Violation: Notes:	Exterior Exterior windows, doors and skylights Over windows broken galss	1		Various location	s 05/27/2005
3)	6-116.5 Violation: Notes:	Interior Fire Protection Hard-wired battery back up smoke detecto	rs required ii	n each unit	Various location	s 05/27/2005
4)	6-114.3 Violation: Notes:	Interior Maintenance of equipment. inoperative steam boiler			Cellar	05/27/2005
5)	6-111.3 Violation: Notes:	Interior Water supply. overall apartments no hot or cold water			Various location	s 05/27/2005
6)	6-113.5 Violation: Notes:	Interior Maintenance of lighting fixtures First floor rear hall loose light fixtures	1		Rear Hall	05/27/2005
7)	6-108.4 Violation: Notes:	1 Stairways, stairwells, stairs, porches. Rear hall wall broken hand rail	2		Rear Hall	05/27/2005
8)	6-108.2 Violation: Notes:	Interior Interior floors, walls, ceilings and doors Bathroom peeling paint	2	2	Bathroom	05/27/2005
9)	6-108.2 Violation: Notes:	Interior Interior floors, walls, ceilings and doors Kitchen wall missing plaster	2	2	Kitchen	05/27/2005
10)	6-108.3 Violation: Notes:	Interior Exterior windows, doors and skylights Front bedroom missing door	2	2	Bedroom	05/27/2005

CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date	
MOULTON JOYCE L		Marland Wing	1/27/2005	
Locatation	CBL	Status	Inspection Type	
75 FESSENDEN ST	117 B020001	Re-Inspect 30 Days	Complaint-Housing Inspection	

Comments: The Apartments shall remain vacant until a re-inspection is completed