

331 Dearino Avenue

117-E-25



October 20, 1977 ✓

John E. Murray
331 Deering Avenue
Portland, Maine 04103

Re: 331 Deering Avenue 117-C-25
NCP - Oakdale

Dear Mr. Murray:

The Housing Inspections Division of the Department of Neighborhood Conservation has recently completed an exterior inspection of your property in conjunction with the above referred program.

Congratulations are extended to you for the general conditions of your property which was found to meet the standards established by the City's Housing Code. We did, however, note the following items that could cause future problems.

1. Overall Roof - Worn shingles.

Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.

Sincerely yours,
Joseph E. Gray, Jr., Director
Neighborhood Conservation

By _____
Lyle D. Noyes,
Chief of Housing Inspections

Inspector H. B. Bartlett
Bartlett

OK-15EX

Housing Inspection Division

1) Insp. Name BAUTIST

2) Insp. Date	3) Insp. Type	4) Proj. Code	5) Assr's Chart	6) Bl.	7) Lot	8) Cens. s. Tract	9) Blk	10) Insp.	11) Form No.		
9/7/77		UCP-04K	117	D	25	15.00	412	16	194		
12) House No.	13) Sec. H. No.	14) Suff.	15) Direct.	16) Street Name							
331				DEERING							
18) Owner or Agent:								19) Status			
JOHN E. MURRAY								00			
21) Address:								20) Bldg's Rat.			
331 DEERING AVE								2			
22) City and State:								Zip Code:			
PORTLAND, ME								04103			
23) D. Units	24) Occ. D. U. s.	25) Rm. Units	26) Occ. R. U. s.	27) No. Occupants	28) Com'l U.	29) Bldg. Type	30) Stories	31) Const. Mat.	32) O. Bs.		
33) C. H.	34) Photo	35) Zoned For	36) Actual Land Use	37) D. D.	38) Lks. Ad. Bth. Fac.	39) Disr.	40) Closing Date				
Viol. No.	Sec. B.	Coord.	Violation Description			Fl. No.	Room Loc.	Area Type	Resp. Partv	Code Sect. Viol.	Viol. Rem. Date
1		10	SHINGLES				0A	RO			

