Marge Schmuckal Zoning Administrator Jeff Levine Director, Planning & Urban Development



#### CITY OF PORTLAND

## **Application for Legalization of Nonconforming Dwelling Units Section 14-391 – In effect March 24, 2004**

Location/Address of Legalization: A) william If Tax Assessor's Chart/Block/Lot: \(\frac{1}{2} / \inftitity\) / \(\frac{1}{2}\) Owner: Will Charges Telephone: Contact Name, address & telephone (if different than above): Cost of Work: \$ \( \) Fee: \$ (\$300 per legalized unit & \$75 per C of O) Total bldg. units: 2 Requested # of Units to be legalized: Current # of Legal D.U.: Attach evidence that each requested unit to be legalized existed as of 04/01/95. LIST evidence that you are submitting: E226 ८०८७ Attach evidence that the current owner/applicant neither constructed NOR established the nonconforming dwelling units to be legalized. LIST evidence that you are submitting: Dept. of Building Inspections City of Portland Manuthorizes the proposed work and that I have been authorized by the owner to make this application as his/her authorized agent. I agree to conform to all applicable laws of this jurisdiction. In addition, if a permit for work described in this application is issued, I certify that the Code Official's authorized representative shall have the authority to enter all areas covered by this permit at any reasonable hour to enforce the provisions of the codes applicable to this permit. **Signature of Applicant:** 

City of Portland, 389 Congress Street, Room 315, Portland Maine 04101 (207)-874-8695, FAX: (207) 874-8716

Application for Legalization of Nonconforming Dwelling Units

This is NOT a permit; you may NOT commence ANY work until the permit is issued.

#### YANKEE RESTORATION & BUILDING

Where quality is never out of Style 45 AUSTIN ST. PORTLAND, ME 04103 WILL CHEEVER

Client:

Job location:

Meg Christie/Will Cheever 72 William St.

Same

Portland, ME 04103

**Phone:** 772-8695

Email: sandplaymc@yahoo.com

**Date:** 7.1.13

# BUDGET FOR WORK TO MAKE FRONT HALL AND STAIRWAY A FIRE SAFE EXIT

This work involves installing five fire doors and sealing off 3 door openings.

Removal of five existing interior doors and replacing them with one hour rated fire doors

Subtotal \$5000

Removal of three interior doors and infilling the openings with one layer of  $\frac{1}{2}$ " CDX and two layers of  $\frac{5}{8}$ " fire rated drywall

Subtotal

\$800

Total for all work listed

\$5800

\*Pricing a repair or remodel is often no more than educated guesswork. There is no practical way to know what is behind walls, whether there be rot, insect damage or substandard workmanship. This budget estimate has been calculated in good faith. The actual job may be more or less but any additional costs would be discussed prior to completion.

Please feel free to call me with any questions-Thanks- Will 854-8400 shop 831-0486 cell

RECEIVED

AUG 2 2 2013

Dept. of Building Inspections City of Portland Maine

#### YANKEE RESTORATION & BUILDING

Where quality is never out of Style

45 AUSTIN ST.

PORTLAND, ME 04103

WILL CHEEVER

207-854-8400 www.yrestoration.com

RECEIVED

AUG 2 2 2013

Dept. of Building Inspections City of Portland Maine

This is a description of the work to be done at 72 William St. to satisfy Life Safety Code sec. 31.2.4.4 for the Fire Department. I have set forth below the provisions of that regulation, and our understanding of what, if anything, we need to do to meet these requirements:

A single exit shall be permitted in buildings where the total number of stories does not exceed three provided that all of the following conditions are met:

(1) The exit stairway does not serve more than one-half of a story below the level of exit discharge.

Does not apply to this situation- there is no living space below the 1st floor.

(2) The travel distance from the entrance door of any dwelling unit to an exit does not exceed 35 ft (10.7 m).

Does not apply to this situation- the travel distance is less than 35 feet from the entrance door to any of the units to the building exit.

(3) The exit stairway is completely enclosed or separated from the rest of the building by barriers having a minimum 1-hour fire protection rating.

The exit stairway is enclosed from the rest of the building with walls/ceilings rated to have a minimum of 1 hour fire resistance/ the existing plaster finish meets this requirement.

(4) All openings between the exit stairway enclosure and the building are protected with self-closing doors having a minimum 1-hour fire protection rating.

All openings between the exit stairway enclosure and the apartments are to be protected with self-closing doors having a minimum 1-hour fire protection rating. Some doors have already been replaced to meet this requirement and the rest will be installed. One door opening on each floor accessing the fire rated stairwell will have a door removed and the opening sealed with two layers of 5/8" fire rated drywall sandwiched around a plywood core.

(5) All corridors serving as access to exits have a minimum 20-minute fire resistance rating.

Does not apply in this situation- there are no corridors serving as access to the building exit.

(6) Horizontal and vertical separation having a minimum 1/2-hour fire resistance rating is provided between dwelling units.

The vertical separation that exists with either a drywall or plaster ceiling finish meets the ½ hour fire resistance requirement between units.



# PORTLAND MAINE

Strengthening a Remarkable City, Building a Community for Life . www.portlandmaine.gov

Jeff Levine, AICP, Director Marge Schmuckal, Zoning Administrator

# LEGALIZATION OF NONCONFORMING DWELLING UNITS FOR OFFICE USE ONLY

Address & CBL:	12 William St	117-C-019
Notices to owners of pro	perties situated within 300 feet se	nt on: gare le bayle startes, mailed 31/1
		5/13 received: Apparel, 3/1/13
City NFPA compliance g	iven on: scheduld, 3/5/1	3 received: Opprared 10/17/13*
Received any letters with	in 10 days from notices sent? 10	business days 3/11/13
Unit(s) existed prior to A	pril 1, 1995? <u>ASSESSON (ea</u>	1 1990 3 Units.
Unit(s) shown to be established	olished by different owner? 9°	a deed for wort over
Site plan included:	yes.	
Floor plans included?	Yes	
Is ZBA action required?	02	·,

Zoning Division Marge Schmuckal Zoning Administrator



## RECEIVE

OCT 1 8 2013

Dept. of Building Inspections City of Portland Maine

## NFPA LIFE SAFETY. CODE - FIRE PREVENTION CODE DWELLING UNIT COMPLIANCE

Section 14-391 of the Land Use Ordinance allows illegal nonconforming dwelling units to become legalized thru a given process. Part of this process is that the dwelling unit(s) that are requested to be legalized must comply or be able to comply with the NFPA Life Safety Code -Fire Prevention Code PRIOR to issuing the requested permit.

Please return this form to the Zoning Administrator (Marge Schmückal) as to compliance or the ability to comply with these codes.

Location:	72 William	St. St		117-0	-019			•
Owner:	Will Cherry							-
Address of	Owner: 45 Avs)	hin St. Rotte	LUE OH	03	Telephone	772-1	195.	
	,							
Applicant i	nformation if d	ifferent than	above:					
.,	•							`
Current nu	mber of legal u	nits: 1/0:1	(a)					
Number of	units to be lega	lized: one	1)		·			
	•	John: Hire	v(3)		•		•	٠,
Comments	of(approval)or	disapproval	(list any at	d all cond	ditions):	6		
FINEPA	evention A	pproves	control	st impo	~ comp	lution.	ofAlla	hol
Cond	itions of Ap	proval	•	•	. •			٠
Signature:	FFWER	Natoll			Date:	10/17/1	3	-
	Congress direct + P		101 (207)	874-8695 - P	AX: (207) 874-8	716 - TTY: (	207) 874-893	б

Room 315 - 389 Congres Street - Portland, Maine 04101

#### 1/17/2013

All units shall comply with the requirement of Chapter 10 Fire Prevention and Protection city ordinance.

All units shall meet the requirements of NFPA 101 Life Safety Code, 2009 edition and NFPA 1 Fire Code 2009 edition.

Legalized unit shall meet the egress requirement of NFPA 101 Life Safety Code, 2009 edition, Chapter 31.2.4.4 for single means of egress.

Hard wire battery backup photoelectric smoke alarms shall be provided on every level of the building and in the common area of each unit and in the bedrooms of each unit.

Hard wire battery backup CO alarms shall be provided in the common area outside the bedrooms of each unit.

All existing Life Safety violations on record for 72 William St shall be corrected

RECLIVED

OCT 1 8 2013

Dept. of Building Inspections City of Portland Maine



### CITY-OF-PORTLAND

# NFPA LIFE SAFETY CODE – FIRE PREVENTION CODE DWELLING UNIT COMPLIANCE

Section 14-391 of the Land Use Ordinance allows illegal nonconforming dwelling units to become legalized thru a given process. Part of this process is that the dwelling unit(s) that are requested to be legalized <u>must</u> comply or be able to comply with the NFPA Life Safety Code – Fire Prevention Code PRIOR to issuing the requested permit.

Please return this form to the Zoning Administrator (Marge Schmuckal) as to compliance or the ability to comply with these codes.

Location: 72	William	St.	117-	6-019		
Owner: Mil	Cherry					
Address of Own	er: 45 Aushin St.	Portland ME	04103	Telephone:	772-81	T
Applicant inform	nation if differe	nt than above:				
						•
Current number	of legal units:	two (2)				· .
Number of units	to be legalized:	one (1)				
		: Hru(3)				•
Comments of ap Disapprove with the Door with Smoke Alaum in	proval ox disapi t. 102 md mea self closing higo	provad(list any motesness on 1st, 2nd	y and all con usual from 1,3nd flow	ditions): 3rd H wr with	it is co	mplete
Smoke Alaumo u	Common Affect	(3 And bedro	ILLA CO EMBE	units		
Signature: Pe				Date:	3/7/13	



### CITY OF PORTLAND

## CITY OF PORTLAND HOUSING CODE DWELLING UNIT COMPLIANCE

Section 14-391 of the Land Use Ordinance allows illegal nonconforming dwelling units to become legalized thru a given process. Part of this process is that the dwelling unit(s) that are requested to be legalized <u>must</u> comply or be able to comply with the City of Portland's Housing Code PRIOR to issuing the requested permit.

Please return this form to the Zoning Administrator (Marge Schmuckal) as to compliance or the ability to comply with these codes.

ability to comply with these education
Location: 72 William St 117-C-019
Owner: Will Chew
Address of Owner: 72 William Portland ME 24103 Telephone: 772-8695
Applicant information if different than above:
Current number of legal units:
Number of units to be legalized: About one (1)
Lohi! thre (3)
Comments of approval/or disapproval (list any and all conditions):  Provide drum drap at 1st floor wash basin, Basement P+T to  term made 6-24" above floor, Handrail to basement, Secure Sond Starr
handrail to 2nd Sleer  Signature: Date: 3-5-13
7000