

413-417 DEERING AVENUE

SHALMISTON

Full cut #920R - Half cut #8.62B - Third cut #0203B - Fifth cut #920R

Date
Issued **Dec. 12, 1969**
Portland Plumbing Inspector
By **ERNOLD R. GOODWIN**

App. First Insp.
Date **Dec. 12, 1969**
By **ERNOLD R. GOODWIN**
CHIEF PLUMBING INSPECTOR

App. Final Insp.
Date **Dec. 12, 1969**
By **ERNOLD R. GOODWIN**
CHIEF PLUMBING INSPECTOR

Type of Bldg.
☐ Commercial
☐ Residential
☐ Single
☐ Multi Family
☐ New Construction
☐ Remodeling

PERMIT TO INSTALL PLUMBING

PERMIT NUMBER **978**

Address 115 Seaside Ave.		Installation For dwelling	
Owner of Bldg. Carl Miller		Owner's Address same	
Plumber Heuben Lutz		Date 12/12/69	
NEW	REPL		
		SINKS	
		LAVATORIES	
		TOILETS	
		BATH TUBS	
		SHOWERS	
		DRAINS FLOOR SURFACE	
		HOT WATER TANKS	
		TANKLESS WATER HEATERS	
		CARRIAGE DISPOSALS	
		SEPTIC TANKS	
		HOUSE SEWERS	1 2.00
	*	ROOF LEADERS	
		AUTOMATIC WASHERS	
		DISHWASHERS	
		OTHER	
		TOTAL	1 2.00

Building and Inspection Services Dept.: Plumbing Inspection



FILL IN AND SIGN WITH INK

APPLICATION FOR PERMIT FOR HEATING, COOKING OR POWER EQUIPMENT

Portland, Maine, March 3, 1950

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location 415 Deering Avenue Use of Building dwelling house No. Stories 1 ~~Existing~~ Building Existing
Name and address of owner of appliance George Lewis, 305 Deering Avenue
Installer's name and address Harris Oil Co., 202 Commercial Street Telephone 2-8504

General Description of Work

To install forced hot water heating system and oil burning equipment (replacement)

IF HEATER, OR POWER BOILER

Location of appliance or source of heat basement Type of floor beneath appliance concrete
If wood how protected? 3' Kind of fuel oil
Minimum distance to wood or combustible material, from top of appliance or casing top of furnace 3'
From top of smoke pipe 5' From front of appliance over 4' From sides or back of appliance over 3'
Size of chimney flue 8x12 Other connections to same flue none
If gas fired, how vented? none Rated maximum demand per hour none

IF OIL BURNER

Name and type of burner General Electric Labelled by underwriter's laboratories? yes
Will operator be always in attendance? yes Does oil supply line feed from top or bottom of tank? top
Type of floor beneath burner basement concrete
Location of oil storage basement Number and capacity of tanks 1-275 gal. existing
If two 275-gallon tanks, will three-way valve be provided? yes
Will all tanks be more than five feet from any flame? yes How many tanks fire proofed? 1-275 gal.
Total capacity of any existing storage tanks for furnace burners 1-275 gal.

IF COOKING APPLIANCE

Location of appliance basement Kind of fuel oil Type of floor beneath appliance concrete
If wood, how protected? 3'
Minimum distance to wood or combustible material from top of appliance 3'
From front of appliance 5' From sides and back 3' From top of smoke pipe 5'
Size of chimney flue 8x12 Other connections to same flue none
Is hood to be provided? yes If so, how vented? out
If gas fired, how vented? none Rated maximum demand per hour none

MISCELLANEOUS EQUIPMENT OR SPECIAL INFORMATION

Amount of fee enclosed? 2.00 (\$2.00 for one heater, etc., 50 cents additional for each additional heater, etc., in same building at same time.)

APPROVED

CH. 3-3-50. [Signature]

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

Harris Oil Co.

Signature of Installer by: [Signature]

INSPECTION COPY

Permit No. 501256 3-27-50

Location 415 Deering Avenue

Owner George Lewis

Date of permit 3/4/50

Approved 3-8-50 V.P. 115

NOTES

- 1 Fill Pipe ☒
- 2 Vent Pipe ☒
- 3 Kind of Heat ☒
- 4 Burner Rating & Supports ☒
- 5 Name & Label ☒
- 6 Tank Capacity ☒
- 7 Tank Rating ☒
- 8 Tank Distance ☒
- 9 Oil Gauge ☒
- 10 Instruction Card ☒
- 11 Capacity of Tank ☒
- 12 Tank Rating & Supports ☒
- 13 Tank Distance ☒
- 14 Oil Gauge ☒
- 15 Instruction Card ☒
- 16 ☒



FILL IN AND SIGN WITH INK

APPLICATION FOR PERMIT FOR
HEATING, COOKING OR POWER EQUIPMENT

NOV 8 1947

Portland, Maine, Nov 5 1947

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location 415 Daring Ave of Building Dwelling No. Stories 1 New Building Existing
Name and address of owner of appliance Harry Marcus, 415 Daring Ave
Installer's name and address Paul Farmer Co, 20 Free St Telephone 3-8187

General Description of Work

To install Oil Burner in gravity hot water system

IF HEATER, OR POWER BOILER

Location of appliance or source of heat Basement Type of floor beneath appliance Concrete
If wood, how protected? None Kind of fuel Oil
Minimum distance to wood or combustible material, from top of appliance or casing top of furnace Complete
From top of smoke pipe Complete From front of appliance Complete From sides or back of appliance Complete
Size of chimney flue Complete Other connections to same flue Complete
If gas fired, how vented? Complete Rated maximum demand per hour Complete

IF OIL BURNER

Name and type of burner Smith Maccomb EMZ Labelled by underwriter's laboratories? Yes
Will operator be always in attendance? No Does oil supply line feed from top or bottom of tank? Bottom
Type of floor beneath burner Concrete
Location of oil storage Basement Number and capacity of tanks One 275 gal
If two 275-gallon tanks, will three-way valve be provided? Yes
Will all tanks be more than five feet from any flame? Yes How many tanks fire proofed? None
Total capacity of any existing storage tanks for furnace burners No others

IF COOKING APPLIANCE

Location of appliance None Kind of fuel None Type of floor beneath appliance None
If wood, how protected? None
Minimum distance to wood or combustible material from top of appliance None
From front of appliance None From sides and back None From top of smokepipe None
Size of chimney flue None Other connections to same flue None
Is hood to be provided? None If so, how vented? None
If gas fired, how vented? None Rated maximum demand per hour None

MISCELLANEOUS EQUIPMENT OR SPECIAL INFORMATION

Amount of fee enclosed? 1.00 (\$1.00 for one heater, etc., 50 cents additional for each additional heater, etc., in same building at same time.)

APPROVED:

Oct 11 7 47 P.M.

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? Yes

Signature of Installer

Paul Farmer Co
by E. Allen

RECEPTION COPY

Permit No. 47/3041
Location 415 Deering Ave
Owner Harry Marcus
Date of permit 11/8/47
Approved NOT COMPLETE

NOTES 6/49
THH

- 1 Fill Pipe.....
- 2 Vent Pipe.....
- 3 Kind of Heat.....
- 4 Burner Rigidity & Supports.....
- 5 Name & Label.....
- 6 Stack Control.....
- 7 High Limit Control.....
- 8 Remote Control.....
- 9 Piping Support & Protection.....
- 10 Valves in Sd, p, & line.....
- 11 Capacity of Tanks.....
- 12 Tank Rigidity & Supports.....
- 13 Tank Distance.....
- 14 Oil Gauge.....
- 15 In.....
- 16

3-10-48 Interline
THH

4-1-48 Same
THH



FILL IN COMPLETELY AND SIGN WITH INK

PERMIT ISSUED

Permit No. 453

OCT 24 1945

APPLICATION FOR PERMIT FOR HEATING, COOKING OR POWER EQUIPMENT

Portland Maine, Oct. 23, 1945

To the INSPECTOR OF BUILDINGS, PORTLAND, ME

The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location 415 Denny St Use of Building 1st No. Stories 2 New Building Existing " "

Name and address of owner of appliance Mrs. R. J. Lewis, 415 Denny St

Installer's name and address Wm. J. Lewis, 70 Fair Telephone 7-8187

General Description of Work

To install

IF HEATER, POWER BOILER OR COOKING DEVICE

Is appliance or source of heat to be in cellar? Yes If not, which story Kind of Fuel Oil

Material of supports of appliance (concrete floor or what kind) Concrete

Minimum distance to wood or combustible material, from top of appliance or casing top of furnace, from top of smoke pipe from front of appliance from sides or back of appliance

Size of chimney flue Other connections to same flue

IF OIL BURNER

Name and type of burner Peter B-9-71 Labeled and approved by Underwriters' Laboratories? Yes

Will operator be always in attendance? Yes Type of oil feed (gravity or pressure) Gravity

Location oil storage Cellar No. and capacity of tanks 1-25 gal.

Will all tanks be more than seven feet from any flame? Yes How many tanks fireproofed? None

Amount of fee enclosed? 1.00 (\$1.00 for one heater, etc., 50 cents additional for each additional heater, etc., in same building at same time.)

Signature of Installer

INSPECTION COPY

305
Permit No. 45/1453
Location 415 Deering Ave.
Owner Mrs. George J. Lewis
Date of Permit 10/25/45

Post Card sent

Notif. for insp.

Approval Tag issued 11-10-45 FHS

Oil Burner Check List (date)

1. Kind of heat: Hot Water
2. Label ✓
3. t-siphon ✓
4. Oil storage ✓
5. Tank Distance ✓
6. Vent Pipe ✓
7. Fill Pipe ✓
8. Gauge ✓
9. Rigidity ✓
10. Feed safety ✓
11. Pipe sizes and material ✓
12. Control valve ✓
13. Ash pit vent ✓
14. Temp. or pressure safety ✓
15. Instruction card ✓
16.

11-10-45 NOTES

Manually operated
Valve at burner
Fusible Valve at
burner FHS

28/175
2-3/11/30

May 12, 1930

Mr. L. E. Butland
176 Coyle Street
Portland, Maine

Dear Sir:

Referring again to the matter of the partition between the garage and dwelling house at the corner of Deering Avenue and Longfellow Street, a letter was sent to you with regard to this matter on August 5, 1929, and I have since seen you on several occasions and you have promised to have the thickness of the asbestos lumber on the garage side of this wall increased to a total thickness of 4/8ths of an inch and well cemented at the joints, and also to have the partition covering made tight around the electric outlet or switch box.

Upon examination on May 9, 1930, it was found that you have not done this work.

I feel that this Department has been very patient indeed with regard to this apparent violation of the Building Code. If the work is not completed in compliance with the Code on or before May 15, 1930, it will be necessary to make complaint against you for violation of the Building Code without further notice.

Very truly yours,

Inspector of Buildings.

AM/HC
CC-Messrs. Schwartz & Rosenberg-102 Exchange St.

228/1675

August 5, 1929

Mr. L. E. Butland
176 Coyle Street
Portland, Maine

Dear Sir:

You will recall that I called your attention to the fact that the asbestos lumber placed upon the wall of the Schwartz and Rosenberg garage where it adjoins their dwelling house at the corner of Doering Avenue and Longfellow Street is not thick enough in accordance with the law.

Apparently you have not yet increased the thickness of this asbestos lumber and you have not made the wall covering tight around the electric outlet or switch box.

I have talked with Mr. Rosenberg concerning this, and he says that the fixing of this matter to comply with the law is up to you.

Will you be kind enough to take care of this matter promptly and notify this office when the same has been completed?

Very truly yours,

Inspector of Buildings.

JH/HO

CC- Schwartz and Rosenberg

48 ft

4 ft

2 car
garage

3 ft


Proposed 1st story
Bed R.
9x16

2 Family
House

7 ft

100 ft

80 ft





APPLICATION FOR PERMIT
Class of Building or Type of Structure Third Class

Portland, Maine, December 15, 1928

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect after install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications: See 412-417 Building Code

Location Elm St., Decatur Ave. & Longfellow Ward Within Fire Limits? No Dist. No. _____

Owner's or lessor's name and address Harry Shwarts & Jesse Rosenberg 103 Exchange Telephone _____

Contractor's name and address J. A. Portland, 176 Maple St. Telephone 8614 M

Architect's name and address _____

Proposed use of building Dwelling house and 2 car garage attached No. families 2

Other buildings on same lot _____

Description of Present Building to be Altered

Material wood No. stories 2 Heat _____ Style of roof _____ Roofing _____

Last use Dwelling house No. families 2

General Description of New Work

To erect one story frame addition (bedroom) 9' x 10', which is to be built between dwelling house and 2 car garage

The partition between addition and garage will be covered on both sides with sheets of combined asbestos and cement not less than 5/8" in thickness with all joints filled with cement mortar. No door between dwelling and garage.

Garage to have concrete floor

Details of New Work

Size, front _____ depth _____ No. stories _____ Height average grade to highest point of roof _____

To be erected on solid or filled land? _____ earth or rock? _____

Material of foundation stone in mortar Thickness, top _____ bottom _____

Material of underpinning " " " Height _____ Thickness _____

Kind of roof flat Roof covering Tar and gravel 5 ply

No. of chimneys no Material of chimneys _____ of lining _____

Kind of heat _____ Type of fuel _____ Distance, heater to chimney _____

If oil burner, name and model _____

Capacity and location of oil tanks _____

Is gas fitting involved? _____ Size of service _____

Corner posts _____ Sills 6x6 Girt or ledger board? _____ Size _____

Material columns under girders _____ Size _____ Max. on centers _____

Studs (outside walls and carrying partitions) 2x4-16" O.C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.

Joists and rafters: 1st floor 2x8, 2nd 2nd ceiling, 3rd _____, roof 2x8

On centers: 1st floor 16", 2nd 16", 3rd _____, roof 16"

Maximum span: 1st floor 9', 2nd _____, 3rd _____, roof 9'

If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

Cars now accommodated on same lot _____, to be accommodated _____

Number commercial cars to be accommodated _____

Will auto body repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? _____

Plans filed as part of this application? yes No. _____

Estimated cost \$ 250. Fee \$.75

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? Yes

Signature of owner Harry Shwarts and Jesse Rosenberg

Signature of owner Lyle Portland

INSPECTION COPY

Wm. F. Leachman

CHIEF OF FIRE DEPT.

833

Ward 8 Permit No. 2875-M
Location Ely Co. Deering St. - 1st
by H.M. Shurtz & Jene Penley
Date of permit 12/19/28
Notif. closing-in _____
Insp. closing-in _____
Final Notif. _____
R. _____ pn. _____
Cert. of Occupancy issued _____

NOTES

5/16/29 -- On 1st
asbestos lumber
on garage side
8/1/29 - location to
Butland
7/1/20 - location to
Butland

7/5/31

ED



APPLICATION FOR PERMIT

Class of Building or Type of Structure Third Class

Portland, Maine, March 21, 1929

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

This undersigned hereby applies for a permit to ~~erect~~ alter ~~install~~ the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location on Deering Ave. & Longfellow St. Ward 8 Within Fire Limits? No Dist. No. _____
Owner's or Lessee's name and address Shwartz & Rosenberg, 102 Exchange St. Telephone _____
Contractor's name and address L. M. Butland, 186 Coyle St. Telephone F 8614 M
Architect's name and address _____
Proposed use of building dwelling house No. families 2
Other buildings on same lot garage

Description of Present Building to be Altered

Material wood No. stories 2 1/2 Heat _____ Style of roof pitch Roofing asphalt
Last use dwelling house No. families 2

General Description of New Work

To put 8' dormer on one side of roof (11' from side lot)
(to provide ventilation for bath room (existing) on third floor)

To cut in new window on the side of dwelling to light stairs to third floor
To remove existing closet and move entrance to third floor stairs over about 3'
To move partition about 2' to make bathroom on second floor smaller, and make window smaller (to have about 24 x 24 glass)
To remove one brick interior chimney

Size, front _____ depth _____ No. stories _____ Height average grade to highest point of roof _____
To be erected on solid or filled land? _____ earth or rock? _____
Material of foundation _____ Thickness, top _____ bottom _____
Material of underpinning _____ Height _____ Thickness _____
Kind of roof _____ Roof covering asphalt roofing Class C Und. Lab.
No. of chimneys _____ Material of chimneys _____ of lining _____
Kind of heat _____ Type of fuel _____ Distance, heater to chimney _____
If oil burner, name and model _____
Capacity and location of oil tanks _____
Is gas fitting involved? _____ Size of service _____
Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____
Material columns under girders _____ Size _____ Max. on centers _____
Studs (outside walls and carrying partitions) 2x4-16" O. C. Girts 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.
Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____
Total number commercial cars to be accommodated _____
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no
Plans filed as part of this application? no No. sheets _____
Estimated cost \$125. Fee \$ 75
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? Yes

Signature of owner. By Lyle Butland

INSPECTION COPY

Ward 8 Permit No. 29/319 M.

Location Cr. Deering Ave + Longfellow St.

Owner Shwartz + Rosenberg

Date of permit 3/21/69

Notif. closing-in _____

Inspn. closing-in _____

Final Notif. _____

Final Inspn. _____

Cert. of Occupancy issued _____

NOTES

Watch that they do not
tend to put in additional
family in 3rd floor

~~9/1/71~~

THOMPSON S. SANDS, VICE PRESIDENT
 EDW. TAYLOR, VICE PRESIDENT
 J. W. SLOAN, VICE PRESIDENT
 J. W. SLOAN, VICE PRESIDENT
 W. P. ACCAIN, SEC. TREASURER
 J. G. SELBRACK, SECRETARY


RALPH B. IVES, PRESIDENT

GEORGE L. BURNHAM, TREASURER
 FRANK G. BUSH, COMPTROLLER
 W. B. GOODWIN, ASSISTANT SECRETARY
 FRANK S. BECKER, JR., ASSISTANT SECRETARY
 ASHBY E. BLADEN, ASSISTANT SECRETARY



SHWARTZ & ROSENBERG
 General Agents
 102 Exchange Street
 Telephone Forest 4080

Portland, Maine,



5
 12
 37
 10

15
 50
 5
 20
 3

12
 12
 37
 1



APPLICATION FOR PERMIT

Permit No. _____

Class of Building or Type of Structure Third Class

Portland, Maine, October 17, 1928

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to ~~erect~~ alter ~~install~~ the following building ~~structure~~ equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications: (See 413-417 Deering Avenue)

Location SELY Corner Deering Ave. & Longfellow St. Ward 8 Within Fire Limits? No Dist. No. _____
Owner's or Lessee's name and address Jesse M. Rosenberg & Harry M. Schwartz, 102 Exchange St. Telephone F 4080
Contractor's name and address Ira Dressner, moving Telephone _____
Architect's name and address _____
Proposed use of building 2 car garage No. families _____
Other buildings on same lot 2 family dwelling house

Description of Present Building to be Altered

Material Wood No. stories 1 Heat _____ Style of roof _____ Roofing _____
Last use _____ 2 car garage No. families _____

General Description of New Work

To move building 18' x 20' from 530 Forest Avenue

THIS PERMIT DOES NOT INCLUDE THE
RIGHT TO MOVE ANY BUILDING THROUGH
THE PUBLIC STREETS OF THE CITY.

Details of New Work

Size, front _____ depth _____ No. stories _____ Height average grade to highest point of roof _____
To be erected on solid or filled land? _____ earth or rock? _____
Material of foundation Concrete in mortar Thickness, top _____ bottom _____
Material of underpinning _____ Height _____ Thickness _____
Kind of roof _____ Roof covering _____
No. of chimneys _____ Material of chimneys _____ of lining _____
Kind of heat _____ Type of fuel _____ Distance, heater to chimney _____
If oil burner, name and model _____
Capacity and location of oil tanks _____
Is gas fitting involved? _____ Size of service _____
Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____
Material columns under girders _____ Size _____ Max. on centers _____
Studs (outside walls and carrying partitions) 2x4-16" O.C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.
Joists and rafters: 1st floor Concrete, 2nd _____, 3rd _____, roof _____
On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot none, to be accommodated 2
Total number commercial cars to be accommodated none
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? no

Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no
Plans filed as part of this application? yes No. sheets 1
Estimated cost \$ _____ Fee \$.42
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? Yes

Signature of owner

INSPECTION COPY

Jesse M. Rosenberg & Harry M. Schwartz
7 Jesse M. Rosenberg

Permit No. 287398 M
Company SEly Cor: Deering Ave to 1st St
Jesse M. Rosenberg
Exhibit 11/6/28
sing-in
sing-in
if.
Fin. on.
Cert. of Occupancy issued hmc

NOTES

5/6/24
hmc



IN GENERAL RESIDENCE ZONE

APPLICATION FOR PERMIT

Class of Building or Type of Structure Third ClassPermit No. 2300

NOV 9 1928

Portland, Maine, October 17, 1928

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect-al. the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location SEly Corner Deering Ave. & Longfellow Stg. Ward 8 Within Fire Limits? No Dist. No. 10, Exchange St.
Owner's or Lessee's name and address Jesse M. Rosenberg, & Harry M. Swartz Telephone 3 4090
Contractor's name and address Ira Dresser - moving Telephone
Architect's name and address
Proposed use of building Dwelling house No. families 2
Other buildings on same lot garage 2 car

Description of Present Building to be Altered

Material Wood No. stories 2 1/2 Heat Style of roof Roofing
Last use Dwelling house No. families 2

General Description of New Work

To move building 50' x 32' from 520 Forest Avenue to above location

THIS PERMIT DOES NOT INCLUDE THE RIGHT TO MOVE ANY BUILDING THROUGH THE PUBLIC STREETS OF THE CITY

Details of New Work

Size, front depth No. stories Height average grade to highest point of roof
To be erected on solid or filled land? earth or rock?
Material of foundation Stone in mortar granite blocks Thickness, top 16" bottom 18"
Material of underpinning brick granite blocks Height 2'6" Thickness 12"
Kind of roof Roof covering
No. of chimneys Material of chimneys of lining
Kind of heat hot water (2) Type of fuel coal Distance heater to chimney 4-5'
If oil burner, name and model
Capacity and location of oil tanks
Is gas fitting involved? Size of service
Corner posts Sills Girt or ledger board? Size
Material columns under girders Size Max. on centers
Studs (outside walls and carrying partitions) 2x4-16" O.C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.
Joists and rafters: 1st floor , 2nd , 3rd , roof
On centers: 1st floor , 2nd , 3rd , roof
Maximum span: 1st floor , 2nd , 3rd , roof
If one story building with masonry walls, thickness of walls? height?

If a Garage

No. cars now accommodated on same lot , to be accommodated
Total number commercial cars to be accommodated
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building?

Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no
Plans filed as part of this application? yes (see garage) No. sheets
Estimated cost \$ Fee \$ 1.00
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? Yes

INSPECTION COPY


Signature of owner

Jesse M. Rosenberg and Harry M. Swartz
Jesse M. Rosenberg

Ward 8 Permit No. 282390
Location SEly. Cor. Deering Ave. & Longfellow St.
Owner Jesse M. Rosenberg et al
Date of permit 11/6/28
Notif. closing-in _____
Inspn. closing-in _____
Final Notif. _____
Final Inspn. _____
Cert. of Occupancy issued _____

NOTES

Side line clearance
at least 5'-0" according
to stakes given on job
12/18/28 LK



Date 13 November 1995
Permit # 4981

LOCATION: 415 Deering Ave

OWNER Miller

ADDRESS

TOTAL EACH FEE

OUTLETS		Receptacles (number of)	Switches							
									.20	
FIXTURES		incandescent	fluorescent						.20	
		fluorescent strip							.20	
SERVICES		Overhead	Upgrade	100 - 200		TTI. AMPS TO	800		15.00	15.00
		Underground					800		15.00	
TEMPORARY SERV.		Overhead				AMPS OVER	800		25.00	
		Underground					800		25.00	
MEYERS		(number of)							1.00	
MOTORS		(number of)							2.00	
RESID/COM		Electric units							1.00	
HEATING		oil/gas units							5.00	
APPLIANCES		Ranges	Cook Tops		Wall Ovens				2.00	
		Water heaters	Fans		Dryers				2.00	
Disposals		Dishwasher	Compactors		Others (denote)				2.00	
MISC. (number of)		Air Cond/win							3.00	
		Air Cond/cent							10.00	
		Signs							5.00	
		Pools							10.00	
		Alarms/res							5.00	
		Alarms/com							15.00	
		Heavy Duty							2.00	
		Outlets								
		Circus/Carnv							25.00	
		Alterations							5.00	
		Fire Repairs							15.00	
		E Lights							1.00	
		E Generators							20.00	
		Panels							4.00	
TRANSFER		0-25 Kva							5.00	
		25-200 Kva							8.00	
		Over 200 Kva							10.00	
TOTAL AMOUNT DUE										
MINIMUM FEE									25.00	25.00

INSPECTION: Will be ready 11/17 10:00 or will call _____

CONTRACTORS NAME Joe Dube
ADDRESS 22 Snow Rd Scarborough
TELEPHONE 885-0030
MASTER LICENSE No. 4981 SIGNATURE OF CONTRACTOR [Signature]
LIMITED LICENSE No. _____

SIGNATURE OF CONTRACTOR

ELECTRICAL INSTALLATIONS—

Permit Number 4481

Location 415 DeSoto Ave

Owner Wiley

Date of Permit 11-13-95

Final inspection 11-17-95

By Inspector He. B. D.

INSPECTIONS: Service 11-17-93 by 813

Service called in 10:00 Am

Closing-in _____ by _____

PROGRESS INSPECTIONS: _____ / _____ / _____

_____ / _____ / _____

_____ / Sp. _____ / No. _____

_____ / _____ / _____

_____ / _____ / _____

_____ / _____ / _____

DATE:

REMARKS:

[illegible]

