

113 Dartmouth Street 118-E-18



July 25, 1977 ✓

Owen and Annabelle Mack
143 Dartmouth Street
Portland, Maine

Dear Mr. and Mrs. Mack: Re: 143 Dartmouth Street -/18-E-18
 NCF-OAKDALE
 Neighborhood Conservation Program

The Housing Inspections Division of the Department of Neighborhood Conservation has recently completed an exterior inspection of your property in conjunction with the above referred program.

Congratulations are extended to you for the general conditions of your property which was found to meet the standards established by the City's Housing Code.

Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.

Sincerely yours,

Joseph E. Gray, Jr. Director
Neighborhood Conservation

By Lyle D. Moyes
Lyle D. Moyes
Chief of Housing Inspections

Inspector G. Bartlett

/ss

OK-1st-EX

STRUCTURE INSPECTION SCHEDULE

1) Insp. Name BARTLETT

[illegible]

