Abram Environmental

Invoice

P. O. Box 1627 Scarborough, ME 04070 Bus: 207-892-7045

Date	Invoice #
9/1/2016	AE-821

Dus. 207-072-7045		Ł	9/1/2010	AE-821
Bill To	201/2016	Ship To		
James Pierce Katherine Lesser 22 Orland St Portland, Maine 04103	09/07/1			and the second
	v			

Quantity Item Code Description Price Each Amount Item #1 Cleanup of asbestos transite siding debris from garage floor at 22 Orland St. in Portland Maine	P.O. Number	r Terms	Rep	Ship	Via	F.O.B.		Project
Item #1 Cleanup of asbestos transite siding debris from garage floor at 22 Orland St. in Portland Maine 300.00		Due on recei	ipt	9/1/2016	10.70			
22 Orland St. in Portland Maine	Quantity	Item Code		Descripti	on	Pı	rice Each	Amount
		Item #1	22 Orland St.	pestos transite siding on Portland Maine	lebris from garage	floor at	300.00	300.0

Total

\$300.00



WASTE SHIPMENT RECORD

	1. Work site (Generator): Name James Pierce Katherine Lesser Mailing Address	Owner's Name JAMES PIETEL					
	Name James Pierce Katherine Lesser Mailing Address 22 Orland St. City/State/Zip Portland, ME-04/03	KATHERINE LESSO	707-232-4543				
	2. Remover's name and address:		Remover's telephone no.				
	Abram ENVITONMENTAL YO BOX 1627 G	Arborough, ME	207-892-7045				
	3. Waste Disposal site (WDS): Name WASTE MANAGEMENT of ME	WDS telephone no. 800	-562-7779				
	Mailing Address PO BOX 637 City/State/Zip Norridgework, ME	Additional Information	n:				
œ	Physical Site Location US Roufe #2 No reviolent he W.	Profile No	100687NE				
VTOF	4. Name and address of responsible agency						
GENERATOR	ME DEP AS						
ত	5. Description of materials	6. Containers No. Type	7. Total quantity m³ (yd³)				
	RQ, ASBESTOS, 9, NA2212, III RQ = 1 LB (ONE POUND) ROW Fridale Siding!	4 Bags	L-01(443)				
	Special handling instructions and additional information (provided I * EMERGENCY RESPONSE NUMBER: (800) 645-8265	oy generator.)					
	9. OPERATOR'S CERTIFICATION: I hereby declare that the accurately described above by proper shipping name and are are in all respects in proper condition for transport by highw government regulations. NOTE: Generator must retain a copy of the condition of the condition of the copy of the condition of the copy of the	classified, packed, mar ay according to applica	ked, and labeled, and				
	Printed/typed name & title	Signature / -/	Month Day Year				
	10. Transporter 1 (Acknowledgement of receipt of materials)	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					
	Printed/typed name & title	Signature	Month Day Year				
	Coling Deckwith President		a al 11				
EH	Address and telephone no. 2017-892-7045	Bur bands	8-31-16				
OR	PO Box 1627 Scarbsrough, ME	, y carye					
NSP	11. Transporter 2 (Acknowledgement of receipt of materials)						
TRANSPORTER	Printed/typed name & title	Signature	Month Day Year				
	Address and telephone no.						
2	12. Discrepancy indication space	Rejected: Yes	No T				
ISPOSALSITE	13. Waste disposal site owner or operator: Certification of receipt of asbestos						
/SO	materials covered by this manifest except as noted in item 12.						
S	Printed/typed name & title	Signature	Month Day Year				



Outline Of Services

Prepared For: James Pierce

Katherine Lesser 22 Orland St.

Portland, Maine 04103

DATE: September 1, 2016

Abram Environmental is pleased to inform you of the following asbestos cleanup conducted at 22 Orland Street located in Portland, Maine. Abram conducted an asbestos cleanup on August 31, 2016 at this residence. The following remediation services have been conducted:

Removal Whole Component Of Asbestos Containing Transite Siding Material: All work operations performed were in compliance with the asbestos regulations as set forth in both OSHA 29 CFR Part 1926.1101 and 1910.1001, and the State of Maine DEP Regulations, Chapter 425.

All of the asbestos remediation related work was performed by asbestos abatement certified personnel (State of Maine).

The asbestos waste was contained in two layers of 6-mil polyethylene sheeting and labeled in accordance with 29 CFR 1910.1001. The generated asbestos waste is being disposed of at a ME DEP approved landfill facility. There were a total of 4 bags of asbestos waste.

Abram Environmental visually accessed the work area. The visual evaluation by Abram complied with Maine DEP CMR 425.10 (d)(1).

If you have any questions or concerns regarding this project, please contact me at (207) 892-7045. We appreciate the opportunity to assist you with your environmental needs. Thank you for your time.

Sincerely,

Colin Beckwith

President