

STATE OF MAINE Department of Environmental Protection



Notice of Intent to Remove an Underground Oil Storage Tank Facility and/or Underground Product Piping

Notification		Maine DEP Local Fire Department			
(Sent a copy of this notice) Certif		Tank Installer (as re	aulred)	Site Assessor (as require	d)
Of Dig Field	o, 🗀 •••••••		, , , , , , , , , , , , , , , , , , , 		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
Facility Information Facility Name: ME Mdical CTR Brighton Campus				Registration #:	1031
335 Brighton Ave				Portland	
Facility Address				Town	802-3000
Maine Medical Center 335 Brighton Ave				207	′- 879 -8000
Owner Name Owner Address Owner Phone					
Identification of Tank / Piping to be removed					
🗓 Tank#	8-1	Tank Size:	10,000	Tank Age:	20
⊠ Piping	Double wall flex	Product:	#2 Fuel	Piping Age:	20
☑ Tank#	9-1	Tank Size:	10,000	Tank Age:	20
⊠ Plping	Double wall flex	Product:	Diesel	Piping Age:	20
□ Tank#		Tank Size:		Tank Age:	
☐ Piping		Product;		Piping Age:	
Additional Removal Information					
Did any tank or piping above store Class I liquids (e.g., gasoline, aviation fuel)					
NO within the last 12 months?					
IF YES, REMOVAL OF THE TANK(S) OR PRODUCT PIPING MUST BE DONE UNDER THE DIRECTION OF A MAINE CERTIFIED TANK INSTALLER AND THE INERTING METHOD AND CLEANING LOCATION MUST BE IDENTIFIED.					
VILLARESSIERE CONTROLLE SEE AND DESCRIPTION OF THE PROPERTY OF				ation Off Location	
			Jan Jak		
	Tank installer Name and i	D Number	Insteller Signature		Date
Note: Site assessments must be conducted in accordance with Chapter 691(11)(A)(1)(d) and Appendix P.					
Site Assessor (if applicable) St Germain Collins				207-591-7000	
Site Assessor				Phone Number	
Contractor wind will remove Portland Pump Co				207-883-4317	
Contractor				Phone Number	
Expected Cate of Cate					
Month/Date/Year I hereby provide Notice that I intend to properly remove the underground oil storage tank facility as described above.					
RICHARD SPICER STEEL SOLVENTIONS KILL SOLVET 5/26/16					
Chros of Arriva	TINT UP	ATUDOS 15	Signature	/હ્યુ	Date IV

NOTE: WHEN TANK AND/OR PIPING HAS BEEN REMOVED, PLEASE FILL OUT AND SEND IN THE REMOVAL CONFIRMATION. EXPIRES AFTER SIX (6) MONTHS IF DEPARTMENT DOES NOT RECEIVE REMOVAL CONFIRMATION