





98 Rack left side  
Portland ME  
1st floor Bathroom  
Bathroom 1



load-bearing wall

All referend with 2x4's 160c.