
CITY OF PORTLAND
DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street
Portland, Maine 04101

Inspection Violations

Owner/Manager MYERS TIMOTHY &		Inspector Jon Rioux	Inspection Date 5/14/2007
Location 9 GLENWOOD AVE	CBL 123 D003001	Status Re-Inspect 10 Days	Inspection Type Complaint-Inspection

Code	Int/Ext	Floor	Unit No.	Area	Compliance Date
1) 6-109.4	Exterior			Porch	
Violation:	Disposal of rubbish, garbage and waste.				
Notes:	All rubbish, garbage and waste must be stored in separate watertight, tightly covered plastic or metal containers. Each container shall be kept covered at all times so as to prevent the ingress and egress of flies, rats or other animals. This shall include the bags of dog feces and carpet left on the left porch, front the property.				

Comments: