## CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

## **Inspection Violations**

	wner/Manag JLSIFER GR			-	Inspector Tom Markley			Inspection Date 10/5/2005	
LocatationCBL278 WOODFORD ST123 F026001			Status Yellow 5-9 Violations			Inspection Type Complaint-Inspection			
	Code	Int/Ext			Floor	Unit No.	Area	Compliance Date	
1)	6-108.3 Violation: Notes:	Exterior311front living roomExterior windows, doors and skylightsFront living roomFront living roomBroken windowFront living roomFront living room					oom		
2)	6-108.3 Violation: Notes:	Exteriorfront bedroomExterior windows, doors and skylightsFront bedroomBroken windowFront bedroom						pm	
3)	6-108.3 Violation: Notes:	Exterior311Through-outExterior windows, doors and skylightsWindows will not stay opened without wedging or windows will not open.							
4)	6-108.2 Violation: Notes:	Interior Interior floors Missing ceili	d doors	3	11	Bathroom			
5)	6-111.4 Violation: Notes:		of plumbing fixture	es.	3	11	Kitchen		
6)	6-116.5 Violation: Notes:	Interior 3 11 Unit Fire Protection No Smoke detectors in the unit Note: Must have smoke detectors in as soon as possible but No Late than							
7)	6-113.3 Violation: Notes:	Interior Passageways and common stair Lights turned off- could not see n		-	1-2-3 way. umbers on doors of some apartm		Hallway ents		
8)	6-113.1 Violation: Notes:	Interior Lighting standards/Habitable rooms switch plates missing in various areas			3	11	throughout		

Comments: