

166-168 COYLE STREET

SHAW-WALKER

Fed. cut #920R Half cut #9202R Third cut #9203R Film cut #9205R

Date Issued **3/10/67**
Portland Plumbing Inspector
By **ERNOLD R. GOODWIN**

App. First Insp.
Date **3/21/67**
By **H. Montgomery**
App. Final Insp.
Date **MAR 22**
ERNOLD R. GOODWIN
CHIEF PLUMBING INSPECTOR
Type of Bldg.

- ☐ Commercial
☐ Residential
☐ Single
☐ Multi Family
☐ New Construction
☐ Remodeling

PERMIT TO INSTALL PLUMBING

PERMIT NUMBER **17000**

Address 166 Maple Street, 2nd.			
Installation For Dwelling			
Owner of Bldg. Alston P. Wood			
Owner's Address 166 Maple Street		Date: 3/12/67	
Plumber Portland Gas Light Company		NO.	FEE
NEW	REF'L		
		SINKS	
		LAVATORIES	
		TOILETS	
		BATH TUBS	
		SHOWERS	
		DRAINS	
		FLOOR SURFACE	
		HOT WATER TANKS	
		ANKLESS WATER HEATERS	
		GARBAGE DISPOSALS	
		SEPTIC TANKS	
		HOUSE SEWERS	
		ROOF LEADERS	
		AUTOMATIC WASHERS	
		DISHWASHERS	
		OTHER	
		TOTAL	2.00

Building and Inspection Services Dept.: Plumbing Inspection



FILL IN AND SIGN WITH INK

APPLICATION FOR PERMIT FOR HEATING, COOKING OR POWER EQUIPMENT

Portland, Maine, $\frac{1}{2}$ 2 1/2 1/2 1/2

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location 155 10th St. S.W. Use of Building Office No. Stories 4 New Building
Existing "X"
Name and address of owner of appliance Mr. J. H. Smith, 155 10th St. S.W.
Installer's name and address Mr. J. H. Smith, 155 10th St. S.W. Telephone 2-2405

General Description of Work

To install Model A Eastwood burner in connection with existing steam heating system

IF HEATER, OR POWER BOILER.

Location of appliance _____ Any burnable material in floor surface or beneath? _____
If so, how protected? _____ Kind of fuel? _____
Minimum distance to burnable material, from top of appliance or casing top of furnace _____
From top of smoke pipe _____ From front of appliance _____ From sides or back of appliance _____
Size of chimney flue _____ Other connections to same flue _____
If gas fired, how vented? _____ Rated maximum demand per hour _____
Will sufficient fresh air be supplied to the appliance to insure proper and safe combustion? _____

IF OIL BURNER

Name and type of burner Hotel A. Sauterhoff Labeled by underwriter's laboratories? Yes
Will operator be always in attendance? Yes Does oil supply line feed from top or bottom of tank? Bottom
Type of floor beneath burner Concrete
Location of oil storage Below Number and capacity of tanks 1 - 275
If two 275-gallon tanks, will three-way valve be provided? Yes
Will all tanks be more than five feet from any flame? Yes How many tanks fire proofed? 0
Total capacity of any existing storage tanks for furnace burners 275

IF COOKING APPLIANCE

Location of appliance _____ Any burnable material in floor surface or beneath? _____
If so, how protected? _____ Kind of fuel? _____
Minimum distance to wood or combustible material from top of appliance _____
From front of appliance _____ From sides and back _____ From top of smokepipe _____
Size of chimney flue _____ Other connections to same flue _____
Is hood to be provided? _____ If so, how vented? _____ Forced or gravity? _____
If gas fired, how vented? _____ Rated maximum demand per hour _____

MISCELLANEOUS EQUIPMENT OR SPECIAL INFORMATION

RECEIVED
OCT 6 1952
DEPT. OF BLD'G. INSP.
CITY OF NEW YORK

Amount of fee enclosed? \$ 2.00 (\$2.00 for one heater, etc., 50 cents additional for each additional heater, etc., in same building at same time.)

APPROVED

APPROVED: OK. 10652. Jms

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? Yes

Signature of Installer

John Marino

INSPECTION COPY

1. Fill Pipe
2. Vent Pipe
3. Kind of Heat
4. Burner Rigidity & Supports
5. Name & Label
6. Stack Control
7. High Heat Content
8. Remote Gas
9. Piping Lines to In-Section
10. Valves in Supply Line
11. Capacity of Tanks
12. Tank Rigidity & Supports
13. Tank Distance
14. Oil Gauge
15. In-Section Card

NOTES

Petition No. 52/1715
 Location 146 Carlee St.
 Owner Joseph M. Davis
 Date of permit 6/06/52
 Approved 0-1852/June



FILL IN AND SIGN WITH INK

APPLICATION FOR PERMIT FOR HEATING, COOKING OR POWER EQUIPMENT

Portland, Maine, March 22, 1951

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location .. 166 Coyle Street .. Use of Building: .. No. Stories .. New Building
Name and address of owner of appliance Joseph Bove, 166 Coyle Street Existing "
Installer's name and address Holland Furnace Co., 7 Franklin Street, Searing Ave. Telephone 3-3803

General Description of Work

To install 2 forced warm air heating systems.

IF HEATER, OR POWER BOILER

Location of appliance or source of heat .. Type of floor beneath appliance ..
If wood, how protected? .. Kind of fuel ..
Minimum distance to wood or combustible material, from top of appliance or casing top of furnace ..
From top of smoke pipe .. From front of appliance .. From sides or back of appliance ..
Size of chimney flue .. Other connections to same flue ..
If gas fired, how vented? .. Rated maximum demand per hour ..

IF OIL BURNER

Name and type of burner .. Labelled by underwriters' laboratories? ..
Will operator be always in attendance? .. Does oil supply line feed from top or bottom of tank? ..
Type of floor beneath burner ..
Location of oil storage .. Number and capacity of tanks ..
If two 275-gallon tanks, will three-way valve be provided? ..
Will all tanks be more than five feet from any flame? .. How many tanks fire proofed? ..
Total capacity of any existing storage tanks for furnace burners ..

IF COOKING APPLIANCE

Location of appliance .. Kind of fuel .. Type of floor beneath appliance ..
If wood, how protected? ..
Minimum distance to wood or combustible material from top of appliance ..
From front of appliance .. From sides and back .. From top of smokepipe ..
Size of chimney flue .. Other connections to same flue ..
Is hood to be provided? .. If so, how vented? ..
If gas fired, how vented? .. Rated maximum demand per hour ..

MISCELLANEOUS EQUIPMENT OR SPECIAL INFORMATION

nothing having been heard about this yet in a long time. pls file in G.P.

WMA
6/25/53

Amount of fee enclosed? 2.50. (\$2.00 for one heater, etc., 50 cents additional for each additional heater, etc., in same building at same time.)

APPROVED:

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? .. yes ..

3-3803-4
Signature of Installer ..

Permit No.	217
Location	1000-11
Owner	1000-11
Date of Permit	1000-11
Approved	1000-11

10-15-1961 - Went over the
circulation - with Mr.
Harry Hird Holland
T. H. H. and the
-ing table in the
I expect to see
-expansion - in
- Monday, Oct 8, that
will fall into
that time in a

a near miss.
The officer-in-charge a
Quet, which had not
been covered, he was
asked by the installed
if everything was
all right, the last
time they were there.
He told me, that
he did not notice
this Quet; inserted
later:

101851 Int at France 1894

12/27/77 - ^{Print} See letter - 44

11-3-57 Mr. Langley of
Holland Ferry Co,
said Mr. Kirby was
not in the office ^{would be in later}
I told him a warm
oil duct running to
the second floor (unusual)
was not covered.
This duct is located
near the coal bin
and is on the side
toward the R.R. tracks.
I asked Mr. Trow
if he was satisfied
that this duct had
done all that we
could. He said, the
system was better
but, did not hat

LOCATION 101

DATE 11/11

PERMIT /

INQUIRY /

COMPLAINT /

11/11/11
Please see list
1. 14 to 1.2
1.2. 1.2 to 1.4
1.4 to 1.6

R.M.T.

Have they called?

If not, pls call
Mr. Kinn and get
some more info -
then carry on till
completed in
compliance with
law

Before a firming
for issued in call
from Bro and see
if he is satisfied
that we have done
him as well as
we could

11/11/11

12/13 I called Mr.
Nagy, and told
him a warm re-
sponse inasmuch
that first the
suggestion was caused
that I did not know
how much further
it would help.
J. P. Rind

AP 166 Coyle Street-I

December 18, 1951

Mr. Joseph Bove
166 Coyle Street
Holland Furnace Company
Attn: Mr. Kirby
7 Deering Avenue

Location: 166 Coyle Street
Installer: Holland Furnace Company

Gentlemen:

Further with relation to heating appliances installed at the above location without a permit having been secured from this department our inspector reports the following defects as compared with Building Code standards for safety and fire prevention, the Building Code containing no requirements as to the efficiency of such apparatus in heating the building:

One warm air duct still requires covering with 14-pound asbestos because it is concealed. This duct is located near the coal bin on the side of the cellar toward the railroad tracks and extends to second floor.

This department has no authority to give instructions directly to the installing company to enter into an owner's building and make any changes without owner's consent. According to the Building Code standards for safety, correction of these defects are necessary to safeguard the building and the occupants, and it is hoped that they may be corrected without delay. If the owner feels that the corrections should not be made, or if the owner does not understand the reason for the corrections, it is hoped that he will contact Inspector Thurlow of this office, so that the matter may be cleared up to his satisfaction. Mr. Thurlow may usually be reached by phone (4-1431, extension 234) week days other than Saturday between 4:00 and 4:30 P. M.

The installer should notify this office for another inspection when defects have been corrected. We shall appreciate a notice from the owner at that time as to whether or not he is satisfied with the work done.

Very truly yours,

Warren McDonald
Inspector of Buildings

WMCD/G

Approved: _____
Inspector



CITY OF PORTLAND, MAINE
DEPARTMENT OF BUILDING INSPECTION

COMPLAINT NO. C-51-10

COMPLAINT

INSPECTION COPY

Date Received 1/19/51

Location 166 Coyle Street

Use of Building Dwelling

Owner's name and address Joseph Anthony Fove, 166 Coyle Street

Telephone _____

Tenant's name and address _____

Telephone _____

Complainant's name and address Owner

Telephone _____

Description: 2 warm air furnaces installed in November 1950 by Holland Furnace Co.,
Daniel Haines, Mgr., without a building permit

1-23-51 Warm Air Duct - In up from
second floor the inside of the stair frame
connects to second floor. This warm air duct
is flush against wall - which is at first floor
level and is exposed up to the second floor
level. The duct - branching - at second
floor, the register - by at this level - is
not connected to the duct - it is not
connected to the main - duct - to second
floor - warm air duct from furnace varies
from 3" diameter to 10" diam. - 3" diam.
pipe clearance, an ill C.A. in both furnaces

Complaint No. C-51-10

3-23-51

Location 166 Coyle Street

Date Received 1/19/51

Date Disposed of

NOTES

Another set of four
this same window
was there - in place
of the old one in
second-floor front
into the window
from the floor, the
front - covered with
resistor in window
glass, as far as I
could tell
The set of four
was what I saw
at the time of the
one - floor front
window
A window on the
first floor - the
opening of the set
is about 3 inches from
the inside wall of front
set all of them is a
2" clearance from top

10211
by cigarette box
A window on
first floor
face to second
floor - set covered
with in place
against the wall
in place
Both cigarettes
used a very
careful inspection
Barn
9/13/51 Three cigarette
boxes - need to
be covered, shields
over window as noted
Could not determine
to what was covered
when it was to
second floor
A window on
first floor
opening of the set
is about 3 inches from
the inside wall of front
set all of them is a
2" clearance from top
9/13/51 (1) window
with the set
10. 2. 2. 2. 2.



(R) RESIDENCE ZONE - C

APPLICATION FOR PERMIT

Class of Building or Type of Structure Three Units

Portland, Maine, November 14, 1948

PERMIT ISSUED

NOV 29 1948

CITY of PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect alter repair demolish install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 100 W. 10th Street Within Fire Limits? no Dist. No. _____
Owner's name and address Austin T. Miller, 100 W. 10th Street Telephone _____
Lessee's name and address _____ Telephone _____
Contractor's name and address C. A. HESS, JR., 29 W. 22nd Street Telephone _____
Architect _____ Specifications _____ Plans _____ No. of sheets _____
Proposed use of building RES. CODE 1948B No. families 2
Last use _____ No. families 1
Material wood No. stories 2 1/2 Heat hot water Style of roof pitch Roofing _____
Other buildings on same lot Garage
Estimated cost \$ 75 Fee \$ 50

General Description of New Work

To close in existing archway between 1st floor and front wall in first story; to cut in one window in second story; and to change the building from one family to two families—one unit in first story, one unit in second story, and no living quarters whatever above second story.

Inasmuch as this building is now being changed to a 2-family dwelling with only one means of egress from third floor, the owner hereby states, in consideration of building permits now issued, that so far as he controls the building there will never be any part of third floor used for living quarters until such time as the means of egress therefrom shall have been made to comply with the Building Code for such a situation in a 2-family dwelling house; and that under no circumstances will any independent dwelling unit be established on third floor.

CERTIFICATE OF GUARANTEE
REQUIREMENT IS WAIVED

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. PERMIT TO BE ISSUED TO Austin T. Miller

Details of New Work

Is any plumbing involved in this work? _____ Is any electrical work involved in this work? _____
Height average grade to top of plate _____ Height average grade to highest point of roof _____
Ex. front _____ depth _____ No. stories _____ solid or filled land? _____ earth or rock? _____
Material of foundation _____ Thickness, top _____ bottom _____ cellar _____
Material of underpinning _____ Height _____ Thickness _____
Kind of roof _____ Rise: _____ foot _____ Roof covering _____
No. of chimneys _____ Material of chimneys _____ of lining _____ Kind of heat _____ fuel _____
Framing lumber—Kind _____ Dressed or full size? _____
Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____
Girders _____ Size _____ Columns under girders _____ Size _____ Max. on centers _____
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____ number commercial cars to be accommodated _____
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

APPROVED:

Miscellaneous

Will work require disturbing of any tree on a public street? no
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

INSPECTION COPY

Signature of owner _____

NOTES

6/10/49. *no inspection made*
22

Permit No. *48/2219*
 Location *166 Cagle Street*
 Owner *Quaker City Millen*
 Date of permit *11/29/48*
 Notif. closing-in _____
 Inspn. closing-in _____
 Final Notif. _____
 Final Inspn. _____
 Cert. of Occupancy issued *none*



APPLICATION FOR PERMIT

Class of Building or Type of Structure Third Class

Portland, Maine, June 28, 1928

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to ~~erect~~ alter install the following ~~building structure~~ equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 166 Coyle Street Ward 8 Within Fire Limits? No Dist. No. _____
Owner's or Lessee's name and address A. C. Bragg, 166 Coyle St. Telephone _____
Contractor's name and address Portland Stove Foundry Co., 59-61 Kennebec St. Telephone 6500
Architect's name and address _____
Proposed use of building Dwelling house No. families 1
Other buildings on same lot garage

Description of Present Building to be Altered

Material Wood No. stories 2 Heat hot water Style of roof _____ Roof g
Last use Dwelling house No. families 1

General Description of New Work

To install combination warm air and hot water furnace

CERTIFICATE OF OCCUPANCY
REQUIREMENT IS WAIVED
NOTIFICATION BEFORE LAYING
OR CLOSING-IN IS WAIVED

Details of New Work

Size, front _____ depth _____ No. stories _____ Height average grade to highest point of roof _____
To be erected on solid or filled land? _____ earth or _____
Material of foundation _____ Thickness, top _____ bottom _____
Material of underpinning _____ Height _____ Thickness _____
Kind of roof _____ Roof covering _____
No. of chimneys no Material of chimneys _____ of lining _____
Kind of heat warm air and hot water Type of fuel oil Distance, heater to chimney 5'
If oil burner, name and model _____
Capacity and location of oil tanks _____
Is gas fitting involved? _____ Size of service _____
Corner posts _____ Sill _____ Girt or ledger board? _____ Size _____
Material columns under girders _____ Size _____ Max. on centers _____
Studs (outside walls and carrying partitions) 2x4-16" O. C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.
Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____
Total number commercial cars to be accommodated _____
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no
Plans filed as part of this application? no No. sheets _____
Estimated cost \$ 400 Fee \$.75
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? Yes

INSPECTION COPY

Signature of owner A. C. Bragg
Portland Stove Foundry Co.


L. H. Cook

6877

Ward 8 Permit No. 28/1261
Location 166 Coyle St.
owner A. C. Bragg
Date of permit 6/28/28
Notif. closing-in
Inspn. closing-in
Final Notif.
Final Inspn. 7/25/28
Cert. of Occupancy issued

NOTES

Top of furnace close
to floor joists, but
heat chamber below
this.





APPLICATION FOR PERMIT

Class of Building or Type of Structure Third Class

Portland, Maine, June 21, 1928

PERMIT ISSUED
Permit No. 193

JUN 21 1928

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to ~~erect~~ alter install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 166 Coyle Street Ward B Within Fire Limits? No Dist. No. _____
Owner's or Lessee's name and address Mrs. Annie M. Bragg, 166 Coyle St. Telephone _____
Contractor's name and address Ballard Oil & Equipment Co., 124 High St. Telephone F 9072
Architect's name and address _____
Proposed use of building Dwelling house No. families 1
Other buildings on same lot Garage

Description of Present Building to be Altered

Material Wood No. stories 2 Heat Hot water & oil of roof _____ Roofing _____
Last use Dwelling house No. families 1

General Description of New Work

To install Oil Burner

CERTIFICATE OF DEPARTMENT OF
PLANNING & ZONING
NOTIFICATION BY MAIL
OR CLOSING IS NOT
NECESSARY

Details of New Work

Size, front _____ depth _____ No. stories _____ Height average grade to highest point of roof _____
To be erected on solid or filled land? _____ earth or rock? _____
Material of foundation _____ Thickness, top _____ bottom _____
Material of underpinning _____ Height _____ Thickness _____
Kind of roof _____ Roof covering _____
No. of chimneys no Material of chimneys _____ of lining _____
Kind of heat hot water and hot air Type of fuel oil Distance, heater to chimney 8'
If oil burner, name and model Super This burner labelled and approved by the Underwriters Lab. Inc
Capacity and location of oil tanks 1 275 gallon tank in basement 8' from heater
Is gas fitting involved? _____ Size of service _____
Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____
Material columns under girders _____ Size _____ Max. on centers _____
Studs (outside walls and carrying partitions) 2x4-16" O.C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.
Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____
Total number commercial cars to be accommodated _____
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no
Plans filed as part of this application? no No. sheets _____
Estimated cost \$450. Fee \$.75
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? Yes

INSPECTION COPY

Signature of owner Mrs. Annie M. Bragg
By Ballard Oil & Equipment Co.


By E.P. Hacker Vice-Pres.


6810

Ward 8 Permit No. 28/1193 M
Location 166 Croyle St.
Owner Mrs. Annie M. Biagg
Date of permit 6/21/28
Notif. closing-in
Inspn. closing-in
Final Notif.
Final Inspn.
Cert. of Occupancy issued

NOTES

11/15/30 - House is vacant
+ for sale. Unable to
get in. Vent & fl.
pipes on outside of house.
Rest of installation
probably O.K. - ags





(3d CLASS BUILDING)

Portland, Me., April 17th, 1926.

TO THE
INSPECTOR OF BUILDINGS:

The undersigned hereby applies for a permit to build, according to the following Specifications:—

Location. 100 Maple St. Wd. 8
Name of owner is? Elliott, C. B. Address, 100 Maple
Name of mechanic is? George Sears " 22 Cottage
Name of architect is? " "
Proposed occupancy of building (purpose)? Garage
If a dwelling or tenement house, for how many families? No.
Are there to be stores in lower story? No.
Size of lot, No. of feet front? ; No. of feet rear? ; No. of feet deep?
Size of building, No. of feet front? 15. ; No. of feet rear? 15. ; No. of feet deep? 21
No. of stories, front? 3. ; rear? one
No. of feet in height from the mean grade of street to the highest part of the roof?
Distance from lot lines, front? feet; side? 6 feet; side? 6 feet; rear? feet
Firestop to be used? 12 feet from any building except that of the owner.
Will the building be erected on solid or filled land?
Will the foundation be laid on earth, rock, or piles? on first floor
If on piles, No. of rows? distance on centres? length of?
Diameter, top of? diameter, bottom of?
Size of posts?
" girts?
" floor timbers? 1st floor, 2d, 3d, 4th.
O. C. " " " " " " " "
Span " " " " " " " "
Braces, how put in?
Building, how framed?
Material of foundation? thickness of? laid with mortar?
Underpinning, material of? height of? thickness of?
Will the roof be flat, pitch, mansard, or hip? Pitch Material of roofing? asphalt shingles
Will the building be heated by steam, furnaces, stoves or grates? Will the flues be lined?
Will the building conform to the requirements of the law?
No. of brick walls? and where placed?
Means of egress?

PERMIT MUST BE RECEIVED BEFORE BEGINNING WORK.

If the building is to be occupied as a Tenement House, give the following particulars:

What is the height of cellar or basement?.....

What will be the clear height of first story?..... second?..... thi: 1?.....

State what means of egress is to be provided?.....

.....Scuttle and stepladder to roof?.....

Estimated Cost,
\$..250

Signature of owner or authorized representative,

Address,

Plans submitted?.....no.....Received by?.....NES.....

