

Rocky Hill Light Corp.-----

July 4, 1942

Even if the plastered ceiling is installed I doubt if you can be assured of approval of a smoke hall license for the second floor hall. Under these circumstances I suggest that your representative confer with Mr. Fletcher about the matter and decide on a course of procedure. The permit for installation of the oven is invariable given to the actual installer, and the permit must bear the approval of the Health Officer before it is issued. Someone has filled out an application for the permit, but it has not been signed, the name of the installer has not been shown, full information structural and as regards fire protection has not been filled and the fee for the permit has not been paid.

Even after such a permit is issued it should be borne in mind that subsequent installations of fire-activated appliances will always have to take into account the occupancy of the second floor. In other words the issuance of the permit for this oven would not give the assurance that permits for installation of appliances such as frying kettles, etc., would be issued.

Very truly yours,

RicG/H

Inspector of Buildings

CC: Chief Sanborn

Fletcher Supreme Bakery  
156 Woodford St.

George E. Sears,  
22 Cottage St.

A. Edwin Smith  
City Clerk

Inquiry 156 Woodford St.

June 5, 1948

Mr. E. M. Fletcher,  
156 Woodford Street,  
Finsbury, Nine

Subject: Proposal to install gas-fired oven  
on 1st story of building at 156 Woodford Street

Dear Sir:

The important feature with regard to your inquiry from my stamping is the question of the Minor Assembly Hall (lodge hall) which is in the second story of the building, and whether or not this installation may have an adverse effect upon the safety of the persons using the hall.

It is not clear whether this is to be an additional oven or whether it is to take the place of one now existing there. Neither have you given information as to how much clearance there will be between the top of the oven and the ceiling, how this ceiling is insulated and so forth.

In regards requirements for strength there is not sufficient information with your inquiry to show precisely where the bearing points upon the floor will be with respect to the present framing of the floor, nor is there any indication of the present framing of the floor or how it will be strengthened if strengthening is necessary. You have given the approximate weight of the oven as 14,000 pounds. We shall assume unless otherwise advised that this 14,000 pounds represents the maximum weight when the oven charged, but will you tell us with information as to where the bearing points on the floor are to be and whether or not this load will be uniformly distributed to these bearing points. Do the radial 4-inch I-beams bear directly upon the floor surface or do the 2-inch angle irons bear on the floor? What is there in the nature of insulation in the bottom of the oven? Is there any air space between the bottom of the oven and the floor where circulation of any overheated air may take place out into the room? I note that you do have on the sketch some 1/16th inch iron sheets to hold the insulation in place so I presume there is insulation in the bottom of the oven. It still is necessary to show how far this will be above the floor, which, I presume has either a wooden surface or at least wooden framing, and about the circulatory air space beneath.

Apparently you understand that the application for installation of the bake oven which you have taken with you may only be signed by the actual installer. Upon examination of the application, partially filed out, I note that the bottom of the oven is apparently to be four inches above a wood floor. Is this four inch clearance from the 1/16th plates to the floor surface? And is there any way for this four inch space to be vented?

I note that the oven is to be vented to an 8x12 chimney flue to which a steam boiler is connected. The only steam boiler in the building, as I recollect it, is fairly close to Woodford Street. If this is still true, it seems to imply that the oven will be fairly close to the Woodford Street front, so please show clearly the location of the proposed oven with relation to the rest of the building. When a gas-fired appliance is to be connected to a chimney flue serving another heating appliance the question always comes up as to the possibility of unburned gas through some miscarriage being carried into the flue and ignited from the other appliance connected to the flue perhaps with disastrous results. This proposition ought to be explained also.

Mr. H. M. Fletcher

June 5, 1945

If this oven is proposed to be in addition to the existing oven (seems to do that is in the rear of the building), or if this oven is proposed to replace all existing ovens but is intended near the front of the building toward Woodlawn Street, there is a great deal of doubt in my mind if I can issue the permit for installation of it, in view of the place of public assemblego overhead.

The owners of the building are receiving a copy of this letter because it appears that they have a very definite interest in it.

Very truly yours,

McD/R

CC: George E. Sears,  
22 Cottage Street

Inspector of Buildings

Rocky Hill Lodge Corp.  
c/o Carl N. Maskell  
34 Hersey Street

June 14 - 1943


The oven which will be used is

# 144-56

on Page 10.

Weight of concrete block is not included in weight of  
oven, nor is weight of contents.

D. H. Darrow





FILL IN COMPLETELY AND SIGN WITH INK

PERMIT ISSUED

Permit No. 123

JUL 24 1933

COPY

## APPLICATION FOR PERMIT FOR HEATING, COOKING OR POWER EQUIPMENT

Portland, Maine,

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.  
The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location 156 Woodford Street Use of Building Restaurant and Hall No. Stories 2 New Building \_\_\_\_\_ Existing \_\_\_\_\_

Name and address of owner of appliance Master Supreme Bakery, 156 Woodford Street

Installer's name and address New England Bakery Equipment Exchange 14 Marshall St. Boston, Mass.

Charles E. Park, 20 St. Rose St., Somerville, Mass. Telephone Boston, Mass.

## General Description of Work

To install one fired bake oven

INSPECTION NOT COMPLETED

## IF HEATER, POWER BOILER OR COOKING DEVICE

Is appliance or source of heat to be in cellar? No If not, which story 1st Kind of Fuel gas

Material of supports of appliance (concrete floor or what kind) wood - 7" above floor

Minimum distance to wood or combustible material, from top of appliance or casing top of furnace, 210"

from top of smoke pipe 15" from front of appliance over 1' from sides or back of appliance 21"

Size of chimney flue 5" Other connections to same flue steam boiler

## IF OIL BURNER

Name and type of burner \_\_\_\_\_ Labeled and approved by Underwriters' Laboratories? \_\_\_\_\_

Will operator be always in attendance? \_\_\_\_\_ Type of oil feed (gravity or pressure) \_\_\_\_\_

Location oil storage \_\_\_\_\_ No. and capacity of tanks \_\_\_\_\_

Will all tanks be more than seven feet from any flame? \_\_\_\_\_ How many tanks fireproofed? \_\_\_\_\_

Amount of fee enclosed? .75 (\$1.00 for one heater, etc., 50 cents additional for each additional heater, etc., in same building at same time.) W2B- 500

INSPECTION COPY

*W. E. Baker, Sup'r of Oil & Gas*  
*Signature of Installer* *Wm. E. Baker, Sup'r of Oil & Gas*

Permit No. 43/703

Location 156 Woodland St.

Owner Fletcher's Supreme Bakery

Date of Permit 7/21/48.

Post Card sent \_\_\_\_\_

Notif. for inspn. \_\_\_\_\_

Approval Tag issued \_\_\_\_\_

Oil Burner Check List (date)

1. Kind of heat \_\_\_\_\_

2. Label \_\_\_\_\_

3. Anti-siphon \_\_\_\_\_

4. Oil storage \_\_\_\_\_

5. Tank Distance \_\_\_\_\_

6. Vent Pipe \_\_\_\_\_

7. Fill Pipe \_\_\_\_\_

8. Gauge \_\_\_\_\_

9. Rigidity \_\_\_\_\_

10. Feed safety \_\_\_\_\_

11. Pipe sizes and material \_\_\_\_\_

12. Control valve \_\_\_\_\_

13. Ash pit vent \_\_\_\_\_

14. Temp. or pressure safety \_\_\_\_\_

15. Instruction card \_\_\_\_\_

16. \_\_\_\_\_


NOTES

These plans (1 sheets) and the specifications accompanying the same, covering construction work on LONG CONTINUOUS,  
14. Two Fl., Fencage Bakery, 156 Woodford St., Portland,  
have been designed and drawn up by the undersigned according to the latest rules of engineering practice and to comply with the allowable working stresses, floor loads, etc. required by the Building Code of the City of Portland.

(Signature)

*M.O. Kitchins*

By  
(This statement is to be signed by the individual responsible for the design, and he should indicate in the blank provided the particular work to which the statement applies.)



CASE I: Beam considered 3 spans with end at (1) restrained from vertical movement.

Reactions: R1: -10,146  
R2: 24,650  
R3: 23,126  
R4: 640

Bending Moments:

M2: -36,378 foot lbs.  
M3: -47,701 "

Section Modulus required at (2) : 291  
" " (3) : 381.6  
" " for 8"x12" : 165.31  
" " 2-6"x12": 242.46  
" " 407.77

Reinforce existing 8"x 12" by adding a 6"x 12" to each side.

CASE II: Beam considered 2 spans with end 1-2 overhanging; and free to move vertically:

Reactions: R2: 13,074  
R3: 23,244  
R4: 1,939.

Bending Moments:  
M3: -35,805 foot lbs.

Section Modulus required: 286

Section Modulus for 8" x 12" : 165.31  
" " 2-4" x 12" : 159.80  
" " 325.11

Reinforce existing 8" x 12" by adding a 4" x 12" to each side

RECEIVED

JUL 19 1943

DEPT. OF BLDG. INS.  
CITY OF PORTLAND

		Original Permit No. 143/722
		Amendment No. 1 AUG 1945
<b>AMENDMENT TO APPLICATION FOR PERMIT</b>		
Portland, Maine, August 11, 1945		
<p>To the INSPECTOR OF BUILDINGS, PORTLAND, ME.</p> <p>The undersigned hereby applies for an amendment to Permit No. 143/722 pertaining to the building or structure comprised in the original application in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith, and the following specifications:</p>		
Location	153 Woodford Street	Within Fire Limits? <input checked="" type="checkbox"/> Yes Dist. No. 18
Owner's or lessor's name and address	Rocky Hill Lodge Corp.	
Contractor's name and address	Leavey Bros., 22 Cottage Street	
Plans filed as part of this Amendment		2-4227
Is any plumbing work involved in this work?		No. of Sheets
Increased cost of work		Is any electrical work involved in this work?
Framing Lumber: Kind?		Additional fee <input checked="" type="checkbox"/>
<p>Description of Proposed Work</p> <p>To remove section about 6' long of 6x12 girder on 12' span beneath existing girder nearest Woodford Street, supporting 2d floor of building. This 6x12 was put in at some previous date to allow the removal of a lost supporting 2d floor. It is now proposed to remove about half of this girder by putting in new 6x6 post up under existing girder with a 2x6 spiked to the side of it to support end of 6x12 remaining in place. There is an existing pipe column directly below location of this new post. The purpose of the removal of this section of girder is to provide head room for the passage to chimney of 12" diameter vent pipe from gas fired heat oven being installed.</p> <p><i>614 d by G.J.S.</i></p>		
<p>Approved:</p> <p><i>Rocky Hill Lodge Corp.</i></p> <p>Signature of Owner</p>		

Office of WADSWORTH & BOSTON - ARCHITECTS

57 Exchange Street • Portland, Maine

Philip Shirley Wadsworth, A. I. A.  
Royal Boston, A. I. A.

July 23, 1943

Mr. Warren MacDonald,  
Inspector of Buildings  
City Hall  
Portland, Maine

Dear Mr. MacDonald:


Mr. Sears called me this morning regarding the matter of the columns to be used to re-enforce the first floor of the Fletcher Bakery at 156 Woodfords Street, Portland, and told me that it is impossible to find new 4" pipe. I have investigated the matter and find that 3½" "Lally" columns are entirely adequate for the purpose and have so informed him.

We propose to re-enforce the beam on the 15' span which you mentioned in your letter of July 21 by installing a 9" channel weighing 13.4 pounds per lineal foot on each side of the existing 6" by 8" beam and bolting the channels together through the beam. These channels are adequate to take the load figured on the basis of the building code requirements without considering the wooden beam as bearing any portion of it. Mr. Sears will install a suitable cap on top of the existing column and a wall post to receive the ends of the channels adequately.

Very truly yours,

Philip Shirley Wadsworth

WADSWORTH & BOSTON



PSW:L

Report No. 75-945  
July 12, 1912

JULY 12, 1912

Pictocer Raynor Company  
153 Waterford Street,  
Portland, Maine

Subject: Installation of oven at 14 York and  
Street and alterations in the structure of the  
building to make way for the oven - H. to support  
the oven.

Gentlemen:

I am issuing the permit to install the oven to the installer and the building permit to cover alterations and strengthening of the building to George G. Fournier, builder. Please note the following in connection therewith:

1. From the figures that have been furnished me by Mr. Fletcher as to the clear headroom and the information from the oven manufacturer's catalogue left here, it seems apparent that there will be plenty of clearance (no less than 18 inches) from the top of the shell of the oven and the combustible material of the building above. The closest place will be the wooden beam, the supports of which have to be adjusted in order to make room for the oven. There is a question in my mind if the operating machinery of the oven which sits on top of it will clear the ceiling if all of the figures which have been given are correct. This is something for you and the installer to straighten out, of course, but if any further adjustment of the framing of the second floor is necessitated by this situation, we must have full details of it by way of a plan.
2. The clearance of the vent pipe from the oven to the chimney to the ceiling above it ought to be at least 15 inches.
3. The new pipe columns are not permitted to be second-hand pipe and are required to be anchored top and bottom. The new pipe columns under the built-up beam are apparently intended to be supported in the ceiling on new "H" columns. The best construction regarding that the columns in the first story go end and not in bearing on and be fastened to the "I" beams in the ceiling. If it is intended to rest the columns in the first story upon the existing wooden girders, it must be demonstrated that the reaction of the columns will not overload the roadway of the girder. Of course if the upper column goes down through and rests upon the lower one, the present girder must be cut and both ends at the break will have to get a good bearing upon the lower column and be anchored to it. If a number and the construction of the oven, there is a possibility that half of the load, approximately 12,000 pounds, might be concentrated upon the plate and slab under the center of the oven and would have to be supported wholly upon the new pipe column to be provided in the ceiling. It seems necessary to provide some type of slab or plate reinforcement large enough in area to be anchored to the top of the column so that this very substantial load would have a reasonable bearing area.
4. Since the post is to be removed from beneath second floor beam toward the rear from the oven and the present beam reinforced, the post supporting this reinforced beam will naturally have more load upon it than before and apparently is now and will be supported upon the lintel over the opening in the existing masonry wall in the ceiling. The strength of this lintel ought to be investigated to make sure it is strong enough; if not, it ought to be reinforced.

Fletcher Supreme Bakery

July 21, 1946

5. Both of the reinforced beams under the second floor will have an unusual width of bearing. Some satisfactory method will have to be worked out of transmitting the entire width and area of bearing from the built-up beams so that the new reinforcing beams will get suitable bearings as well as the existing beam.

6. It is understood that after the oven is installed, its vent pipe will be the only connection to the chimney flue to which it is connected, the existing stone outer lining having been removed.

Very truly yours,

18<sup>th</sup>

Wien/R

Inspector of Buildings



CC: Rocky Hill Lodge Corp.  
c/o Carl N. Haskell  
54 Hersey Street

George E. Sears,  
22 Cottage St.

Wadsworth & Boston  
57 Exchange Street

New England Bakery Equipment Exchange  
14 Marshall St., Boston

P.S. I am unable to check satisfactorily the strength of the reinforced beam to be provided on a span of about 15 feet where the post is to be removed toward the rear from the oven. I can find nothing on the plan which shows the size of the present beam. Mr. Sears, the builder, says that it is 6x8 but I do not know whether Douglas fir or spruce or what. Even figuring the existing 6x8 and the 2-6x12's to be added as Douglas fir the beam does not seem to figure out. I would like to have Wadsworth & Boston straighten this matter out before this post is removed and before the reinforcing beams are sent out there; also indicate how this beam is to get a good bearing on the wooden post since the 6x8 is shallower than the 6x12. It would be well at the same time to show that this post will adequately support over the opening below.



156-158 W 52nd St.

Office of WADSWORTH & BOSTON - ARCHITECTS

57 Exchange Street • Portland, Maine

Philip Shirley Wadsworth, A. I. A.  
Royal Boston, A. I. A.

July 19, 1943

Warren MacDonald  
Inspector of Buildings  
Portland, Maine

Dear Mr. MacDonald:

Accompanying this are revised drawings of the structural changes  
at the Fletcher Bakery on Woodfords Street, Portland.

Mr. W. O. Hutchins has gone over his figures and has tabulated them  
for you on the attached sheet. He has also included a statement  
of design covering the work which he did.

Mr. Hutchins discovered an error in his calculations which has  
made him change his suggestions on the work. He now plans to re-  
enforce the existing 8" x 12" fir girder with a 6" x 12" piece of  
fir, 24' long, on each side and bolted through as indicated on the  
drawing. The remainder of the work was done by us and I enclose  
a statement of design covering it.

Mr. Hutchins is absolutely sure that his figures are now correct  
and there will be no changes in design unless required by you.


Very truly yours,

*Philip Shirley Wadsworth*

WADSWORTH & BOSTON

PSW:L

Enclosures



*Office of* WADSWORTH & BOSTON · ARCHITECTS

57 Exchange Street · Portland, Maine

Philip Shirley Wadsworth, A. I. A.  
Royal Boston, A. I. A.

July 12, 1943

Mr. Warren MacDonald,  
Inspector of Buildings  
Portland, Maine

Dear Mr. MacDonald:

Accompanying this is a revised drawing of the basement of the Fletchers Bakery at 156 Woodfords Street in which I have incorporated the additional column supports suggested in my recent telephone conversation with you.

I believe this gives you the information which is required for the basement and the drawing which we made for the first floor would stand unless the girders were changed. Any such change would have to meet with your approval.


I have talked with Mr. Sears and I believe he has the matter well in mind and knows where he can get the necessary materials, and I believe he is prepared to start work immediately you give him the permit. Is there not information enough on this drawing so that a permit could be given with possible later revisions if another type of beam were used in the second story? I shall plan too for the drawing of the proposed built-up girder tomorrow.


Very truly yours,

*Philip Shirley Wadsworth*

WADSWORTH & BOSTON

PSW:L





post

new post


X = 4 eyebolts = 14 of these in bottom of oven  
O = 2  $\frac{3}{8}$  bolts each side  
of Vs which is 2 inch  
angle iron


Directly in the center  
is a 16" x 1/2" piece  
of boiler plate

S - 1/16" iron sheets for  
to hold the insulation

The approximate weight

~~16000 lbs~~ 11' dia if it is 14' dia - 14000 lbs





(G) GENERAL BUSINESS ZONE PERMIT ISSUED  
APPLICATION FOR PERMIT

Permit No. 600

Class of Building or Type of Structure Third Class JUL 26 1943

Portland, Maine, July 20, 1943

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect, alter or install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 156 Woodford Street

Within Fire Limits? Yes Dist. No. 1

Owner's or Lessee's name and address Rocky Hill Laine Corp. 156 Woodford Street Telephone

Lessee Fletcher's Supreme Bakery

Contractor's name and address Gen. F. Sears, 22 Cottage St. Telephone 3-9827

Architect

Plans filed yes No. of sheets

Proposed use of building Bakery and Lodge purposes

No. families

Other buildings on same lot

Estimated cost \$ 50 Fee \$ .50

## Description of Present Building to be Altered

Material wood No. stories 2 Heat steam Style of roof pitch Roofing asphalt

Last use Bakery and Lodge purposes No. families

## General Description of New Work

To reinforce first and second floors as per plan to provide for installation of new bake oven

To provide new vestibule 2'6" x 4' for existing men's toilet, 2x3 studs 16" O.C., sheathed both sides - doors to be at least 24" wide and made self-closing in such a way that there will be little chance of both doors being open at the same time.

## INSPECTION NOT COMPLETED

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor.

## Details of New Work

Is any plumbing work involved in this work?

Height average grade to top of plate

Is any electrical work involved in this work?

Size, front depth No. stories Height average grade to highest point of roof

To be erected on solid or filled land?

earth or rock?

Material of foundation Thickness, top bottom cellar

Material of underpinning Height Thickness

Kind of roof Rise per foot Roof covering

No. of chimneys Material of chimneys of lining

Kind of heat Type of fuel Is gas fitting involved?

Framing lumber Kind Dressed or full size?

Corner posts Sills Girt or ledger board? Size

Material columns under girders Size Max. on centers

Studs (outside walls and carrying partitions) 2x4-16" O. C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.

Joists and rafters 1st floor 2nd 3rd roof

On centers 1st floor 2nd 3rd roof

Maximum span 1st floor 2nd 3rd roof

If one story building with masonry walls, thickness of walls? height?

## If a Garage

No. cars now accommodated on same lot to be accommodated

Total number commercial cars to be accommodated

Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building?

## Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no

Will there be any connection with public water supply? no

Permit No. 43702

Location 156-158 Woodland St.  
Owner Rock Hill Bridge Corp.

Date of permit 7/21/43

Notif. closing-in

Inspn. closing-in

Final Notif.

Final Inspn.

Cert. of Occupancy issued

NOTES

8/9/43 - 12" concrete floor  
1. This entire structure  
will be 1st floor under  
basement. All exterior  
concrete walls will be  
beneath roof and floor  
and supporting 1st floor  
by means of columns along  
front. Floor joists of 1st  
floor will be 12" wide to  
be reinforced with wire  
to No. 416, 1/4" diameter  
reinforcing bars 4" apart  
at center line.


8 X 10' hard pine 1/4"

9' high

Post missing 1st story

more

10' Beam 5" flange



WRITTEN CONSENT AND AGREEMENT RELATING TO A CERTAIN SIGN PROPOSED TO BE  
ERECTED PROJECTING OVER A PUBLIC SIDEWALK FROM THE PREMISES

AT 156 Woodford Street IN PORTLAND, MAINE

Rocky Hill Lodge Corporation, being the owner of the premises at 156 Woodford Street in Portland, Maine hereby gives consent to the erection of a certain sign owned by Fletcher Bakery projecting over the public sidewalk from said premises as described in application to the Inspector of Buildings of Portland, Maine for a permit to cover erection of said sign;

And in consideration of the issuance of said permit Rocky Hill Lodge Corporation owner of said premises, in event said sign shall cease to serve the purpose for which it was erected or shall become dangerous and in event the owner of said sign shall fail to remove said sign or make it permanently safe in case the sign still serves the purpose for which it was erected, hereby agrees for himself or itself, for his heirs, its successors, and his or its assigns, to completely remove said sign within ten days of notice from said Inspector of Buildings that said sign is in such condition and of order from him to remove it.

In Witness whereof the owner of said premises has signed this consent and agreement this 7th day of January, 19 42.

Lawrence A. Hatch  
Witness

Rocky Hill Lodge Corpor  
Owner  
) Felix S. Bowie Pres.

*OK*

GENERAL BUSINESS PERMIT ISSUED  
ON NOV 1

**APPLICATION FOR PERMIT TO ERECT**

Report No. \_\_\_\_\_

**SIGN OVER PUBLIC SIDEWALK OR STREET**



Portland, Maine, January 16, 1942 19

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect the following described sign extending over a public sidewalk or street in accordance with the Building Code of the City of Portland, and the following specifications:

Location 156 Woodford Street Within Fire Limits? yes Dist. No. 1

Owner of building to which sign is to be attached Rocky Hill Lodge Corp.

Name and address of owner of sign Fletcher's Bakery, 156 Woodford St.

Contractor's name and address United Neon Display, 27 Montmont Sq. Telephone 2-0695

When does contractor's bond expire? January 1943

Information Concerning Building

No. stories 2 Material of wall to which sign is to be attached wood

Details of Sign and Connections

Electric? yes Vertical dimension after erection 25" Horizontal 519"

Weight 99 lbs. Will there be any hollow spaces? yes Any rigid frame? yes

Material of frame angle iron No. advertising faces 2 material galv. iron

No. rigid connections 2 Are they fastened directly to frame of sign? yes

No. through bolts none Size Location, top or bottom

No. guys 2 material angle iron cable Size 1x1x3/16 1"

Minimum clear height above sidewalk or street 1013"

Maximum projection into street 519"

United Neon Display

Fee \$ 1.00

CHARLES C. ROBERTS Signature of contractor By P.C. Roberts  
INSPECTION COPY

Permit No. 42) 61

Location 156 Woodland Sts

Owner Petchers Bakery

Date of permit 1/20/42

Sign, Contractor

Final Insp. 1/15/42

NOTES

Sticker  
Ready for inspection 1/15/42  
Shop door 1/20/42  
140 ft. of cable guy each  
side instead of single on  
one side. 100 ft.

TOE PLATE  
TELEPHONE  
CLERK

NO. 2000000000

1001



(3) GENERAL BUSINESS ZONE  
APPLICATION FOR PERMIT <sup>PERMIT ISSUED</sup>

Class of Building or Type of Structure Third Class

Portland, Maine, April 25, 1939

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect alter install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 156 Woodford Street Within Fire Limits? No Dist. No. \_\_\_\_\_

Owner's or Lessee's name and address Rocky Hill Lodge Corporation, 156 Woodford Street Telephone 3-9827

Contractor's name and address George E. Sears, 22 Cottage Street Telephone 3-9827

Architect \_\_\_\_\_ Plans filed \_\_\_\_\_ No. of sheets \_\_\_\_\_

Proposed use of building Stores & Lodge Hall No. families \_\_\_\_\_

Other buildings on same lot \_\_\_\_\_ Fee \$ .25

Estimated cost \$ 15.00 Description of Present Building to be Altered

Material Wood No. stories 2 Heat \_\_\_\_\_ Style of roof pitch Roofing \_\_\_\_\_

Last use Stores & Lodge Hall No. families \_\_\_\_\_

General Description of New Work  
To cut in one new window ( 20" x 30" - 4 lights ) in easterly wall first story in store.

Assume this window is more than 5 ft from property line, otherwise it should be a fire window.

CERTIFICATE OF OCCUPANCY  
REQUIRMENT IS WAIVED

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor.

Details of New Work: No

Size, front \_\_\_\_\_ depth \_\_\_\_\_ No. stories \_\_\_\_\_ Height average grade to top of plate \_\_\_\_\_

To be erected on solid or filled land? \_\_\_\_\_ earth or rock? \_\_\_\_\_

Material of foundation \_\_\_\_\_ Thickness, top \_\_\_\_\_ bottom \_\_\_\_\_ cellar \_\_\_\_\_

Material of underpinning \_\_\_\_\_ Height \_\_\_\_\_ Thickness \_\_\_\_\_

Kind of Roof \_\_\_\_\_ Rise per foot \_\_\_\_\_ Roof covering \_\_\_\_\_

No. of chimneys \_\_\_\_\_ Material of chimneys \_\_\_\_\_ of lining \_\_\_\_\_

Kind of heat \_\_\_\_\_ Type of fuel \_\_\_\_\_ Is gas fitting involved? \_\_\_\_\_

Framing Lumber Kind \_\_\_\_\_ Sills \_\_\_\_\_ Girt or ledger board? \_\_\_\_\_ Size \_\_\_\_\_

Corner posts \_\_\_\_\_ Sills \_\_\_\_\_ Girt or ledger board? \_\_\_\_\_ Size \_\_\_\_\_

Material columns under girders \_\_\_\_\_ Max. on centers \_\_\_\_\_

Tuds (outside walls and carrying partitions) 2x4-16" O. C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.

Joists and rafters 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_ roof \_\_\_\_\_

On centers: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_ roof \_\_\_\_\_

Maximum span: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_ roof \_\_\_\_\_

If one story building with masonry walls, thickness of walls? \_\_\_\_\_ height? \_\_\_\_\_

If a Garage \_\_\_\_\_ to be accommodated \_\_\_\_\_

No. cars now accommodated on same lot \_\_\_\_\_

Total number commercial cars to be accommodated \_\_\_\_\_

Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? \_\_\_\_\_

Miscellaneous \_\_\_\_\_

Will above work require removal or disturbing of any shade tree on a public street? \_\_\_\_\_ No \_\_\_\_\_

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? Yes \_\_\_\_\_

Signature of owner Rocky Hill Lodge Corporation

By George E. Sears

INSPECTION COPY

Permit No. 39/453

Location: 156 Woodland St.

Owner: Riviera Hill Edge

Date of permit: 4/25/39

Notif. closing-in:

Inspr. closing-in:

Final Notif.:

Final Inspr. 5/4/39

Cert. of Occupancy issued None

NOTES

5/4/39 - Work done - Agt



GENERAL BUSINESS ZONE PERMIT  
APPLICATION FOR PERMIT

Permit No.

0758

Class of Building or Type of Structure Third Class

MAY 24 1933

Portland, Maine, May 24, 1933

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect alter install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 158 Woodford Street Ward 8 Within Fire Limits? no Dist. No.

Owner's or Lessor's name and address Rocky Hill Lodge Corp. Telephone \_\_\_\_\_

Contractor's name and address Geo. E. Sears, 22 Cottage St. Telephone 3-2227

Architect \_\_\_\_\_ Plans filed \_\_\_\_\_ No. of sheets \_\_\_\_\_

Proposed use of building Store and Lodge No. families \_\_\_\_\_

Other buildings on same lot \_\_\_\_\_

Estimated cost \$40. Fee \$ .50

Description of Present Building to be Altered

Material wood No. stories 2 Heat Style of roof Roofing

Last use Store and Lodge No. families \_\_\_\_\_

General Description of New Work

To put in new partition (8x8 studs - sheathing) to provide storeroom in rear of bakery,  
first floor 12' to lot line  
to provide hood 6' x 6' over rear door

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor.

CERTIFICATE OF OCCUPANCY

REQUIREMENT IS WAIVED

Details of New Work

Height average grade to top of plate

Size, front depth No. stories Height average grade to highest point of roof

To be erected on solid or filled land? earth or rock?

Material of foundation hood 2x4 brackets Thickness, top bottom

Material of underpinning Height Thickness

Kind of Roof flat Rise per foot 1" Roof covering Asphalt roofing Class C Und. Lbs.

No. of chimneys Material of chimneys of lining

Kind of heat Type of fuel Is gas fitting involved?

Corner posts Sills Girt or ledger board? Size

Material columns under girders Size Max. on centers

Studs (outside walls and carrying partitions) 2x4-16" O. C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.

Joists and rafters: 1st floor 2nd 3rd roof 2x4

On centers: 1st floor 2nd 3rd roof 50"

Maximum span: 1st floor 2nd 3rd roof

If one story building with masonry walls, thickness of walls? height?

If a Garage

No. cars now accommodated on same lot to be accommodated

Total number commercial cars to be accommodated

Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building?

Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto

are observed? yes

Rocky Hill Lodge Corp.

Signature of owner

By *George L. Sears*

INSPECTION COPY

Ward 8 Permit No. 38758  
Location 158 Woodford St  
Owner Rockey Hill Bridgeling  
Date of permit 6/24/38  
Notif. closing-in  
Inspn. closing-in  
Final Notif.  
Final Inspn. 7/26/38  
Cert. of Occupancy issued None

NOTES

File: Rept. 9211B-1

May 31, 1937

Rocky Hill Lodge Corp.,  
158 Woodford Street,  
Portland, Maine.

Gentlemen:

We are issuing today to George A. Sears the permit covering repair after fire of your building at 158 Woodford Street, including strengthening of a portion of the second floor of the building.

After the new 6x12 girder is in place, I believe you will experience no further difficulty with the supports of the second floor.

I wish to correct any impression, however, that this second floor, because of the strengthening is capable of standing any load that may come upon it. As a matter of fact the line of 6x12 girders towards the rear of the building from the new 6x12 girders which you are putting in seems to be the weakest part of that part of the floor of which we have knowledge. These girders seem to figure out fair for a rated live load of slightly under 60 pounds per square foot, while the new 6x12 girders appear to figure to about 75 pounds per square foot. The existing 3x8 joists on the longest span appear to be good for about 65 pounds per square foot. The Building Code rating for a floor put to such use as this second floor is put, in new buildings is required to provide a strength of at least 100 pounds per square foot. I am giving you these figures in detail, not to disturb your organization in any way, but so that members will understand that even after the strengthening, the floor is substantially deficient in comparison with what would be required in the case of a new building for the same use.

Very truly yours,

Inspector of Buildings

RCD/H  
CC: George Sears  
158 Cottage St.

Rept. 92118-I

May 4, 1937

Rocky Hill Lodge Corporation,  
158 Woodford St.,  
Portland, Me.

Concluoon:

We are compelled to hold without issuing the building permit applied for in your name by George S. Sears, Contractor, to cover repairs to the building at 158 Woodford St. after the recent fire there, because of the structural condition of the second floor. The safety of this floor seems very questionable on account of conditions which apparently existed before the fire.

I am sorry that this department is unable to thoroughly investigate the strength of this floor, but it is doubtless evident to you why the city cannot stand the cost or assume the responsibility of such an investigation.

As stipulated by the Building Code, it is my duty to require that you have some competent person who can actually figure the strength of structures and materials, make a complete framing plan of both first and second floors of the building, figure the safe load per square foot indicated by the existing framing as shown on the plan, and indicate the method of strengthening, if strengthening seems necessary, as I am very sure the investigation will show. It is not necessary to show every member in the first story floor frame, but merely those which are essential to the support of the assembly hall.

As soon as the investigation is made and the data prepared, please submit both to this office for checking and approval. This report should also indicate whether the assembly hall floor is used for dancing or playing games or merely for quiet assembly. In the meantime it would be well to refrain from applying vibration or loads of impact to the second floor.

Very truly yours,

CC George S. Sears  
22 Cottage St.

(Signed) Warren McDonald  
Inspector of Buildings

K & P 13 Bay Floor Strengthening - Woodford 1st 9/1/37

Second Floor

$$3 \times 8 = 1.8" G.C. = 16' span \quad m = \frac{S I}{c} = \frac{W L}{\pi}, \quad W = \frac{8 \times 11.50}{\pi} \times \frac{I}{c} = \frac{733.3 \frac{1}{c}}{3}$$

$$\frac{11.50}{c} = \frac{16.0}{8}$$

$$W = 3 \times 8 \text{ on } 16' \text{ span} = \frac{733.3 \times 8^2}{3} = 14.66$$

$$\frac{244.4}{14.66} = 16.1 \frac{1}{4} / \text{sq ft} = \text{about } 16 \frac{1}{4} / \text{sq ft}$$

4

$$M.C. \quad 3 \times 8 \text{ on } 12' \text{ span}, \quad W = \frac{733 \times 8^2}{3} = 19.54.4, \quad \frac{325.7}{19.54.4} = 109.5 \text{ /sq ft}$$

$$6 \times 8 \text{ (present)}, 6 \times 6 \text{ (under) } \frac{I}{c} = 64 + 27.7 = 91.7$$

$$W = \frac{733 \times 48.3}{12^2} = 244 \times 12.3 = 44.65, \quad \frac{44.65}{91.7} = 27$$

$$\frac{244}{12.3} = 19.52$$

$$\frac{44.65}{27} = 1.63$$

$$1.63 + 1.63 = 4.86$$

$$6 \times 8 \text{ (F.S) on } 15' \text{ span good for } 6 \times 5.21 \frac{1}{2}$$

$$6 \times 6 \text{ (Dr)} = 64 + 27.7 = 91.7$$

$$W = \frac{733 \times 48.3}{15^2} = 244 \times 12.3 = 44.65, \quad \frac{44.65}{91.7} = 0.486$$

$$\frac{44.65}{0.486} = 91.7 \text{ /sq ft}$$

$$\frac{44.65}{91.7} = 0.486$$

$$1.63 + 0.486 = 2.116$$

$$1.63 + 0.486 = 2.116$$

$$1.63 + 0.486 = 2.116$$

$$1.63 + 0.486 = 2.116$$

$$1.63 + 0.486 = 2.116$$

$$1.63 + 0.486 = 2.116$$

$$1.63 + 0.486 = 2.116$$

$$1.63 + 0.486 = 2.116$$

$$1.63 + 0.486 = 2.116$$

$$1.63 + 0.486 = 2.116$$

$$1.63 + 0.486 = 2.116$$

$$1.63 + 0.486 = 2.116$$

$$1.63 + 0.486 = 2.116$$

$$1.63 + 0.486 = 2.116$$

$$1.63 + 0.486 = 2.116$$

$$1.63 + 0.486 = 2.116$$

$$1.63 + 0.486 = 2.116$$

$$1.63 + 0.486 = 2.116$$

$$1.63 + 0.486 = 2.116$$

$$1.63 + 0.486 = 2.116$$

$$1.63 + 0.486 = 2.116$$

$$1.63 + 0.486 = 2.116$$

$$1.63 + 0.486 = 2.116$$

$$1.63 + 0.486 = 2.116$$

$$1.63 + 0.486 = 2.116$$

$$1.63 + 0.486 = 2.116$$

*Held for  
main office  
file*

Rec. No. 8970-1

April 3, 1957

Rocky Hill Lodge Corp.,  
158 Woodford St.,  
Portland, Me. c/o George E. Sears, 22 Cottage St.

Gentlemen:

We are issuing to George E. Sears, today, a permit covering installation of a pair of doors at the head of the stairs in your building at 158 Woodford St. with the understanding that both doors are to have sufficient glass in them so that persons on either side of the doors may have a clear view of floor and stairs.

This arrangement is approved under the State Law by the Board of Fire Engineers as being adequate as a means of egress, but with the express stipulation that the Board is fearful that the closeness of the new doors to the top of the stairs may prove a cause of accident, which is probably outside of the jurisdiction of the Board.

Very truly yours,

APPROVED FOR BOARD OF FIRE  
ENGINEERS

Inspector of Buildings

Chief Engineer of Fire Dept.

GENERAL BUSINESS ZONE  
APPLICATION FOR PERMIT

Permit No. 1155623

0389

APR 5 1937



Class of Building or Type of Structure Third Class

Portland, Maine, March 29, 1937

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect alter install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 159 Woodford Street Ward 9 Within Fire Limits? no Dist. No.

Owner's or lessee's name and address Rocky Hill Lodge Corp., 158 Woodford St. Telephone

Contractor's name and address George Sears, 22 Cottage Street Telephone 3-2827

Architect's name and address \_\_\_\_\_

Proposed use of building Lodge Hall and mercantile No. families \_\_\_\_\_

Other buildings on same lot \_\_\_\_\_

Plans filed as part of this application? no No. of sheets \_\_\_\_\_

Estimated cost \$ 25. Fee \$ .25

Description of Present Building to be Altered

Material frame No. stories 2 Heat \_\_\_\_\_ Style of roof \_\_\_\_\_ Roofing \_\_\_\_\_  
Last use Lodge hall and mercantile No. families \_\_\_\_\_

General Description of New Work

To install double 2' doors at the head of the front stairs leading from the second story to a street swinging outwards and located so that there will be at least 2' between the new doors and the edge of the top riser on the stairs. These doors will be without locks that could prevent persons leaving the building through them at any time and ~~will~~ merely for the purpose of affording additional privacy to the lodge.

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor.

Details of New Work

Size, front \_\_\_\_\_ depth \_\_\_\_\_ No. stories \_\_\_\_\_ Height average grade to top of plate \_\_\_\_\_

To be erected on solid or filled land? \_\_\_\_\_ earth or rock? \_\_\_\_\_

Material of foundation \_\_\_\_\_ Thickness, top \_\_\_\_\_ bottom \_\_\_\_\_

Material of underpinning \_\_\_\_\_ Height \_\_\_\_\_ Thickness \_\_\_\_\_

Kind of Roof \_\_\_\_\_ Rise per foot \_\_\_\_\_ Roof covering \_\_\_\_\_

No. of chimneys \_\_\_\_\_ Material of chimneys \_\_\_\_\_ of lining \_\_\_\_\_

Kind of heat \_\_\_\_\_ Type of fuel \_\_\_\_\_ Is gas fitting involved? \_\_\_\_\_

Corner posts \_\_\_\_\_ Sills \_\_\_\_\_ Girt or ledger board? \_\_\_\_\_ Size \_\_\_\_\_

Material columns under girders \_\_\_\_\_ Size \_\_\_\_\_ Max. on centers \_\_\_\_\_

Studs (outside walls and carrying partitions) 2x4-16" O. C. Gird. - 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.

Joists and rafters 1st floor \_\_\_\_\_ 2nd \_\_\_\_\_ 3rd \_\_\_\_\_ roof \_\_\_\_\_

On centers: 1st floor \_\_\_\_\_ 2nd \_\_\_\_\_ 3rd \_\_\_\_\_ roof \_\_\_\_\_

Maximum span: 1st floor \_\_\_\_\_ 2nd \_\_\_\_\_ 3rd \_\_\_\_\_ roof \_\_\_\_\_

If one story building with masonry walls, thickness of walls? \_\_\_\_\_ height? \_\_\_\_\_

If a Garage

No. cars now accommodated on same lot \_\_\_\_\_ to be accommodated \_\_\_\_\_

Total number commercial cars to be accommodated \_\_\_\_\_

Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? \_\_\_\_\_

Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed?

*Rocky Hill Lodge Corp.*

*John T. Lawrence*

Signature of owner E.V.L.

INSPECTION COPY

CHIEF OF FIRE DEPT.

Ward 9 Permit No. 37/389

Location 158 Woodford St.

Owner Rocky Hill Lodge Corp

Date of permit 4/15/37

Notif. closing-in

Inspn. closing-in

Final Notif.

Final Inspn. 5/29/37

Cert. of Occupancy issued None

NOTES

5/29/37 - Work done  
ago

Permit No. \_\_\_\_\_

PERMIT ISSUED



APPLICATION FOR PERMIT

Class of Building or Type of Structure third

REC 24-133  
Portland, Maine, Dec. 21, 1958

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect alter install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location Reer 154 Woodfords St. Ward 9 Within Fire Limits? Y Dist. No. \_\_\_\_\_

Owner's or lessee's name and address Carroll Skillin and Allen Quimby 175 Aspinwall St. Telephone \_\_\_\_\_

Contractor's name and address L. Turner Woodfords St. Telephone \_\_\_\_\_

Architect's name and address \_\_\_\_\_

Proposed use of building \_\_\_\_\_ No. families \_\_\_\_\_

Other buildings on same lot mercantile and dwelling \_\_\_\_\_

Plans filed as part of this application? \_\_\_\_\_ No. of sheets \_\_\_\_\_

Estimated cost \$ \_\_\_\_\_ Fee \$ 1.00

Description of Present Building to be Altered

Material frame No. stories 2 Heat \_\_\_\_\_ Style of roof \_\_\_\_\_ Roofing \_\_\_\_\_

Last use garage and paint shop \_\_\_\_\_ No. families \_\_\_\_\_

General Description of New Work

To demolish 2 story frame building 20' x 25'

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor.

Details of New Work

Size, front \_\_\_\_\_ depth \_\_\_\_\_ Height average grade to top of plate \_\_\_\_\_

Size, front \_\_\_\_\_ depth \_\_\_\_\_ Height average grade to highest point of roof \_\_\_\_\_

To be erected on solid or filled land? \_\_\_\_\_ earth or rock? \_\_\_\_\_

Material of foundation \_\_\_\_\_ Thickness, top \_\_\_\_\_ bottom \_\_\_\_\_

Material of underpinning \_\_\_\_\_ Height \_\_\_\_\_ Thickness \_\_\_\_\_

Kind of Roof \_\_\_\_\_ Rise per foot \_\_\_\_\_ Roof covering \_\_\_\_\_

No. of chimneys \_\_\_\_\_ Material of chimneys \_\_\_\_\_ of lining \_\_\_\_\_

Kind of heat \_\_\_\_\_ Type of fuel \_\_\_\_\_ Is gas fitting involved? \_\_\_\_\_

Corner posts \_\_\_\_\_ Sills \_\_\_\_\_ Girt or ledger board? \_\_\_\_\_ Size \_\_\_\_\_

Material columns under girders \_\_\_\_\_ Size \_\_\_\_\_ Max. on centers \_\_\_\_\_

Studs (outside walls and carrying partitions) 2x4-16" O. C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.

Joists and rafters: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_

On centers: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_

Maximum span: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_

If one story building with masonry walls, thickness of walls? \_\_\_\_\_ height? \_\_\_\_\_

If a Garage

No. cars now accommodated on same lot \_\_\_\_\_ to be accommodated \_\_\_\_\_

Total number commercial cars to be accommodated \_\_\_\_\_

Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? \_\_\_\_\_

Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

Signature of owner Carroll R. Quimby

INSPECTION COPY

24963

Ward 8 Permit No. 3612173

Location Rec 154 Woodfalls St.

Owner Carroll, D. H. & Son  
Allen County

Date of permit Dec 21, 86

Notif. closing-in

Inspn. closing-in

Final Notif.

Final Inspn. Miller C. I. A.

Cert. of Occupancy issued None

NOTES

Permit No.	3612173	Issue Date	Dec 21, 86
Location	Rec 154 Woodfalls St.	Owner	Carroll, D. H. & Son Allen County
Date of permit	Dec 21, 86	Notif. closing-in	
Inspn. closing-in		Final Notif.	
Final Inspn.	MILLER C. I. A.	Cert. of Occupancy issued	None
NOTES			
<del>Permit No. 3612173 Issue Date Dec 21, 86 Location Rec 154 Woodfalls St. Owner Carroll, D. H. &amp; Son Allen County Date of permit Dec 21, 86 Notif. closing-in Inspn. closing-in Final Notif. Final Inspn. MILLER C. I. A. Cert. of Occupancy issued None NOTES</del>			

CITY OF PORTLAND, MAINE  
DEPARTMENT OF BUILDING INSPECTION

Record of Inquiry

Verbal in person  
By telephone

Date 4/8/36

Location 154 Woodford St

Made by C. A. Athrine - 170 Woodford St 2-6206

Inquiry-1 Can 2 story bldg. on rear, be used  
for painting of automobiles.

1 Directly rear  
19 1st ch. to S. Bentham (ring door) & L. P. Bentham, Painter  
19 25 new vacant  
19 26 entirely vacant  
19 27 property vacant

8 19 28 " " "

Answer-1 19 29 vacant

19 30 property vacant in rear

19 31 " " "

19 32 " " "

19 33 " " "


19 34 " " "

31 See letter 4/16/36 - m.s.

Reply by F.M.

HPI402

Deerling A-V.



N/00 off 5th St

Inquiry: 154 Woodford St.

April 16, 1936

Mr. C. N. Anthoine  
170 Woodford Street  
Portland, Maine

Dear Sir:

With reference to your inquiry concerning the legal right to use the building in the rear of 154 Woodford Street as a garage for painting automobiles, I have examined the building itself and have also ascertained the history of the use of the building as well as I can from the information at hand.

Apparently this portion of the building was used in 1924 by Charles H. Dickson & Son for cleaning rugs and by L. P. Leighton as a painter. I do not know whether Mr. Leighton used any part of the building for painting automobiles or not. As far as we can ascertain this part of the building was probably vacant at least through 1925 and 1926.

On the strength of this information it appears that that part of the building has no legal right to be used for the repair or painting of automobiles. Perhaps you can produce concrete evidence that the building does have a legal right to be used for that purpose. If so, I shall be glad to examine it.

The part of the building which you inquired about is not in good condition. The roof, particularly, is inadequately supported. Some person has seen fit to saw off the bottom part of what appears to have been roof trusses.

If the building could be used without alterations or the installation of heat which require a permit from this department, I doubt if we have sufficient information to require the tenants to move out, but unless I can secure additional information that would tend to show that the building has rights as a repair garage, I should not be able to give a permit for any alterations or addition or for any heating device in the building if that part of the building were so used.



FILL IN COMPLETELY AND SIGN WITH INK

PERMIT ISSUED  
Permit No. 0806

MAY 25, 1931

APPLICATION FOR PERMIT FOR HEATING, COOKING OR POWER EQUIPMENT

Portland, Maine, May 25, 1931

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location 156 Woodford Street Rear

Name and address of owner Supreme Baking Co. 156 Woodford St. Use of Building Bakery, upholstery, lodge purposes Ward 8

Contractor's name and address Carl N. Haskell Plumbing Co. 109 Center St Telephone F 8922 W

To install doughnut fryer - metal hood to be provided over same General Description of Work

NOTIFICATION BEFORE LATHING  
OR CLOSING-IN IS WAIVED

IF HEATER, POWER BOILER OR COOKING DEVICE  
Is heater or source of heat to be in cellar? no If not, which story 1st Kind of Fuel wood - metal covering  
Material of supports of heater or equipment (concrete floor or what kind) legs 2' high  
Minimum distance to wood or combustible material, from top of boiler or casing top of furnace, 6'  
from top of smoke pipe over 4' from front of heater from sides or back of heater sides over 4' air  
from front of heater rear wall insulated with metal 2" air space

Name and type of burner Approved by Underwriters' Laboratories? \_\_\_\_\_  
Location oil storage No. and capacity of tanks \_\_\_\_\_

Will all tanks be more than seven feet from any flame? 1.00 How many tanks fireproofed? \_\_\_\_\_  
amount of fee enclosed? (\$1.00 for one heater, etc., 50 cents additional for each additional heater, etc., in same  
building at same time.) Carl N. Haskell Plumbing Co.

ITION COPY

Signature of contractor

Carl N. Haskell

4902A

Ward 8 Permit No. 31/856

Location 56 Woodford St. Run

Owner Supreme Bakery

Date of permit 5/25/31

Notif. closing-in

Inspn. closing-in

Final Notif.

Final Inspn. 7/29/32

Cert. of Occupancy issued None

NOTES

6/8/31 - Hand not yet  
up - A.G.S.  
7/15/32 - Work - A.G.S.

C-31-42-I  
R-3/26/31

March 19, 1931.

Rocky Hill Lodge Corporation.  
C/o Mr. Carl N. Haskell  
34 Hersey Street  
Portland, Maine

Gentlemen:

Upon examination of the scene of a recent fire in your building at 156 Woodford Street, we find that the oven under which the fire occurred was improperly installed.

The brickwork of the oven extends with a solid wall to the floor of the room in which the oven is located, thus confining the heat that naturally travels downwards from the oven and setting fire to the wooden floor below.

It will be necessary for you to remove all of this brickwork up to the level of the bottom of the oven or ash box and to support the brickwork around the oven upon steel beams in such a manner that there will be at least four inches between the bottom of the beams and the floor to offer a free circulation of air underneath the oven and out into the room. The floor underneath the oven and extending at least two feet out in front of the fuel door and ash box should be covered with asbestos directly on the floor and sheet metal covering the asbestos.

A new oven has recently been installed in place of the old oven which stood in the same room for many years, and the smokepipe of this new oven is too close to be safe to the woodwork above it. A shield of asbestos lumber at least three times the diameter of this smokepipe and suspended halfway between the smokepipe and the woodwork above by means of incombustible hangers is required.

A permit to cover repair after fire is also required.

Please attend to these matters promptly.

Very truly yours,

Inspector of Buildings.

WM/HG



Permit No. 235

## APPLICATION FOR PERMIT PERMIT ISSUED

Class of Building or Type of Structure Third Class

Portland, Maine, November 1, 1926

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to ~~erect~~ alter ~~install~~ the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 158 Woodford Street Ward 8 Within Fire Limits? No Dist. No.

Owner's or Lessee's name and address Rocky Hill Lodge Corporation Telephone

Contractor's name and address Geo. E. Sears, 22 Cottage Street Telephone

Architect's name and address Telephone F 4567

Proposed use of building Mercantile No. families

Other buildings on same lot

## Description of Present Building to be Altered

Material Wood No. stories 2 Heat Style of roof Roofing

Last use Mercantile No. families

## General Description of New Work

To cut in one door on side of building, first floor (in alleyway)

To partition off toilet on first floor (window for ventilation)

(these changes are for bakery tenant)

NOTIFICATION BEFORE LATHING  
OR CLOSING-IN IS WAIVEDCERTIFICATE OF OCCUPANCY  
REQUIREMENT IS WAIVED

## Details of New Work

Size, front \_\_\_\_\_ depth \_\_\_\_\_ No. stories \_\_\_\_\_ Height average grade to highest point of roof \_\_\_\_\_

To be erected on solid or filled land? \_\_\_\_\_ earth or rock? \_\_\_\_\_

Material of foundation \_\_\_\_\_ Thickness, top \_\_\_\_\_ bottom \_\_\_\_\_

Material of underpinning \_\_\_\_\_ Height \_\_\_\_\_ Thickness \_\_\_\_\_

Kind of roof \_\_\_\_\_ Roof covering \_\_\_\_\_

No. of chimneys \_\_\_\_\_ Material of chimneys \_\_\_\_\_ of lining \_\_\_\_\_

Kind of heat \_\_\_\_\_ Type of fuel \_\_\_\_\_ Distance, heater to chimney \_\_\_\_\_

If oil burner, name and model \_\_\_\_\_

Capacity and location of oil tanks \_\_\_\_\_

Is gas fitting involved? \_\_\_\_\_ Size of service \_\_\_\_\_

Corner posts \_\_\_\_\_ Sills \_\_\_\_\_ Girt or ledger board? \_\_\_\_\_ Size \_\_\_\_\_

Material columns under girders \_\_\_\_\_ Size \_\_\_\_\_ Max. on centers \_\_\_\_\_

Tuds (outside walls and carrying partitions) 2x4-16" O.C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.

Joists and rafters: 1st floor \_\_\_\_\_ 2nd \_\_\_\_\_ 3rd \_\_\_\_\_ roof \_\_\_\_\_

On centers: 1st floor \_\_\_\_\_ 2nd \_\_\_\_\_ 3rd \_\_\_\_\_ roof \_\_\_\_\_

Maximum span: 1st floor \_\_\_\_\_ 2nd \_\_\_\_\_ 3rd \_\_\_\_\_ roof \_\_\_\_\_

One story building with masonry walls, thickness of walls? \_\_\_\_\_ height? \_\_\_\_\_

## If a Garage

Cars now accommodated on same lot \_\_\_\_\_ to be accommodated \_\_\_\_\_

Number commercial cars to be accommodated \_\_\_\_\_

Automobile repairing to be done other than minor repairs to cars habitually stored in the proposed building? \_\_\_\_\_

## Miscellaneous

Above work require removal or disturbing of any shade tree on a public street? No

Filed as part of this application? No No. sheets \_\_\_\_\_

Fee \$ .50

Will be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? Yes

Rocky Hill Lodge Corp.

ON COPY

Signature of owner

George E. Sears

99

Ward 8 Permit No. 289365

Location 158 Woodfords

Owner Ricky Hill Lodge

Date of permit 11/2/28

Notif. closing-in

Inspn: closing-in

Final Notif.

Final Inspn: 11/2/28

Cert. of Occupancy issued None

NOTES

11/2/28 - Final  
work all done  
before permit issued

**PERMIT ISSUED**

Permit No. 1612

AUG 14 1928

**APPLICATION FOR PERMIT**

Class of Building or Type of Structure Third Class

Portland, Maine, August 13, 1928



To the INSPECTOR OF BUILDINGS, POEZLAND, ME.

The undersigned hereby applies for a permit to erect alter install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 158 Woodford Street Ward 8 Within Fire Limits? No Dist. No. \_\_\_\_\_

Owner's or lessor's name and address Rocky Hill Lodge Corp. Telephone \_\_\_\_\_

Contractor's name and address Geo. E. Sears, 22 Cottage St. Telephone S 4568

Architect's name and address \_\_\_\_\_

Proposed use of building Mercantile Bldg. No. families \_\_\_\_\_

Other buildings on same lot \_\_\_\_\_

Description of Present Building to be Altered

Material Wood No. stories 2 Heat \_\_\_\_\_ Style of roof \_\_\_\_\_ Roofing \_\_\_\_\_

Last use Mercantile building No. families \_\_\_\_\_

General Description of New Work

To cut in small door in side of building on driveway

NOTIFICATION BEFORE  
OR CLOSING IN IS WAIVED.

To partition off room in rear of store

CERTIFICATE OF OCCUPANCY  
REQUIREMENT IS WAIVED.

Details of New Work

Size, front \_\_\_\_\_ depth \_\_\_\_\_ N. stories \_\_\_\_\_ Height average grade to highest point of roof \_\_\_\_\_  
To be erected on solid or filled land? \_\_\_\_\_ earth or rock? \_\_\_\_\_

Material of foundation \_\_\_\_\_ Thickness, top \_\_\_\_\_ bottom \_\_\_\_\_

Material of underpinning \_\_\_\_\_ Height \_\_\_\_\_ Thickness \_\_\_\_\_

Kind of roof \_\_\_\_\_ Roof covering \_\_\_\_\_

No. of chimneys \_\_\_\_\_ Material of chimneys \_\_\_\_\_ of lining \_\_\_\_\_

Kind of heat \_\_\_\_\_ Type of fuel \_\_\_\_\_ Distance, heater to chimney \_\_\_\_\_

If oil burner, name and model \_\_\_\_\_

Capacity and location of oil tanks \_\_\_\_\_

Is gas fitting involved? \_\_\_\_\_ Size of service \_\_\_\_\_

Corner posts \_\_\_\_\_ Sills \_\_\_\_\_ Girt or ledger board? \_\_\_\_\_ Size \_\_\_\_\_

Material columns under girders \_\_\_\_\_ Size \_\_\_\_\_ Max. on centers \_\_\_\_\_  
Studs (outside walls and carrying partitions) 2x4-16" O.C. Girders 6x8 or larger. Bridging in every floor and flat roof  
span over 8 feet. Sills and corner posts all one piece in cross section.

Joists and rafters: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_

On centers: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_

Maximum span: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_

one story building with masonry walls, thickness of walls? \_\_\_\_\_ height? \_\_\_\_\_

If a Garage

cars now accommodated on same lot \_\_\_\_\_ to be accommodated \_\_\_\_\_

number commercial cars to be accommodated \_\_\_\_\_

automobile, repairing be done other than minor repairs to cars habitually stored in the proposed building? \_\_\_\_\_

Miscellaneous

above work require removal or disturbing of any shade tree on a public street? No \_\_\_\_\_

filed as part of this application? No \_\_\_\_\_ No. sheets \_\_\_\_\_

Fee \$ .50

ited cost \$ .50

be in charge of the above work a person competent to see that the State and City requirements pertaining thereto

served? Yes \_\_\_\_\_

Rocky Hill Lodge Corp.

ITION COPY

Signature of owner

*Geo. E. Sears*

*7244*

Ward 8 Permit No. 281612  
Location 158 Woodland St.  
Owner Ricky Hill Lodge Corp  
Date of permit 8/14/28  
Notif. closing-in  
Inspu. closing-in  
Final Notif.  
Final Inspn.  
Cert. of Occupancy issued


NOTES



**City of Portland, Maine – Building or Use Permit Application** 389 Congress Street, 04101, Tel: (207) 874-8703, FAX: 874-8716

Location of Construction: 156 Woodford St	Owner: Dean Johnson	Phone:	Permit No <b>960279</b>
Owner Address:	Leasee/Buyer's Name: Reo Window Shade	Phone:	Business Name:
Contractor Name: Signature Signs	Address: P.O. Box 1023 Ptld, ME 04104	Phone:	<b>PERMIT ISSUED</b> Permit Issued: <b>APR 23 1996</b>
Past Use: Retail	Proposed Use: Same w/signage	COST OF WORK: \$ FIRE DEPT. <input type="checkbox"/> Approved <input type="checkbox"/> Denied	PERMIT FEE: \$ 39.40 INSPECTION: Use Group: Type: Signature: <i>[Signature]</i>
Proposed Project Description: Erect Signage (45" x 18')		PEDESTRIAN ACTIVITIES DISTRICT (P.A.D.) Action: <input checked="" type="checkbox"/> Approved <input type="checkbox"/> Approved with Conditions <input type="checkbox"/> Denied Signature: <i>[Signature]</i> Date: <i>18 April 1996</i>	
Permit Taken By: Mary Gresik	Date Applied For: 18 April 1996	Zoning Approval: Special Zone or Reviews: <input type="checkbox"/> Shoreland <input type="checkbox"/> Wetland <input type="checkbox"/> Flood Zone <input type="checkbox"/> Subdivision <input type="checkbox"/> Site Plan maj <input type="checkbox"/> minor <input type="checkbox"/> mm	
1. This permit application doesn't preclude the Applicant(s) from meeting applicable State and Federal rules. 2. Building permits do not include plumbing, septic or electrical work. 3. Building permits are void if work is not started within six (6) months of the date of issuance. False information may invalidate a building permit and stop all work..		Zoning Appeal: <input type="checkbox"/> Variance <input type="checkbox"/> Miscellaneous <input type="checkbox"/> Conditional Use <input type="checkbox"/> Interpretation <input type="checkbox"/> Approved <input type="checkbox"/> Denied	
		Historic Preservation <input type="checkbox"/> Not in District or Landmark <input checked="" type="checkbox"/> Does Not Require Review <input type="checkbox"/> Requires Review	
		Action: <input type="checkbox"/> Approved <input type="checkbox"/> Approved with Conditions <input type="checkbox"/> Denied Date: <i>18 April 1996</i>	
SIGNATURE OF APPLICANT <i>Keith Morin</i>	ADDRESS:	DATE: <i>18 April 1996</i>	PHONE: <i>893-2500</i>
RESPONSIBLE PERSON IN CHARGE OF WORK, TITLE		PHONE:	CEO DISTRICT <i>b</i> <i>A. Rowe</i>

White–Permit Desk Green–Assessor's Canary–D.P.W. Pink–Public File Ivory Card–Inspector



**City of Portland, Maine – Building or Use Permit Application** 389 Congress Street, 04101, Tel: (207) 874-8703, FAX: 874-8716

Location of Construction: 156 Woodford St	Owner: Dean Johnson	Phone:	Permit No. 960278
Owner Address:	Leasee/Buyer's Name: Red Window Shade	Phone:	BusinessName:
Contractor Name: Signature Signs	Address: P.O. Box 1023 Peld, ME 04104	Phone: 125-P-005	
Past Use: Retail	Proposed Use: Same w/signage	COST OF WORK: \$ PERMIT FEE: \$ 39.40	FIRE DEPT. <input type="checkbox"/> Approved <input type="checkbox"/> Denied
		INSPECTION: Use Group: Type: Signature:	
Proposed Project Description: Erect Signage (45" x 10')		PEDESTRIAN ACTIVITIES DISTRICT (P.A.D.) Action: Approved Approved with Conditions Denied Signature:	Date:
Permit Taken By: Mary Gresik	Date Applied For: 18 April 1996		

1. This permit application doesn't preclude the Applicant(s) from meeting applicable State and Federal rules.
2. Building permits do not include plumbing, septic or electrical work.
3. Building permits are void if work is not started within six (6) months of the date of issuance. False information may invalidate a building permit and stop all work..

**CERTIFICATION**  
I hereby certify that I am the owner of record of the named property, or that the proposed work is authorized by the owner of record and that I have been authorized by the owner to make this application as his authorized agent and I agree to conform to all applicable laws of this jurisdiction. In addition, if a permit for work described in the application issued, I certify that the code official's authorized representative shall have the authority to enter all areas covered by such permit at any reasonable hour to enforce the provisions of the code(s) applicable to such permit

SIGNATURE OF APPLICANT

ADDRESS:

DATE:

PHONE:

RESPONSIBLE PERSON IN CHARGE OF WORK, TITLE

PHONE:

White-Permit Desk Green-Assessor's Canary-D.P.W. Pink-Public File Ivory Card-Inspector

**PERMIT ISSUED**

Permit Issued:  
APR 23 1996

**CITY OF PORTLAND**

Zone: B2 CBL: 125-P-005

Zoning Approval:

Special Zone or Review:  
 Shoreland  
 Wetland  
 Flood Zone  
 Subdivision  
 Site Plan major  minor  mm

**Zoning Appeal**

Variance  
 Miscellaneous  
 Conditional Use  
 Interpretation  
 Approved  
 Denied

**Historic Preservation**  
 Not in District or Landmark  
 Does Not Require Review  
 Requires Review

Action:

Approved  
 Approved with Conditions  
 Denied

Date:

**CEO DISTRICT**

N. K. 6

COMMENTS

7/29/95

Completed

AC

N

Inspection Record

Type

Date

Foundation: \_\_\_\_\_

Framing: \_\_\_\_\_

Plumbing: \_\_\_\_\_

Final: \_\_\_\_\_

Other: \_\_\_\_\_

Inspection Services  
P. Samuel Hoffses  
Chief



Planning and Urban Development  
Joseph E. Gray Jr.  
Director

## CITY OF PORTLAND

April 22, 1996

Signature Signs  
P. O. Box 1023  
Portland, Maine 04104

RE: 156 Woodford Street

Dear Sir,

Your application to erect two signs has been reviewed and a permit is herewith issued subject to the requirements listed below. This permit does not excuse the applicant from meeting applicable State and Federal laws.

1. This permit is being issued with the understanding that you supply this office a detail of how the signs will be attached to the building before work begins.
2. As previously requested by Ms. Schmuckal, this office must be supplied with the building frontage before work begins.

If you have any questions regarding these requirements, please do not hesitate to contact this office.

Sincerely,

A handwritten signature in black ink, appearing to read "P. Samuel Hoffses".

P. Samuel Hoffses  
Chief, Code Enforcement Division

cc: M. Schmuckal, Asst C, Code Enf Div

SIGNAGE

PLEASE ANSWER ALL QUESTIONS

ADDRESS: 156 Woodford St. Portland, Me. ZONE: B-2

OWNER: Red Window Shd

APPLICANT: Signature Signs

ASSESSOR NO.: \_\_\_\_\_

SINGLE TENANT LOT? YES  NO \_\_\_\_\_

MULTI TENANT LOT? YES \_\_\_\_\_ NO

FREESTANDING SIGN? YES \_\_\_\_\_ NO  DIMENSIONS 3.25' x 18' = 67.5'  
x 2  
(ex. pole sign..)

MORE THAN ONE SIGN? YES  NO \_\_\_\_\_ DIMENSIONS 45" x 18"

BLDG. WALL SIGN? YES  NO \_\_\_\_\_ DIMENSIONS 45" x 18"  
(attached to bldg)

MORE THAN ONE SIGN? YES  NO \_\_\_\_\_ DIMENSIONS 45" x 18"

LIST ALL EXISTING SIGNAGE AND THEIR DIMENSIONS: NO Signs @ Site

NAME LOT FRONTAGE (FEET)

→ BLDG FRONTAGE (FEET)

AWNING YES  NO  IS AWNING BACKLIT? YES  NO


HEIGHT OF AWNING: \_\_\_\_\_

IS THERE ANY COMMUNICATION, MESSAGE, TRADEMARK OR SYMBOL ON IT? \_\_\_\_\_

A SITE SKETCH AND BUILDING SKETCH SHOWING EXACTLY WHERE EXISTING AND NEW

SIGNAGE IS LOCATED MUST BE PROVIDED. SKETCHES AND/OR PICTURES OF THE

PROPOSED SIGNS ARE ALSO REQUIRED.



### INFORMATION REQUIREMENTS FOR SIGN PERMIT APPLICATION

APPLICANTS FOR A SIGN PERMIT WILL BE ASKED TO SUBMIT THE FOLLOWING INFORMATION TO THE CODE ENFORCEMENT OFFICE:

1. PROOF OF INSURANCE
2. LETTER OF PERMISSION FROM THE OWNER
3. A SKETCH PLAN OF THE LOT, INDICATING LOCATION OF BUILDINGS, DRIVEWAYS AND ANY ABUTTING STREETS OR RIGHT OF WAYS. LENGTHS OF BUILDING FRONTAGES AND STREET FRONTAGES SHOULD BE NOTED (SEE ATTACHED)
4. INDICATE ON THE PLAN ALL EXISTING AND PROPOSED SIGNS
5. COMPUTATION OF THE FOLLOWING:
  - A) SIGN AREA OF EACH EXISTING AND PROPOSED BUILDING SIGN
  - B) SIGN AREA HEIGHT AND SETBACK OF EACH EXISTING AND PROPOSED FREESTANDING SIGN

A SKETCH OF ANY PROPOSED SIGN(S), INDICATING DIMENSIONS, MATERIALS, SOURCE OF ILLUMINATION AND CONSTRUCTION METHOD (SEE ATTACHED)

FEE FOR PERMIT - \$25.00 PLUS \$.20 PER SQUARE FOOT

NOTE: ONCE A SKETCH PLAN HAS BEEN FILED FOR A PROPERTY, THE CODE ENFORCEMENT OFFICE WILL KEEP A RECORD OF THE PLAN SO THAT A NEW SKETCH PLAN WILL NOT BE REQUIRED FOR LATER CHANGES TO SIGNAGE ON THE PROPERTY. IN SUCH AN INSTANCE, APPLICANTS WILL ONLY BE REQUIRED TO SUBMIT INFORMATION APPLICABLE TO THE NEW SIGNS.


04/09/96

13:47

C.M. BOWKER COMP.

Page 1 of 1

ACORD® CERTIFICATE OF INSURANCE				ISSUE DATE (MM/DD/YY)		
PROPOSER				04/09/96		
C.M. Bowker Co. 835 Forest Avenue Portland ME 04103				THIS CERTIFICATE IS ISSUED AS A MATTER OF INFORMATION ONLY AND CONFERNS NO RIGHTS UPON THE CERTIFICATE HOLDER. THIS CERTIFICATE DOES NOT AMEND, EXTEND OR ALTER THE COVERAGE AFFORDED BY THE POLICIES BELOW.		
INSURED		COMPANIES AFFORDING COVERAGE				
Reo Window Shade Co 156 Woodford Street Portland ME 04103		COMPANY LETTER A	Maryland Casualty Co.			
		COMPANY LETTER B	Maine Employers Mutual			
		COMPANY LETTER C	Commercial Union			
		COMPANY LETTER D				
		COMPANY LETTER E				
<p>STATEMENT</p> <p>THIS IS TO CERTIFY THAT THE POLICIES OF INSURANCE LISTED BELOW HAVE BEEN ISSUED TO THE INSURED NAMED ABOVE FOR THE POLICY PERIOD INDICATED, NOTWITHSTANDING ANY REQUIREMENT, TERM OR CONDITION OF ANY CONTRACT OR OTHER DOCUMENT WITH RESPECT TO WHICH THIS CERTIFICATE MAY BE ISSUED OR MAY PERTAIN, THE INSURANCE AFFORDED BY THE POLICIES DESCRIBED HEREIN IS SUBJECT TO ALL THE TERMS, EXCLUSIONS AND CONDITIONS OF SUCH POLICIES. LIMITS SHOWN MAY HAVE BEEN REDUCED BY PAID CLAIMS.</p>						
CO LTR	TYPE OF INSURANCE	POLICY NUMBER	POLICY EFFECTIVE DATE (MM/DD/YY)	POLICY EXPIRATION DATE (MM/DD/YY)	LIMITS	
					GENERAL AGGREGATE	\$ 2,000,000.
C	GENERAL LIABILITY <input checked="" type="checkbox"/> COMMERCIAL GENERAL LIABILITY <input checked="" type="checkbox"/> CLAIMS MADE <input checked="" type="checkbox"/> OCCUR. <input checked="" type="checkbox"/> OWNERS & CONTRACTORS PROT.	CNR 130681	07/28/95	07/28/96	PRODUCTS-COMP/OP AGG.	\$ 2,000,000.
A	AUTOMOBILE LIABILITY <input checked="" type="checkbox"/> ANY AUTO <input checked="" type="checkbox"/> ALL OWNED AUTOS <input checked="" type="checkbox"/> SCHEDULED AUTOS <input checked="" type="checkbox"/> Hired Autos <input checked="" type="checkbox"/> NON-OWNED AUTOS <input checked="" type="checkbox"/> GARAGE LIABILITY <input checked="" type="checkbox"/> EXCESS LIABILITY <input checked="" type="checkbox"/> UMBRELLA FORM <input checked="" type="checkbox"/> OTHER THAN UMBRELLA FORM <input checked="" type="checkbox"/> WORKERS COMPENSATION <input checked="" type="checkbox"/> AND <input checked="" type="checkbox"/> EMPLOYERS' LIABILITY <input checked="" type="checkbox"/> OTHER	ECA26580725	11/14/95	11/14/96	PERSONAL & ADV. INJURY	\$ 1,000,000.
B		18 10007027	04/18/95	04/18/96	EACH OCCURRENCE	\$ 1,000,000.
					FIRE DAMAGE (Any one fire)	\$ 50,000.
					MED. EXPENSE (Any one person)	\$ 5,000.
					COMBINED SINGLE LIMIT	\$ 100000
					BODILY INJURY (Per person)	\$
					BODILY INJURY (Per accident)	\$
					PROPERTY DAMAGE	\$
					EACH OCCURRENCE	\$
					AGGREGATE	\$
					STATUTORY LIMITS	
					EACH ACCIDENT	\$ 100000
					DISEASE - POLICY LIMIT	\$ 500000
					DISEASE - EACH EMPLOYEE	\$ 100000
<p>DESCRIPTION OF OPERATIONS/LOCATIONS/VEHICLES/SPECIAL ITEMS AS RESPECTS VERIFICATION OF INSURANCE COVERAGE</p>						
CERTIFICATE NO.		CANCELLATION				
SIGNATURE SIGNS PO BOX 1023 PORTLAND ME 04104		SHOULD ANY OF THE ABOVE DESCRIBED POLICIES BE CANCELLED BEFORE THE EXPIRATION DATE THEREOF, THE ISSUING COMPANY WILL ENDEAVOR TO MAIL <u>10</u> DAYS WRITTEN NOTICE TO THE CERTIFICATE HOLDER NAMED TO THE LEFT, BUT FAILURE TO MAIL SUCH NOTICE SHALL IMPOSE NO OBLIGATION OR LIABILITY OF ANY KIND UPON THE COMPANY, ITS AGENTS OR REPRESENTATIVES.				
		AUTHORIZED REPRESENTATIVE				
		KAREN PETERSON				



12" Letter

18"

Gold Letters  
on Green

45"

Black Aluminum Border

White Panel  
Green Letters

7-1/2" Letter

