CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date
KOW INVESTMENTS LLC		Suzanne Hunt	10/2/2006
Locatation	CBL	Status	Inspection Type
615 FOREST AVE	125 N003001	Re-Inspect 30 Days	Complaint-Inspection

	Code	Int/Ext	Floor	Unit No.	Area	Compliance Date
1)	6-116.5 Violation: Notes:	Interior Fire Protection no smoke detectors	3	3	Various loca	tions
2)	6-108.2 Violation: Notes:	Interior Interior floors, walls, ceilings and doors hole in wall, stairway	1		Hallway	11/06/2006
3)	6-108.2 Violation: Notes:	Interior Interior floors, walls, ceilings and doors ceiling and wall in dis repair	3	3	Kitchen	
4)	6-108.2 Violation: Notes:	Interior Interior floors, walls, ceilings and doors ceiling tiles are missing	1	back	Bathroom	11/06/2006
5)	6-108.2 Violation: Notes:	Interior Interior floors, walls, ceilings and doors missing screens	3	3	Various loca	tions
6)	6-108.4 Violation: Notes:	Interior Stairways, stairwells, stairs, porches. broken hand rail back stairs egress		3	Stairways	11/06/2006
7)	6-108.4 Violation: Notes:	Interior Stairways, stairwells, stairs, porches. missing light bulbs in egress	all	all	Stairways	11/06/2006
8)	6-108.3 Violation: Notes:	Exterior Exterior windows, doors and skylights missing screen door first floor back	1		doorway	
9)	6-109.4 Violation: Notes:	Exterior Disposal of rubbish, garbage and waste. no weather tight trash cans supplied for te	nants	all		11/06/2006
10)	105.1 Violation: Notes:	Building w/o Permit permit required to change use of building				

CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager KOW INVESTMENTS LLC		Inspector	Inspection Date 10/2/2006	
		Suzanne Hunt		
Locatation	CBL	Status	Inspection Type	
615 FOREST AVE	125 N003001	Re-Inspect 30 Days	Complaint-Inspection	

11) 6-108.4 Interior 3 Stairways 11/06/2006

Violation: Stairways, stairwells, stairs, porches.

Notes: broken step back stairs egress

Comments: