CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

June 19, 2017

Responsible Party 1:				
R & G REALTY LLC				
542 FOREST AVE				
PORTLAND, ME 04101				
Location	CBL	Inspection Date		
Location 542 FOREST AVE	CBL 126 B020001	Inspection Date 5/26/2017		
		•		

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 7/15/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 101- 7.5.1.1 AND 7.5.1.1.1 OBSTRUCTED EGRESS ; Exits shall be located and exit access shall be arranged so that exits are readily accesible at all times (7.5.1.1). Where exits are not immediately accessible from an open floor area, continuous passageways, aisles, or corridors leading directly to every exit shall be maintained and shall be arranged to provide access for each occupant to not less than two exits by separate ways of travel, unless otherwise provided in 7.5.1.1.3 and 7.5.1.1.4 (7.5.1.1.1). Excessive cardboard waste in storeroom.	//
1-4.5.8 MAINTENANCE, INSPECTION, AND TESTING; WHENEVER OR WHEREVER ANY DEVICE, EQUIPMENT, SYSTEM, CONDITION, ARRANGEMENT, LEVEL OF PROTECTION, FIRE-RESISTIVE CONSTRUCTION, OR ANY OTHER FEATURE IS REQUIRED FOR COMPLIANCE WITH THE PROVISIONS OF THIS CODE, SUCH DEVICE, EQUIPMENT, SYSTEM, CONDITION, ARRANGEMENT, LEVEL OF PROTECTION, FIRE-RESISTIVE CONSTRUCTION, OR OTHER FEATURE SHALL THEREAFTER BE CONTINUOUSLY MAINTAINED. Emergency lighting in need or repair in storeroom.	//
NFPA 54- 9.6.4 UTILITY DISCONNECTS BLOCKED; Each appliance connected to a piping system shall have an accessible, approved manual shutoff valve with a nondisplaceable valve member, or a listed gas convenience outlet. Appliance shutoff valves and convenience outlets shall serve a single appliance only and shall be installed in accordance with 9.6.4.1. Racks in in front of electrical panels	//
NFPA 1- 19.1.2 INSIDE STORAGE NOT ORDERLY; Persons owning or having control of any property shall not allow any combustible waste material to accumulate in any area or in any manner that creates a fire hazard to life or property. Possible violation of CO2 cylinders stored without chains or racks.	//

Violation		Proposed Date of Completion
shall be connected to an equip grounding conductor and othe personnel. Lamp tie wires, mo least 38 mm from lamp termin	XPOSED LIVE ELECTRICAL WIRES; Exposed metal parts oment grounding conductor or insulated from the equipment or conducting surfaces or be inaccessible to unqualified unting screws, clips, and decorative bands on glass spaced at als shall not be required to be grounded. If at door way from storeroom to show room.	
FINAL DATE OF COMPLETE	ED VIOLATION(S)	//
FIRE PREVENTION BUREAU	J RE-INSPECTION OF COMPLETED VIOLATION(S)	//
_	nt to reject or modify any proposed plan of action, and may nical capacity to complete the proposed plan. Please contact TION	-
understand that I must conto	ions listed within the timeframes provided. If I require add act the Fire Prevention Bureau <u>prior to the deadline</u> to req a's discretion to grant or deny.	
· ·	is my responsibility to schedule a reinspection of my prope o. My failure to schedule a reinspection shall be deemed an nedied.	•
2 - 7	agreement, I understand that I am liable for penalties pursues $\S\S$ 1-15 and 10-25, and 30-A M.R.S. \S 4452 and may be	• •
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	