

Erik Selbeg
Service Master Elite
14 Willey Rd
Saco, ME, 04072

Michael Welch
33 Clifton St.
Portland, ME, 04101

Kitchen

- Removal of soffit against affected wall
- Removal of 40ft of drywall around entrance
- Removal of 1/3 of ceilings
- Removal of baseboard and crown around doorway
- Removal of toe kicks

Dining Room

- Walls adjacent to the hallway
- Partial walls connected to kitchen
- Removal of Insulation
- Removal of Crown Molding
- Removal of affected baseboard
- Attempt to save the trim