

Erik Selbeg  
Service Master Elite  
14 Willey Rd  
Saco, ME, 04072

Michael Welch  
33 Clifton St.  
Portland, ME, 04101

## Fire Loss Scope of Work

### Level 2, Apartment 35

#### Hallway

- Removal of ceiling 14x3'6
- Removal of walls, 162 SF
- Removal of baseboards
- Removal of crown molding
- Removal of Insulation
- cut around Trim
- Shellac of exposed stud walls/ceiling joists/sub flooring

#### Bedroom One

- Removal of Ceiling
- Removal of 1/2 of walls
- Removal of carpet
- Removal of Underlayment
- Removal of baseboards
- Removal of 1/2 crown
- Removal of Insulation
- Cut around Trim
- Shellac of exposed stud walls/ceiling joists/sub flooring

#### Bathroom

- Removal of Bathtub and surround
- Detach of Vanity
- Detach of Toilet
- Removal of all walls
- Removal of all flooring
- Removal of all insulation
- Save old trim if possible.
- Removal of baseboards
- Removal of Crown
- Shellac of exposed stud walls/ceiling joists/sub flooring