

Erik Selbeg  
Service Master Elite  
14 Willey Rd  
Saco, ME, 04072

Michael Welch  
33 Clifton St.  
Portland, ME, 04101

## Fire Loss Scope of Work

### Level 3, Apartment 35

#### Bathroom

- Full gut of Walls and insulation
- Remove Toilet
- Remove Tub and surround
- Remove Vanity
- Remove flooring
- Remove Debris
- Shellac of exposed stud walls/ceiling joists/sub flooring

#### Upper Hallway

- Removal of ceiling
- Removal of 1/2 the walls (affected)
- Removal of carpet
- Removal of baseboards
- Removal of crown
- Removal of insulation
- Save trim if possible
- Shellac of exposed stud walls/ceiling joists/sub flooring

#### Bedroom Three

- Removal of Ceiling
- Removal 1/2 the walls (affected)
- Removal of insulation
- Removal of Carpet
- Removal of debris
- Demo Closet
- Shellac of exposed stud walls/ceiling joists/sub flooring