

Erik Selbeg
Service Master Elite
14 Willey Rd
Saco, ME, 04072

Michael Welch
33 Clifton St.
Portland, ME, 04101

Fire Loss Scope of Work

Main Level, Apartment 33

33 Bedroom Two

- Remove Ceiling
- Remove 1/2 of the walls
- Remove Insulation
- Remove Crown Molding
- Remove baseboard
- Cut around Trim on doors and windows.

33 Bathroom

- Remove crown
- Remove Ceiling
- Remove 1/2 of the walls
- Remove Insulation

33 Bedroom

- Removal of 3*3ft section of Wall/Ceiling.
- Removal of Insulation

33 Kitchen

- Removal of 25SF of wall - Possibility of Secondary walls.
- Removal of 1/2 ceiling
- Removal of Insulation
- Removal of vinyl floor

33 Hallway

- Removal of 25SF of wall
- Removal of 16SF of Ceiling
- Removal of Insulation