CITY OF PORTLAND, MAINE · RESURGAM
Reviewed for Code Compliance
Inspections Division
Approved with Conditions
Date: 01/20/15

57 Coyle Existing conditions photos

Side view

Carriage house and the oldest ash tree in Portland.

Reviewed for Code Compliance
Inspections Division
Approved with Conditions
Date: 01/20/15

Rear corner

Back of house. The rear yard is boxed in on all sides with garages set on the property line.

Reviewed for Code Compliance
Inspections Division
Approved with Conditions
Date: 01/20/15

Interior photos

Front foyer

Living room looking into the dining room that will become the kitchen