Reviewed for Code Compliance
Inspections Division
Approved with Conditions
Date: 04/13/17

Legalization Inspection Form

Date: 3/28/17

Address: 15 Longfellow Street

Legal Use: Two unit

Proposed Use: Three unit - 3rd floor

Basement

- Fire Door: Yes, in place
- Detection: yes, in place
- Sprinkler Head: yes, in place

Notes: Electrical box needs to be secured
Penetrations need to be sealed - above door on stairs
Stairs (lower) that are no longer in use should be removed or blocked

Unit 1

- Fire Door: yes, in place
- Detection: yes, in place

Notes: a 1 hr. rated fire door will need to be installed at the rear entry
* All units and doors should be labeled or numbered

Unit 2

- Fire Door: yes, in place
- Detection: yes, in place

Notes: Remove battery detector in the office

Reviewed for Code Compliance
Inspections Division
Approved with Conditions
Date: 04/13/17

Unit 3

- Fire Door: yes, in place
- Detection: yes, in place

Notes: Stairwell will need fall protection
Cover plate for outlet behind heater
Remove battery detector on Stairs

Unit ___

- Fire Door: _____
- Detection: _____

Notes: _____

Unit ___

- Fire Door: _____
- Detection: _____

Notes: _____

Unit ___

- Fire Door: _____
- Detection: _____

Notes: _____

Overall Pass_____ Fail_____ Follow up Required ✓